

AND PLAN OF CORRECTION

PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

535029

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - MAIN BUILDING 01

B. WING

(X3) DATE SURVEY
COMPLETED

06/29/2007

NAME OF PROVIDER OR SUPPLIER

CROOK COUNTY MEDICAL SERVICES

STREET ADDRESS, CITY, STATE, ZIP CODE

BOX 517

SUNDANCE, WY 82729

(X4) ID
PREFIX
TAGSUMMARY STATEMENT OF DEFICIENCIES
(EACH DEFICIENCY MUST BE PRECEDED BY FULL
REGULATORY OR LSC IDENTIFYING INFORMATION)ID
PREFIX
TAGPROVIDER'S PLAN OF CORRECTION
(EACH CORRECTIVE ACTION SHOULD BE
CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY)(X5)
COMPLETION
DATE

K 000 INITIAL COMMENTS

K 000

Requirements for Long Term Care Facilities
Section 42 CFR 483.70 (a) except as otherwise
provided in the section, the facility must meet the
applicable provisions of the 2000 edition of the
Life Safety Code, Existing Health Care, of the
National Fire Protection Association.

The facility was a fully sprinklered single story
building of Type II (111) construction built in
1985.

K 011 NFPA 101 LIFE SAFETY CODE STANDARD

K 011

K011
The facility will maintain NFPA 101
Section 8.2.3.2.3.1 standard for 2 hour
fire barrier. The unsealed cable
penetration will be sealed.
Maintenance will monitor this
standard monthly by inspections.

If the building has a common wall with a
nonconforming building, the common wall is a fire
barrier having at least a two-hour fire resistance
rating constructed of materials as required for the
addition. Communicating openings occur only in
corridors and are protected by approved
self-closing fire doors. 19.1.1.4.1, 19.1.1.4.2

This STANDARD is not met as evidenced by:
Based on observations the facility failed to seal
penetrations in 1 of 1 fire rated assembly. The
finding was:

Observation on 5/30/07 at 10:15 AM revealed the
hospital 2-hour fire barrier had one unsealed
cable penetration in the ceiling cavity above the
double doors.

NFPA 101 Section 8.2.3.2.3.1 states "Every
opening in a fire barrier shall be protected to limit
the spread of fire and restrict the movement of
smoke from one side of the fire barrier to the
other. The fire protection rating for opening
protectives shall be as follows:

ALL CITED DEFICIENCIES WILL
BE REPORTED TO NEXT QA &
QUALITY TRUST AFTER THE
NEXT YEAR.
APPROVED W/ LARRY POTTER.

07/13/07
4/30/07

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

JUN 22 2007

AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

535029

(X2) MULTIPLE CONSTRUCTION

A. BUILDING 01 - MAIN BUILDING 01

B. WING

(X3) DATE SURVEY
COMPLETED

05/29/2007

NAME OF PROVIDER OR SUPPLIER

CROOK COUNTY MEDICAL SERVICES

STREET ADDRESS, CITY, STATE, ZIP CODE

BOX 517

SUNDANCE, WY 82729

6/20/07

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 011	Continued From page 1	K 011		
K 018 SS=D	(1) 2-hour fire barrier - 1 1/2-hour fire protection rating..." NFPA 101 LIFE SAFETY CODE STANDARD Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 1 3/4 inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. 19.3.6.3 Roller latches are prohibited by CMS regulations in all health care facilities.	K 018	K018 The facility will meet this NFPA 101 standard. The latch bolt and assembly will be replaced. Weekly inspections will be done by maintenance staff.	06/30/07
K 047 SS=F	This STANDARD is not met as evidenced by: Based on observations the facility failed to maintain 1 of 36 corridor doors. The finding was: Observation 05/30/07 at 9:12 AM revealed the corridor door to resident room #213 was equipped with a latch bolt which would not insert into the strike plate of the door frame. NFPA 101 LIFE SAFETY CODE STANDARD Exit and directional signs are displayed in accordance with section 7.10 with continuous	K 047	K047 The facility will meet NFPA 101 section 7.10, 19.2, 10.1 standard with daily inspections done by maintenance and housekeeping staff. Any lights not working will be replaced when inspected.	06/27/07

JUN-22-2007 12:01 PM CCMSD		3072832255		P. 04
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535029		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____
				(X3) DATE SURVEY COMPLETED 05/29/2007

NAME OF PROVIDER OR SUPPLIER CROOK COUNTY MEDICAL SERVICES	STREET ADDRESS, CITY, STATE, ZIP CODE BOX 517 SUNDANCE, WY 82729
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 047	Continued From page 2 illumination also served by the emergency lighting system. 19.2.10.1 This STANDARD is not met as evidenced by: Based on observations the facility failed to maintain 4 of 10 exits signs. The findings were: Observation on 5/30/07 between 9:30 AM and 10 AM revealed the following exit signs were not maintained with both light bulbs continuously illuminated; a. The sign near the kitchen's rear exit. b. The sign in the kitchen near the dining room. c. The sign near the smoke barrier. d. The sign near the nurses station, NFPA 101 LIFE SAFETY CODE STANDARD Required automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested periodically. 19.7.6, 4.6.12, NFPA 13, NFPA 25, 9.7.5 This STANDARD is not met as evidenced by: Based on observations the facility failed to maintain an continuous ceiling membrane in 1 of 46 rooms. The finding was: Observation on 5/30/07 at 9:42 AM revealed the tub room's ceiling was not a continuous membrane due to a hole out into the ceiling for repairs of a heater. NFPA 13 Section 1-4.6 states "...other members do not impede heat flow or water distribution in a	K 047		
K 062 SS=D		K 062	K062 The facility will maintain NFPA 13 section 1-4.6 standard with weekly inspections by maintenance staff. A new heater was installed on 5/30/07, giving a continuous ceiling membrane.	05/30/07

CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535029	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/29/2007
NAME OF PROVIDER OR SUPPLIER CROOK COUNTY MEDICAL SERVICES			STREET ADDRESS, CITY, STATE, ZIP CODE BOX 517 SUNDANCE, WY 82729		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 062	Continued From page 3 manner that materially affects the ability of sprinklers to control or suppress a fire..."	K 062			
K 064 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Portable fire extinguishers are provided in all health care occupancies in accordance with 9.7.4.1, 19.3.5.6, NFPA 10 This STANDARD is not met as evidenced by: Based on observations and staff interview the facility failed to test 10 of 10 portable fire extinguisher. The findings were: 1. Observation on 5/30/07 between 8:30 AM and 10:30 AM revealed 10 of 10 portable fire extinguisher had not received an annual maintenance in the past year. The last maintenance was performed in April 2006. 2. Interview with the Maintenance Manager on 5/30/07 at 9:30 AM revealed the portable fire extinguishers were not scheduled for the annual maintenance. NFPA 10 Section 4-4.1 states "Frequency. Fire extinguishers shall be subjected to maintenances at intervals of not more than 1 year, and the time of hydrostatic test, or when specifically indicated by an inspection."	K 064	K064 The facility will meet NFPA 10 9.7.4.1, 19.3.5.6 standard by having portable fire extinguishers maintained yearly and monitoring to be done by maintenance staff monthly.	06/29/07	
K 147 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code. 9.1.2 This STANDARD is not met as evidenced by: Based on observations the facility failed to	K 147			

AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535029		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 05/29/2007	
NAME OF PROVIDER OR SUPPLIER CROOK COUNTY MEDICAL SERVICES				STREET ADDRESS, CITY, STATE, ZIP CODE BOX 517 SUNDANCE, WY 82720			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE			
K 147	Continued From page 4 prohibit flexible wiring replacing temporary fixed wiring in 2 of 46 rooms. The findings were: Observation on 5/30/07 between 8:30 AM and 9 AM revealed the following locations had temporary electrical wiring replacing permanent fixed wiring: a. Resident room #201 bed "A" had the radio plugged into an extension cord. b. Resident room #210 had a surge protector plugged into another surge protector. NFPA 70 Article 400-8 states " Uses not permitted. Unless specifically permitted in section 400-7, flexible cords and cables shall not be used for the following: (1) As a substitute for the fixed wiring of a structure."	K 147	K147 The facility will meet NFPA 70, National Electric Code 9.1.2 standard by weekly inspections by housekeeping and maintenance staff. Extension cords will be removed. Surge protectors plugged into one another will be unplugged and rearranged to meet this standard.	06/27/07			

CENTERS FOR MEDICARE & MEDICAID SERVICES

AH

"A" FORM

STATEMENT OF ISOLATED DEFICIENCIES WHICH CAUSE NO HARM WITH ONLY A POTENTIAL FOR MINIMAL HARM FOR SNF; AND NF;		PROVIDER # 535029	MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____	DATE SURVEY COMPLETE: 5/29/2007
NAME OF PROVIDER OR SUPPLIER CROOK COUNTY MEDICAL SERVICES		STREET ADDRESS, CITY, STATE, ZIP CODE BOX 517 SUNDANCE, WY		
ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES			
K 050	NFPA 101 LIFE SAFETY CODE STANDARD Fire drills are held at unexpected times under varying conditions at least quarterly on each shift. The staff is familiar with procedures and is aware that drills are part of established routine. Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are conducted between 9 PM and 6 AM a coded announcement may be used instead of audible alarms 19.7.1.2 This STANDARD is not met as evidenced by: Based on record review and staff interview, the facility failed to conduct a fire drill on 1 of 8 quarterly shifts in the past year. The findings were: 1. Review of the fire drill records revealed the second shift had not conducted a fire drill during the second quarter of 2006. 2. Interview with the Maintenance Manager on 5/29/07 at 4 PM revealed there were no other records to review.			

Any deficiency statement ending with an asterisk(*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of

The above isolated deficiencies pose no actual harm to the residents