

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICESPRINTED: 07/21/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535040	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED C 07/19/2010
NAME OF PROVIDER OR SUPPLIER DOUGLAS CARE CENTER LLC			STREET ADDRESS, CITY, STATE, ZIP CODE 1109 BIRCH STREET DOUGLAS, WY 82633		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS Requirements for Long Term Care Facilities Section 42 CFR 483.70 (a) except as otherwise provided in this section, the facility must meet the applicable provisions of the 2000 edition of the Life Safety Code, Existing Health Care, of the National Fire Protection Association (NFPA). The facility was a fully sprinkled single story building with a basement of Type V (111) construction built in 1967. The building was equipped with a supervised automatic wet sprinkler system with a zoned fire alarm system. The facility had a capacity of 60 certified Medicare and Medicaid beds.	K 000			
K 038 SS=F	NFPA 101 LIFE SAFETY CODE STANDARD Exit access is arranged so that exits are readily accessible at all times in accordance with section 7.1. 19.2.1 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure 3 of 6 exit discharge pathways were accessible. The findings were: Observation on 7/19/10 at 4:45 PM showed the exit discharge pathway for the northeast, northwest and north Central exits were obstructed. The north sidewalk system terminated at a gravel-based parking lot, which was not compacted or traversable by residents with impaired mobility. The parking lot, which was part of the discharge path, was obstructed by three contractor work trailers. The northwest sidewalk	K 038	Fisher Construction, contractor is responsible for correcting an exit leading to a public way. There will be a parking lot will be paved. The parking lot should be paved by the end of September. Until then there is sidewalk along the backside of the building leading to the alley way. The area will be free and clear of trailers and such to keep a clear path. This will be monitored by Kelli Rogge, NHA of DCC to ensure that the situation does not develop again. Fisher Construction, connector is responsible		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE:

(X6) DATE


Lori Liebert (for Kelli Rogge NHA)

KN CON

7-28-10

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 60 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

POC ACCEPTED WITH LORI LIEBERT, DON. ON 8/6/10.


RECEIVED
Wyoming Dept of Health

JUL 28 2010

Office of Healthcare
Licensing and Surveys

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICESPRINTED: 07/21/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535040	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED C 07/19/2010
NAME OF PROVIDER OR SUPPLIER DOUGLAS CARE CENTER LLC			STREET ADDRESS, CITY, STATE, ZIP CODE 1108 BIRCH STREET DOUGLAS, WY 82633		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS Requirements for Long Term Care Facilities Section 42 CFR 483.70 (a) except as otherwise provided in this section, the facility must meet the applicable provisions of the 2000 edition of the Life Safety Code, Existing Health Care, of the National Fire Protection Association (NFPA). The facility was a fully sprinkled single story building with a basement of Type V (111) construction built in 1967. The building was equipped with a supervised automatic wet sprinkler system with a zoned fire alarm system. The facility had a capacity of 80 certified Medicare and Medicaid beds. NFPA 101 LIFE SAFETY CODE STANDARD Exit access is arranged so that exits are readily accessible at all times in accordance with section 7.1. 19.2.1 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure 3 of 6 exit discharge pathways were accessible. The findings were: Observation on 7/19/10 at 4:45 PM showed the exit discharge pathway for the northeast, northwest and north Central exits were obstructed. The north sidewalk system terminated at a gravel-based parking lot, which was not compacted or traversable by residents with impaired mobility. The parking lot, which was part of the discharge path, was obstructed by three contractor work trailers. The northwest sidewalk	K 000	<i>φ SIGNATURE</i>  B/DL/D		
K 038 SS=F		K 038	Fisher Construction, contractor is responsible for correcting an exit leading to a public way. There will be a parking lot will be paved. The parking lot should be paved by the end of September. Until then there is sidewalk along the backside of the building leading to the alley way. The area will be free and clear of trailers and such to keep a clear path. This will be monitored by Kelli Rogge, NHA of DCC to ensure that the situation does not develop again. Fisher Construction, contractor is responsible		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

RECEIVED
Wyoming Dept of Health

JUL 28 2010

Office of Healthcare
Licensing and Surveys

PRINTED: 07/21/2010
FORM APPROVED
OMB NO. 0938-0391

If continuation sheet Page 2 of 3

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICESPRINTED: 07/21/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: S35040	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED C 07/19/2010
NAME OF PROVIDER OR SUPPLIER DOUGLAS CARE CENTER LLC			STREET ADDRESS, CITY, STATE, ZIP CODE 1108 BIRCH STREET DOUGLAS, WY 82633	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 052	Continued From page 2 detector in the central smoke compartment showed none of the power indicator lights were illuminated. Observation of the west smoke compartment showed none of these smoke detector were supplied with power either. Review of the fire alarm system testing records showed an annual inspection was conducted on 6/18/10 by an outside contractor. Further review showed a new fire alarm system was installed as part of the facility wide renovation on 7/08/10. The "Fire Alarm System Record of Completion" shows the system was installed in accordance with NFPA 70, national Electrical Code, NFPA 72, National Fire Alarm Code and the manufacturer's published instructions. The record was signed by the installing electrical contractor and installing fire alarm system contractor. At the time of observation the installing electrical contractor was not able to determine why the system was not operational.	K 052		