

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

JUL 30 2009

PRINTED: 07/29/2009
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 53503	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		Office of Healthcare Licensing and Surveys (X3) DATE SURVEY COMPLETED 07/07/2009
NAME OF PROVIDER OR SUPPLIER ROCKY MOUNTAIN CARE EVANSTON			STREET ADDRESS, CITY, STATE, ZIP CODE 475 YELLOW CREEK ROAD EVANSTON, WY 82930		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS Requirements for Long Term Care Facilities Section 42 CFR 483.70 (a) except as otherwise provided in the section, the facility must meet the applicable provisions of the 2000 edition of the Life Safety Code, Existing Health Care of the National Fire Protection Association (NFPA). The facility was a fully sprinkled single story building of Type V (111) construction built in 1985. The building was equipped with supervised automatic dry sprinkler system with an addressable fire alarm system.	K 000	DOC ACCEPTED W/ CHANGES W/ NANCY BOWEN, NHA, RN 7/30/09. 		
K 012 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Building construction type and height meets one of the following. 19.1.6.2, 19.1.6.3, 19.1.6.4, 19.3.5.1 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure non-conforming buildings were separated by a 2-hour fire rated barrier in 1 of 5 smoke compartments. The findings were: Observation on 7/07/09 at 10:56 AM allowed the facility had converted an existing cinder block barrier wall into a wood frame storage shed. The roof and exterior walls were constructed of 2-inch by 4-inch pine studs and sheathed with 5/8-inch plywood. The shed was located 6 feet from the southeast exterior wall of the facility. The shed housed the facility's utility tractor along with various yard equipment. The maintenance director reported at the time of observation that he was not aware of a 2-hour separation	K 012	K 012 The storage shed will be moved to a location on the facility property with at least 20 feet of separation from the facility. A plan approval request will be submitted to the WY Dept. of Health (no later than 8/17/09) prior to construction of the new shed. The facility will seek prior approval before conducting any construction projects in the future.	08/17/09	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes that the facility is in the process of correcting the deficiency. Other safeguards provide sufficient protection to the patient, following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the program participation.

deficiency which the institution may be excused from correcting providing it is determined that the instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date these documents are made available to the facility. If deficiencies are altered, an approved plan of correction is requisite to continued

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/29/2009
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 835031		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/07/2009	
NAME OF PROVIDER OR SUPPLIER ROCKY MOUNTAIN CARE EVANSTON				STREET ADDRESS, CITY, STATE, ZIP CODE 475 YELLOW CREEK ROAD EVANSTON, WY 82930			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 012	Continued From page 1 required. He further reported that he was not aware a 15 foot separation was equivalent to a 2-hour separation. The administrator reported that the newly converted shed did not have plan approval from the Wyoming Department of Health prior to construction.			K 012			
K 029 SS=E	NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with 1/2 hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure hazardous areas were separated from use areas in 2 of 5 smoke compartments. The findings were: 1. Observation on 7/07/09 at 9:22 AM showed the central electrical room had two unsealed cable penetrations. The largest penetration was 1-inch in diameter with two thin cables running through it. At the time of observation the maintenance director reported hazardous areas were inspected quarterly. He also reported the last inspection had occurred during the first week of April 2009. 2. Observation on 7/07/09 at 10:45 AM showed			K 029	K029 1. The unsealed cable penetrations in the central electrical room were filled with fire rated caulk on 7/20/2009. The maintenance director will ensure inspection is taking place quarterly and any issues are addressed immediately. He will report any concerns to the Quality Assurance (QA) Committee at least quarterly. 2. The unsealed conduit penetrations in the main electrical room were filled with fire rated caulk on 7/20/2009. The maintenance director will ensure inspection is taking place quarterly. Any issues found will be addressed immediately. Any concerns will be reported to the QA committee at least quarterly.		7/20/09

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/29/2009
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535031	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/07/2009
NAME OF PROVIDER OR SUPPLIER ROCKY MOUNTAIN CARE EVANSTON			STREET ADDRESS, CITY, STATE, ZIP CODE 475 YELLOW CREEK ROAD EVANSTON, WY 82230		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 029	Continued From page 2 the main electrical room had three unsealed conduit penetrations above the main electrical disconnect switch gear. The largest penetration was 2.5 inches in diameter, with a conduit running through it.	K 029			
K 062 SS=F	NFPA 101 LIFE SAFETY CODE STANDARD Required automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested periodically. 19.7.6, 4.6.12, NFPA 13 NFPA 26, 9.7.5 This STANDARD is not met as evidenced by: Based on record review and staff interview the facility failed to ensure 1 of 3 sprinkler system components was tested annually. The findings were: Review of the sprinkler system testing records documented the back flow preventer had not been tested in the past year. The maintenance director reported that he was not aware that the backflow preventer required testing. He further reported that he did not have records to show the backflow preventer had ever been tested.	K 062	K062 The backflow preventers will be tested by an independent contractor on or before 8/7/2009. They will be put on a schedule to be tested annually.	8/07/09	
K 069 SS=E	NFPA 101 LIFE SAFETY CODE STANDARD Cooking facilities are protected in accordance with 9.2.3, 19.3.2.6, NFPA 96 This STANDARD is not met as evidenced by: Based on record review and staff interview the facility failed to ensure 2 of 5 electrical receptacles under the kitchen hood were connected to the disconnect switch. The findings	K 069	K069 The electrical receptacles under the kitchen hood were inactivated prior to the end of the survey. The receptacles remained off until an electrician could be found to connect the receptacles to the disconnect switch. An electrician connected the receptacles to the disconnect switch on 7/20/2009 and a letter of completion was received from the electrician.	7/20/09	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICESPRINTED: 07/29/2009
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535034	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/07/2009
NAME OF PROVIDER OR SUPPLIER ROCKY MOUNTAIN CARE EVANSTON			STREET ADDRESS, CITY, STATE, ZIP CODE 475 YELLOW CREEK ROAD EVANSTON, WY 82930		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY REGULATORY OR LSC IDENTIFYING INFORMATION)	S FULL (ATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 089	Continued From page 3 were: Review of the fire suppression system records documented that two 110 volt electrical receptacles under the hood in the kitchen were not wired to the power disconnect micro switch. Further review showed that this issue was cited by the testing contractor on the last two semi-annual inspections. The maintenance director reported that he was aware of the problem. He further reported that the facility had contacted an electrician in February 2009, shortly after the last inspection. He confirmed that no further attempts to contact the electrician or any other electrician had been made since February.		K 089		
K 130 SS=F	NFPA 101 MISCELLANEOUS OTHER LSC DEFICIENCY NOT ON 2 '86 This STANDARD is not met as evidenced by: Based on observation and staff interviews the facility failed to ensure 2 of 2 conversion projects had plan approval from the Wyoming Department of Health. The findings were: 1. Observation on 7/07/09 at 10:58 AM showed a wood framed roof and wall had been added to an existing cinder block wall to form a shed to house a tractor. The administrator confirmed the newly converted shed did not have plan approval from the Wyoming Department of Health prior to construction. 2. Observation on 7/07/09 at 1:40 PM showed the original, zoned, fire alarm panel had been replaced with an addressable fire alarm panel in		K 130	K130 1. THE ROOF & OUTSIDE WALL OF THE SHED WILL BE REMOVED, LEAVING THE CINDER BLOCK WALL ASY 8/19/09. 2. The shed will be moved to a different location on the facility property. The facility will secure plan approval prior to moving the shed to the new location. The facility will seek plan approval from the WY Department of Health before conducting any construction projects in the future. 3. The facility will submit an extension request to complete this project to the WY Dept. of Health, Office of Health Care Licensing and Surveys by 8/7/09 a waiver for additional time to complete the plan approval process for the fire panel. A letter requesting plan approval will be sent to the WY Dept. of Health by 8/17/09. The facility estimates to have the project completed, along with appropriate approvals no later than 2/28/2010.	8/19/09

EWS PRESENTS
WILL BE SUBMITTED
FOR

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/28/2009
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535038	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/07/2009
NAME OF PROVIDER OR SUPPLIER ROCKY MOUNTAIN CARE EVANSTON			STREET ADDRESS, CITY, STATE, ZIP CODE 475 YELLOW CREEK ROAD EVANSTON, WY 82930		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 130	Continued From page 4 October 2008. At the time of observation the maintenance director reported that the system was replaced without plan approval from the Wyoming Department of Health. During the exit conference the administrator reported that the system was replaced without plan approval because the last inspection of August 5, 2008 showed ten smoke detectors did not pass the sensitivity test and the facility did not feel they could wait 4-6 months for plan approval. When the administrator was asked why plans were not submitted after the project was completed to ensure that all standards and requirements were met she stated that the replacement was maintenance of the system and did not need plan approval. When asked, the maintenance director reported the original system was a zoned level 2 system and was replaced with an addressable level 1 system. He further reported that all smoke detectors were replaced along with on added and new wiring was required so the system would be able to self-monitor and function properly.		K 130		
K 147 SS-E	NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code, 9.1.2 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure the electrical system was properly maintained in 2 of 5 smoke compartments. The findings were: 1. Observation on 7/07/09 at 8:49 AM showed the face of an electrical receptacles in the staff lounge was charred in between the power blade		K 147	K147 1. The electrical receptacle in the staff lounge that was found to be charred was replaced on 7/7/09. The electrical system will be inspected quarterly and problems will be remedied immediately. The maintenance director will report any concerns to the QA committee at least quarterly. 2. The extension cord was removed from the portable microphone/speaker system. The maintenance director will conduct checks on a monthly basis to inspect the facility for any extension cords or other problems with electrical wiring. He will report any concerns to the QA committee at least quarterly. 3. The electrical receptacle near the residential washer in the laundry and the receptacle near the sink in the 200-hall clean linen room were changed to GFCI receptacles on 7/28/09. The maintenance director will check all other locations and make certain that we have GFCI receptacles in locations that are near water. He will report any concerns to the QA committee at least quarterly.	7/28/09

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 07/29/2009
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 53503	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 07/07/2009
NAME OF PROVIDER OR SUPPLIER ROCKY MOUNTAIN CARE EVANSTON			STREET ADDRESS, CITY, STATE, ZIP CODE 475 YELLOW CREEK ROAD EVANSTON, WY 82930		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 147	Continued From page 5 ports. At the time of observation the maintenance director reported the electrical system was inspected quarterly and that the last inspection occurred during the last week of April 009. 2. Observation on 7/07/09 at 9:12 AM showed the portable microphone/speaker in the dining room was plugged into a surge protector which was, itself, plugged into an extension cord. 3. Observation on 7/07/09 between 9:00 AM and 10:30 AM showed the electrical receptacle near the residential washer in the laundry and the receptacle near the sink in the 200 clean linen room were not protected with grounded fault circuit interrupter (GFCI) receptacles. At 9:41 AM the maintenance director reported that he was aware that GFCI receptacles were required in wet location in new construction, but he was not aware that they were required in existing locations.	K 147			