

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535022		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/27/2009	
NAME OF PROVIDER OR SUPPLIER PIONEER MANOR NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 900 W 8TH ST GILLETTE, WY 82716			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	INITIAL COMMENTS			K 000			
	Requirements for Long Term Care Facilities Section 42 CFR 483.70 (a) except as otherwise provided in the section, the facility must meet the applicable provisions of the 2000 edition of the Life Safety Code, Existing Health Care, of the National Fire Protection Association.						
K 012 SS=D	The facility was a fully sprinklered three story building of Type V (111) construction built in 1965 and 1987. The building was equipped with a supervised automatic wet sprinkler system with an anti-freeze branch and fire alarm system NFFA 101 LIFE SAFETY CODE STANDARD			K 012	K 012		2/27/09
	Building construction type and height meets one of the following. 19.1.6.2, 19.1.6.3, 19.1.6.4, 19.3.5.1				The ceiling tile in the bathroom in room 507 was put back in place by Pioneer Manor Staff on February 27, 2009.		
	This STANDARD is not met as evidenced by: Based on observation and staff interview, the facility failed to ensure the facility smoke partition was maintained as a continuous membrane in 2 of 11 smoke compartments. The findings were:				The 2x4 inch hole in the old pharmacy room ceiling in the basement was filled and painted by Plant Operations painter on February 27, 2009.		2/27/09
	Observation on 2/26/09 between 11:30 AM and 3 PM revealed two ceiling tiles in the bathroom of resident room #507 on the main floor were displaced, a hole about 2 sq. ft. in diameter. In addition, a 2 x 4 in. hole was noted in the old pharmacy room ceiling in the basement. Interview with the facility's maintenance manager at the time of the observation confirmed the ceiling tile was displaced and the presence of the hole in the ceiling in the basement room.				Pioneer Manor Plant Operation staff will periodically inspect resident rooms and the entire facility to ensure ceiling tiles are properly in place and penetrations are filled.		
K 017	NFFA 101 LIFE SAFETY CODE STANDARD			K 017			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See Instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

MAR 20 2009

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535022	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/27/2009
NAME OF PROVIDER OR SUPPLIER PIONEER MANOR NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 900 W 8TH ST GILLETTE, WY 82716		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 017 SS=D	Continued From page 1 Corridors are separated from use areas by walls constructed with at least 1/2 hour fire resistance rating. In sprinklered buildings, partitions are only required to resist the passage of smoke. In non-sprinklered buildings, walls properly extend above the ceiling. (Corridor walls may terminate at the underside of ceilings where specifically permitted by Code. Charting and clerical stations, waiting areas, dining rooms, and activity spaces may be open to the corridor under certain conditions specified in the Code. Gift shops may be separated from corridors by non-fire rated walls if the gift shop is fully sprinklered.) 19.3.6.1, 19.3.6.2.1, 19.3.6.5 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure corridor walls were smoke resistant in 1 of 11 smoke compartments. The findings were: Observation on 2/26/09 between 11:30 AM and 3 PM revealed the corridor wall near resident room #209 had two unsealed wall penetrations. Each was 1/2 in. in diameter. Maintenance staff reported the egress doors to the secure unit had been moved 15 ft. down the hall a year ago, and the holes were a result of removing the doors. NFFA 101 LIFE SAFETY CODE STANDARD	K 017	K 017 The two unsealed wall penetrations noted near resident room 209 were filled and painted by Plant Operations staff on February 27, 2009. Pioneer Manor Plant Operations will inspect the facility periodically for penetrations and repair any penetrations as needed.	2/27/09	
K 018 SS=D	Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or	K 018	K 018 The gaps noted in resident rooms 302 and 411 as well as the tub room on wing one that exceed 1/8 inch have been eliminated.	3/7/09	

If continuation sheet Page 3 of 10

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535022	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/27/2009
NAME OF PROVIDER OR SUPPLIER PIONEER MANOR NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 900 W 8TH ST GILLETTE, WY 82716		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 018	Continued From page 3	K 018			
K 027	NFPA 101 LIFE SAFETY CODE STANDARD	K 027			
SS=E	Door openings in smoke barriers have at least a 20-minute fire protection rating or are at least 1 1/4-inch thick solid bonded wood core. Non-rated protective plates that do not exceed 48 inches from the bottom of the door are permitted. Horizontal sliding doors comply with 7.2.1.14. Doors are self-closing or automatic closing in accordance with 19.2.2.2.6. Swinging doors are not required to swing with egress and positive latching is not required. 19.3.7.5, 19.3.7.6, 19.3.7.7 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure 3 of 16 smoke barrier doors were able to resist the passage of smoke. The findings were: • Observation on 2/26/09 between 11:30 AM and 3 PM revealed the following concerns: a. The cross corridor doors at the entrance to wing #2, when closed, had a vertical gap greater than 1/8 inch. b. The cross corridor doors at the entrance to wing #3 from the dining room, when closed, had a vertical gap greater than 1/8 inch. In addition, one of the doors didn't completely latch into the door frame with three separate attempts. c. The cross corridor doors at the entrance to wing #3 at the chapel, when closed, did not completely latch into the door frame with three separate attempts. Interview with the maintenance manager at the	A) The cross corridor door at the entrance to Wing #2 that had a vertical gap greater than 1/8 inch no longer have the 1/8 inch gap. The gap was sealed using astragal on March 7, 2009 B) The cross corridor door at the entrance to Wing #3 that had a vertical gap greater than 1/8 inch no longer has the 1/8 inch gap. The gap was sealed using astragal on March 7, 2009. C) The cross corridor doors at the entrance on Wing #3 did not completely latch. Plant Operations repaired the latch the same day as the survey and now the latch functions properly. Plant Operations will periodically monitor gaps and latches to ensure compliance with applicable codes and regulations.	3/7/09 3/7/09 3/7/09		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 636022	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/27/2009
NAME OF PROVIDER OR SUPPLIER PIONEER MANOR NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 900 W 8TH ST GILLETTE, WY 82716		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 027	Continued From page 4 time of the observations confirmed the gaps and latching problems of the aforementioned doors.	K 027			
K 045 66=E	NFPA 101 LIFE SAFETY CODE STANDARD Illumination of means of egress, including exit discharge, is arranged so that failure of any single lighting fixture (bulb) will not leave the area in darkness. (This does not refer to emergency lighting in accordance with section 7.8.) 19.2.8 This STANDARD is not met as evidenced by: Based on observation and staff interview, the facility failed to ensure two corridor exit signs were fully lit in 1 of 11 smoke compartments. The findings were: Observation on 2/26/09 between 11:30 AM and 3 PM revealed one of two light bulbs was burned out in two exit signs in the special care unit above the exit door and in the hall corridor. Interview with the facility's maintenance manager at the time of the observations confirmed the bulbs were burned out.	K 045	During the inspection, two light bulbs were burnt out in two exit signs in the special care unit. Plant Operations installed new light bulbs and now the two exit signs are fully illuminated. Plant Operations will continually check exit signs to ensure that they are fully illuminated.	3/3/09	
K 047 66=E	NFPA 101 LIFE SAFETY CODE STANDARD Exit and directional signs are displayed in accordance with section 7.10 with continuous illumination also served by the emergency lighting system. 19.2.10.1 This STANDARD is not met as evidenced by: Based on observation and staff interview, the facility failed to ensure one directional corridor	K 047	The hallway corridor emergency exit sign attached to the ceiling at a "T" juncture in the hallway in the special care unit did not have the "right" directional arrow punched out directing traffic to the right and to the facilities emergency exit has been remedied. The arrow was positioned correctly on March 3, 2009 by Plant Operations staff. Plant Operations will periodically check directional signage to ensure it is correct.	3/3/09	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535022	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/27/2009
NAME OF PROVIDER OR SUPPLIER PIONEER MANOR NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 900 W 8TH ST GILLETTE, WY 82716		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 047	Continued From page 5 exit sign was properly configured in 1 of 11 smoke compartments. The findings were: Observation on 2/26/09 between 11:30 AM and 3 PM revealed a hallway corridor emergency exit sign attached to the ceiling at a "T" juncture in the hallway in the special care unit (SCU). The sign did not have the "right" direction arrow punched out directing traffic to the right and to the facility's emergency exit.	K 047			
K 050 SS=E	NFPA 101 LIFE SAFETY CODE STANDARD Fire drills are held at unexpected times under varying conditions, at least quarterly on each shift. The staff is familiar with procedures and is aware that drills are part of established routine. Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are conducted between 9 PM and 6 AM a coded announcement may be used instead of audible alarms. 19.7.1.2 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility staff was not familiar with emergency procedures under varying conditions. The findings were: 1. Observation of the wing #5 fire drill on 2/27/09 at 2:57 PM revealed two certified nursing assistants entered the "fire" room, turned off the nurse call light and did not announce the presence of a "fire." Maintenance staff had to inform them the flashing fire/light represented a mock fire drill. He also had to tell them to activate the fire alarm system. In addition, during the drill,	K 050	K 050 Pioneer Manor takes this deficiency seriously and took immediate actions to ensure fire drills are performed appropriately. A) The Fire Drill policy was reviewed and rewritten with specific duties and responsibilities for various departments. B) This policy was reviewed with staff at various meetings on March 12, 2008. C) Pioneer Manor leadership met with Dave King from the Campbell County Fire Department on March 10, 2009 and he agreed to observe fire drills and critique these drills. D) The staff that was involved in the fire drill during the inspection has been provided coaching and counseling regarding their role in a fire drill. E) A plan was developed to have "confidence" fire drills whereby a fire drill occurs and the staff slowly conducts the drill with coaching and supervision from appropriate staff to ensure staff is		4/30/09

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535022	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/27/2009
NAME OF PROVIDER OR SUPPLIER PIONEER MANOR NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 900 W 8TH ST GILLETTE, WY 82716		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 050	Continued From page 6 no staff transported a fire extinguisher to the "fire." 2. Observation of the wing #4 fire drill on 2/27/09 at 3:18 PM revealed after staff entered the "fire" room, two minutes elapsed before staff pulled the fire alarm. In addition, a second public announcement of the fire was required before staff responded to the drill and during the drill, four resident doors were not closed and no notice (facility uses rubber bands) was attached to the cleared resident rooms. 3. Interview with the facility's maintenance manager and staff education officer on 2/27/09 at 3:48 PM confirmed the above observations and both stated staff needed more education related to fire drills.	K 050	K 050 Continued from page 6 educated as to their duties and responsibilities. F) Pioneer Manor leadership will monitor drills and emphasize the importance of conducting fire drills appropriately. G) Staff that fail to respond to proper fire drill procedures will be disciplined. Pioneer Manor Administration and Plant Operations will conduct drills and observe staff for compliance with policy and procedures.		
K 062 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Required automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested periodically. 19.7.6, 4.6.12, NFPA 13, NFPA 25, 9.7.5 This STANDARD is not met as evidenced by: Based on observation and staff interview the facility failed to ensure sprinkler heads were properly maintained in 3 of 11 smoke compartments. The findings were: Observation on 2/26/09 between 11:30 AM and 3 PM revealed gaps greater than 1 inch between the sprinkler head escutcheons and the ceiling in the following locations: a. Resident rooms #108, #114 and the bathroom near the nurses station on wing #1. b. The pantry (mini kitchen) by the dining	K 062	K 062 The gaps greater than 1 inch between the sprinkler head escutcheons reported in resident rooms 108, 114, and the pantry by the dining room have been sealed. The two sprinkler heads in the main kitchen, in the kitchen's janitor's closet and one in the dry storage room also have been sealed. Plant Operations will periodically inspect sprinkler head escutcheons to ensure that a 1 inch gap does not exist and if it does they will seal them.	3/11/09	3/11/09

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535022	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/27/2009
NAME OF PROVIDER OR SUPPLIER PIONEER MANOR NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 900 W 8TH ST GILLETTE, WY 82716		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 082	Continued From page 7 room. c. Two sprinkler heads in the main kitchen hallway, one over the kitchen sink, one over the food preparation area, one in the kitchen janitors' closet, and one in the dry storage room. Observation on 2/26/09 between 11:30 AM and 3 PM revealed an artificial Christmas tree was stored two inches directly below a sprinkler head in the old pharmacy room in the basement. NFPA 101 LIFE SAFETY CODE STANDARD	K 082			
K 069 SS=D	Cooking facilities are protected in accordance with 9.2.3. 19.3.2.6, NFPA 96 This STANDARD is not met as evidenced by: Based on review of records and staff interviews the facility failed to ensure an annual inspection of the facility's cooking equipment. The findings were: Review of facility records on 02/27/09 at 8 AM revealed the kitchen cooking equipment was last inspected 02/21/08 by Armstrong Extinguishers Inc. Inspection report stated "recommend upgrade to UL300 per NFPA. Appliances do not have adequate surface protection." Records review also indicated the last test of the kitchen hood was conducted in 2003 indicating another test to be conducted in 2009 at which time regulations require equipment must be upgraded to meet UL 300 requirements. Maintenance manager and kitchen manager confirmed the findings.	K 069	This survey revealed that the kitchen cooking equipment was last inspected on 2/21/08 by Armstrong Extinguishers and they recommended upgrade to UL300 per NFPA. Pioneer Manor has contacted Armstrong Extinguishers to inspect and upgrade equipment to UL 300. Armstrong Extinguishers are scheduled to be on site on March 26 to inspect equipment and upgrade to UL 300. The survey cited the kitchen hood was last tested in 2003. Armstrong Extinguishers will test the kitchen hood on March 26 or 27, 2009 and put a tag or other documentation that test was conducted. Nutrition Manager and staff will periodically inspect cooking equipment and the kitchen hood and communicate any problems or concerns to Plant Operations. Plant Operation will notify the proper entities to remedy the situation.	3/25/09	
K 147 SS=E	NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code. 9.1.2	K 147	K 147 The surge protector that was plugged into the surge protector was unplugged. The	3/26/09	2/26/09

If continuation sheet Page 9 of 10

DEF MAR. 20, 2009- 3:15PM AND PIONEER WING ONE
CENTERS FOR MEDICARE & MEDICAID SERVICES

NO. 587 PRP. 36 03/12/2009
APPROVED
OMB NO. 0938-0381

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 635022	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 02/27/2009
NAME OF PROVIDER OR SUPPLIER PIONEER MANOR NURSING HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 900 W 8TH ST GILLETTE, WY 82716		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE