

Healthcare Licensing and Surveys


STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED 06/09/2016
NAME OF PROVIDER OR SUPPLIER PARK PLACE ASSISTED LIVING COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1930 EAST 12 STREET CASPER, WY 82601		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
S 000	General Comments A Life Safety Code survey was conducted at your facility on June 9, 2016 by Healthcare Licensing and Surveys. (HLS) The facility was a three story, fully sprinklered facility of TypeV (111) construction built in 1987. The building was equipped with a supervised automatic wet sprinkler system with an addressable fire alarm system. The facility had a capacity of 116 licensed beds with a census of 58 residents. Wyoming Department of Health, Rules and Regulations for Licensure of Assisted Living Facilities Chapter 4, Section 10 Life Safety and Electrical Safety. The requirements in Department of Health Chapter III, Construction Rules for Health Facilities apply. (ii) Assisted Living Facilities operation prior to the effective date of these rules, shall meet the Life Safety Code of the National Fire Protection Association that was in effect at the time the facility was licensed as an Assisted Living Facility. All references are based on the requirements of the NFPA 101 Life Safety Code, New Board and Care, 1994 unless otherwise noted.	S 000			
S8003	NFPA Life Safety - Nfpa Means of Egress Components NFPA 101 Means of Egress Components This State Rule and Regulation is not met as evidenced by: Based on observation and staff interview, the facility failed to arrange exit access so that exits are readily accessible at all times. The findings	S8003			

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM



0609 BXJM11

If continuation sheet 1 of 7

Spoke with Robert Lempha on 8/1/2016 to let him know we have accepted his Plan of correction. Also talked to Robert accepting the Plan of correction with changes of completion date. 8/1/2016

PRINTED: 08/23/2016
FORM APPROVED

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED 06/09/2016
NAME OF PROVIDER OR SUPPLIER PARK PLACE ASSISTED LIVING COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1930 EAST 12 STREET CASPER, WY 82501		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
9 000	General Comments A Life Safety Code survey was conducted at your facility on June 9, 2016 by Healthcare Licensing and Surveys. (HLS) The facility was a three story, fully sprinklered facility of Type V (111) construction built in 1987. The building was equipped with a supervised automatic wet sprinkler system with an addressable fire alarm system. The facility had a capacity of 116 licensed beds with a census of 68 residents. Wyoming Department of Health, Rules and Regulations for Licensure of Assisted Living Facilities Chapter 4, Section 10 Life Safety and Electrical Safety. The requirements in Department of Health Chapter III, Construction Rules for Health Facilities apply. (ii) Assisted Living Facilities operation prior to the effective date of these rules, shall meet the Life Safety Code of the National Fire Protection Association that was in effect at the time the facility was licensed as an Assisted Living Facility. All references are based on the requirements of the NFPA 101 Life Safety Code, New Board and Care, 1994 unless otherwise noted.	9 000			
88003	NFPA Life Safety - Nfpa Means of Egress Components NFPA 101 Means of Egress Components This State Rule and Regulation is not met as evidenced by: Based on observation and staff interview, the facility failed to arrange exit access so that exits are readily accessible at all times. The findings	88003			

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

RECEIVED

WY Dept of Health

AUG 01 2016

Healthcare Licensing
and Surveys

Signature: *[Signature]* TITLE: Executive Director DATE: July 13, 2016

8X1111 If continuation sheet 1 of 7

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
STATE FORM

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
STATE FORM

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 06/09/2016
NAME OF PROVIDER OR SUPPLIER PARK PLACE ASSISTED LIVING COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 EAST 12 STREET CASPER, WY 82601		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S8018	Continued From page 3	S8018	S8018	
S8018	NFPA Life Safety - Nfpa Extinguishment Req NFPA 101 Extinguishment Requirements This State Rule and Regulation is not met as evidenced by: Based on observation and staff interview, the facility failed to ensure that automatic sprinkler systems are installed, and continuously maintained per the requirements of NFPA 13 and NFPA 25. The findings were: 1) Observation of the sprinkler system on 06/09/2016 at 8:47 AM revealed several sprinkler heads were obstructed by gypsum board in the boiler room. At the time of the observation interview with the Facility Maintenance Manager acknowledged the obstruction of the sprinkler head. Ref: 1994 NFPA 101, Sections 22-3.3.5.1 and 7-7 1994 NFPA 13, Section 4-4.1.3.1 2) Observation on 06/09/2016 at 9:28 AM located on the canopy outside the main entrance revealed an overhang over 4 feet of Type V construction. Interview with Facility Maintenance Manager at the time of observation confirmed the area was not provided with sprinklers. Ref: 1994 NFPA 101, Section 22-3.3.5.1 and 7-7.1.1 1994 NFPA 13, Section 4-5.7.2	S8018 S8018	1) A certified Fire Suppression company will be contacted and the Maintenance Director will oversee the sprinkler heads in the boiler room are put back onto compliance and are no longer obstructed by the gypsum board so that they have proper coverage in the boiler room. a) We will continue to monitor all fire suppression systems. We will continue to utilize Western Fire to inspect all of our fire suppression sprinkler heads so that they remain in compliance. 2) The Maintenance Director will contact a certified fire suppression company and they will install a system outside in the canopy for proper coverage of the canopy. Mountain West will be sending plans for a project number. a) We will continue to monitor all fire suppression systems. We will continue to utilize Western Fire to inspect all of our fire suppression sprinkler heads so that they remain in compliance	8/31/16 8/18/16 AL 8/31/16 8/18/16 AL

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 06/09/2016
NAME OF PROVIDER OR SUPPLIER PARK PLACE ASSISTED LIVING COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 EAST 12 STREET CASPER, WY 82601		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S8022	Continued From page 4	S8022	S8022	
S8022	NFPA Life Safety - Nfpa Electric NFPA 101 Electric This State Rule and Regulation is not met as evidenced by: Based on observation and staff interview, the facility failed to ensure that ground-fault circuit-interrupter protection was installed in accordance to NFPA 70. The findings were: 1) Observation on 06/09/2016 at 9:20 AM in the bathroom of the administration office revealed a receptacle without ground-fault circuit-interruption protection next to the sink. Interview with the Facility Maintenance Manager acknowledged the missing ground-fault circuit-interrupter. 2) Observation on 06/09/2016 from 10:00 AM to 10:35 AM revealed the majority of the second floor residents rooms in the kitchens where the receptacles were installed to serve the countertop surfaces were missing ground-fault circuit-interruption. Interview with the Facility Maintenance Manager acknowledged the missing ground-fault circuit-interrupters Ref: 1993 NFPA 70, Section 210.8 3) Observation on 06/09/2016 at 10:14 AM storage room adjacent to the elevator room on the 2nd floor revealed a circuit breaker had been removed from the panel board and not covered for protection. Interview with the Facility Maintenance Manager acknowledged the missing breaker. Ref:	S8022 S8022	1) A GFCI receptacles will be put into place in the bathroom of the administration office. 2) The Maintenance Director will audit all rooms on second floor and replace all receptacles that are not in accordance with NFAP regulations, with GFCI receptacles. 3) The Maintenance Director will place a blank circuit breaker in the storage room adjacent to the elevator room, where the circuit breaker has been removed.	8/31/16 08/08/16 AD 8/31/16 08/08/16 AD 6/30/16

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED 06/09/2016
NAME OF PROVIDER OR SUPPLIER PARK PLACE ASSISTED LIVING COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1930 EAST 12 STREET CASPER, WY 82601		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
S8022	Continued From page 5 1993 NFPA 70, Section 240.41	S8022			
S8030	NFPA Life Safety - Nfpa Miscellaneous NFPA 101 Miscellaneous This State Rule and Regulation is not met as evidenced by: Based on observation and staff interview, the facility failed to ensure that racks were provided to protect oxygen cylinders from accidental damage or dislocation in accordance with NFPA 99. The findings were: Observation on 06/09/2016 from 8:17 AM to 10:35 AM located throughout facility revealed unsecured oxygen tanks in the majority of the rooms. Interview with the Facility Maintenance Manager acknowledged the lack of unsecured tanks throughout the entire facility. Ref: WDH Chapter 3 Guidelines, Section 5(a)(ii) 2005 NFPA 99, Section 5-3.13.1.3	S8030	S8030 1) The Director of Clinical Services and Executive Director will contact all oxygen supply companies and ask them to supply oxygen tank holders for all residents that use portable oxygen. a) The Clinical Service Director will discuss this at the next all staff. Any Oxygen tanks that are not being properly stored in tank holders, they will be instructed to tell the Clinical Service Director, so that she can contact that Oxygen Supply Company so they can bring more tank holders over to the community.	6/30/16	
S8032	IPC Life Safety - Int'l Plumbing Cod This State Rule and Regulation is not met as evidenced by: Based on observation and staff interview, the facility failed to maintain the existing plumbing systems in a manner that is in accordance with the WDH Chapter 3 Rules and Regulations for healthcare facilities, in accordance with the original design, and in a safe and sanitary condition. The findings were:	S8032			

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED 06/09/2016
NAME OF PROVIDER OR SUPPLIER PARK PLACE ASSISTED LIVING COMMUNITY			STREET ADDRESS, CITY, STATE, ZIP CODE 1930 EAST 12 STREET CASPER, WY 82601		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
S8032	Continued From page 6 Observation on 06/09/2016 at 9:32 AM in the Dining Room revealed that a vacuum breaker was missing on the coffee machine. At the time of observation interview with the Facility Maintenance Manager revealed he was unaware of the requirement. Ref: 2006 IPC, Section 608.1	S8032	S8032 The Director of Dining Services will contact the company whom we are renting the coffee machine from and have them place a proper vacuum breaker on the coffee machine, or we will contact a certified plumber to have it installed.	7/15/16	