

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: WY0016	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 09/17/2019
NAME OF PROVIDER OR SUPPLIER DOUGLAS CARE CENTER LLC		STREET ADDRESS, CITY, STATE, ZIP CODE 1108 BIRCH STREET DOUGLAS, WY 82633		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S 000	General Comments A Life Safety Code survey was conducted by Healthcare Licensing and Surveys on September 17, 2019. Wyoming Department of Health, Rules and Regulations for Licensure of Nursing Care Facilities Chapter 19, Section 8 Life Safety and Electrical Safety. The requirements in the Department of Health Chapter III, Construction Rules and Regulations for Health Care Facilities apply. The facility was a fully sprinklered single story building with a basement of Type V (111) construction built in 1987 and 2010. The building was equipped with a supervised wet sprinkler system with a dry branch, and an addressable fire alarm system. The facility had a capacity of 60 certified Medicare and Medicaid beds with a census of 55 residents.	S 000		
S7999	State Miscellaneous Life Safety State Miscellaneous This STANDARD is not met as evidenced by: Based on observation and staff interview, the facility failed to maintain roof assemblies and rooftop structures in accordance with the 2006 International Building Code. Failure to maintain roof assemblies and rooftop structures as required could result in mold development and the deterioration of the structural supports. The deficiency affected one (1) of numerous rooms in the facility. The findings were: Observation on 9/17/2019 at 9:24 AM in the kitchen confirmed a water leak above the convection ovens which was first reported by the	S7999	S7999 State Miscellaneous Life Safety The facility will ensure to maintain roof assemblies and rooftop structures in accordance with the 2006 International Building Code. 1. The kitchen water leak above the convection ovens will be repaired. 2. All water leaks that are presented through the building will be repaired. 3. The NHA or designee will educated the maintenance personnel the importance off maintaining roof assemblies. 4. An audit of root assemblies will be	11/4/19

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Electronically Signed

10/03/19

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: WY0016	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 09/17/2019
NAME OF PROVIDER OR SUPPLIER DOUGLAS CARE CENTER LLC		STREET ADDRESS, CITY, STATE, ZIP CODE 1108 BIRCH STREET DOUGLAS, WY 82633		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S7999	Continued From page 1 health team on 9/11/2019. Interview with the kitchen staff stated that the leak only occurs during heavy rains, and happens a couple times a year. Interview with the facility maintenance supervisor at the time of observation acknowledged the deficiency, and indicated awareness of the requirement. Interview with the facility administrator at the time of exit acknowledged the deficiency. REF: 2006 IBC, Section: 1503.2 Flashing	S7999	completed by maintenance personnel monthly and brought to QAPI for three months or until resolved.	