

RECEIVED

JAN 03 2020

PRINTED: 12/10/2019
FORM APPROVED

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF018	(X2) MULTIPLE CONSTRUCTION A. BUILDING: Healthcare Licensing and Surveys B. WING: _____		(X3) DATE SURVEY COMPLETED 12/04/2019
NAME OF PROVIDER OR SUPPLIER SUNDANCE ASSISTED CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 108 ABBY LANE SUNDANCE, WY 82729			
(X4) ID PREFIX TAG S 000	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG S 000	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
	General Comments A Life Safety Code survey was conducted by Healthcare Licensing and Surveys on December 5, 2019. The facility was a single story, fully sprinklered building of Type II (111) construction built in 2001. The building was equipped with a supervised automatic wet sprinkler system, and an addressable fire alarm system. The facility had a capacity of 15 licensed beds with a census of 13 residents. Wyoming Department of Health Rules and Regulations for Licensure of Assisted Living Facilities Chapter 4, Section 10 Life Safety and Electrical Safety. The requirements in the Department of Health Chapter III, Construction Rules for Health Facilities apply. (ii) Assisted Living Facilities in operation prior to the effective date of these rules shall meet the Life Safety Code of the National Fire Protection Association that was in effect at the time the facility was licensed as an Assisted Living Facility. All references are based on the requirements of NFPA 101, Life Safety Code, New Board and Care, 2000 Edition unless otherwise noted.		S8017 <u>1 a. The survey and corrective actions will be posted for all residents and employees to review.</u> <u>b. Staff will be instructed as to the policy to identify red fire alarm breakers.</u> <u>c. The quality assurance system will be adjusted to include monitoring of simulated fire locations.</u> <u>D. recognition will be monitored with different monthly scenerios</u> <u>e. The completion of this corrective action will be established by</u> <i>[Signature]</i> 11-27-19 12-04-19		
S8017	NFPA Life Safety - Nfpa Det, Alarm & Comm Systems NFPA 101 Detection, Alarm and Communication Systems This State Rule and Regulation is not met as evidenced by: Based on observation and staff interview, the facility failed to maintain fire alarm systems in accordance with the 2000 NFPA 101, Life Safety	S8017			

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURETITLE
OWNER

(X6) DATE

12/26/19

STATE FORM

9/2011

If continuation sheet 1 of 2

Talked to WAYNE JOHNSON, Administrator, Per Phone 82
1/6/20 @ 0830 and advised of Pol Acceptance.
Call P ALK
38730

Healthcare Licensing and Surveys

PRINTED: 12/10/2019
FORM APPROVEDSTATEMENT OF DEFICIENCIES
AND PLAN OF CORRECTION(X1) PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

ALF019

(X2) MULTIPLE CONSTRUCTION

A. BUILDING: _____

B. WING: _____

(X3) DATE SURVEY
COMPLETED

12/04/2019

NAME OF PROVIDER OR SUPPLIER

SUNDANCE ASSISTED CARE

STREET ADDRESS, CITY, STATE, ZIP CODE

108 ABBY LANE

SUNDANCE, WY 82729

(X4) ID
PREFIX
TAGSUMMARY STATEMENT OF DEFICIENCIES
(EACH DEFICIENCY MUST BE PRECEDED BY FULL
REGULATORY OR LSC IDENTIFYING INFORMATION)ID
PREFIX
TAGPROVIDER'S PLAN OF CORRECTION
(EACH CORRECTIVE ACTION SHOULD BE
CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY)(X5)
COMPLETE
DATE

S8017

Continued From page 1

Code and the 1999 NFPA 72, National Fire Alarm and Signaling Code. Failure to maintain fire alarm systems as required could result in injury or death during an emergency. The deficiency affected one (1) of numerous requirements for the fire alarm system. The findings were:

Observation on 12/05/2019 at 9:34 AM in the main electrical room revealed that the fire alarm annunciator panel breaker was not marked in red and identified as Fire Alarm Circuit.

Interview with the facility director at the time of observation acknowledged the deficiency, and indicated she was unaware of the requirement.

REF: 2000 NFPA 101, Sections: 32.2.3.4; 9.6.1.4
1999 NFPA 72, Section: 4.4.1.4.2.2

S8017