

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/20/2005
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535019	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/05/2005
NAME OF PROVIDER OR SUPPLIER BONNIE BLUEJACKET MEMORIAL NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 388 SOUTH US HWY 20 BASIN, WY 82410		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	INITIAL COMMENTS Surveyor #: 18185 The regulatory reference is 42 CFR 483.70 (a) except where a different regulation may be specifically referenced. K3: Building- Nursing Home Type V (000) with a complete wet sprinkler system. The facility is a single story building with one smoke barrier. The South Bighorn Hospital is adjacent to the nursing home with a 2-hour fire rated barrier and two 1 1/2-hour fire rated doors. The hospital is a Type II (111) without a sprinkler system. The four closest hospital rooms to the nursing homes 2-hour fire barrier are used for nursing home residents sleeping rooms. K6: Date of Plan Approval Nursing Home 1973, CAH 1956 K7: Life Safety Code surveyed under 2000 Existing Health Care K8: Total Beds=37 ;SNF/NF=37 K9: The facility meets the Life Safety Code standards based on acceptance of a plan of corrections "NFPA" National Fire Protection Association "CAH" Critical Access Hospital	K 000			
K 018 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 1 1/4 inch solid-bonded core wood, capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only	K 018	This facility will ensure that corridor door openings resist the passage of smoke. Resident room #112 will have smoke barrier replaced at gap between the top edge of the corridor door and the door frame		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Jackie Claus Administration 4-29-05

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

RECEIVED AT THE FACILITY WITH JACQUELINE CLAUDIA, MAY 10 5/5/05 @ 2:55 PM VIA TELECONFERENCE. JH JH

PRINTED: 04/20/2005
FORM APPROVED
OMB NO. 0938-0391

FORM CMS-2567(02-99) Previous Versions Obsolete Event ID: W4ER21 Facility ID: WY0002 If continuation sheet Page 2 of 4

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/20/2005
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535019	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/05/2005
NAME OF PROVIDER OR SUPPLIER BONNIE BLUEJACKET MEMORIAL NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 388 SOUTH US HWY 20 BASIN, WY 82410		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 025	Continued From page 2 Based on observation, blue print review, and staff interview on 4/5/05 between 2 PM and 2:30 PM, the facility failed to protect 1 of 1 smoke barriers in accordance with NFPA 101 Section 19.3.7.3 and 8.3.2. The findings were: 1. The smoke barrier in the West corridor had gypsum board on only one side of the wood studs above the ceiling tile. Review of the facilities blue prints with the maintenance director revealed the smoke barrier was originally designed to be a 1-hour fire rated barrier with one sheet of 5/8-inch gypsum board on each side of the wood studs. Maintenance staff verified the gypsum board was only on one side of the wood studs.	K 025	one-half hour fire resistance. Any barriers found not to meet this requirement will have additional fire barriers provided. Monitored by Safety Officer through quarterly Quality Improvement review.	4-25-05	
K 029 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with ¾ hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and staff interview on 4/5/05 between 1 PM and 2 PM, the facility failed to provide 1 of 4 hazardous areas with proper separation in accordance with NFPA 101 Section 19.3.2.1. The findings were: 1. The self-closing device on the soiled utility	K 029	This facility will ensure separation of hazardous area from other spaces by smoke resisting partitions and doors. Self-closing device on soiled utility room door will be adjusted to proper closure and full latch. All hazardous area doors will be checked for proper closure. Those found to have improper closure or latching will be repaired or replaced as appropriate. Monitored by Safety Officer through quarterly Quality Improvement review.	4-6-05	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/20/2005
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 535019	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/05/2005
NAME OF PROVIDER OR SUPPLIER BONNIE BLUEJACKET MEMORIAL NURSING HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 388 SOUTH US HWY 20 BASIN, WY 82410		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 029	Continued From page 3 room near resident room #103 did not fully latch the door into the door frame. Maintenance staff verified the door did not fully latch into the door frame.	K 029			
K 045 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD Illumination of means of egress, including exit discharge, is arranged so that failure of any single lighting fixture (bulb) will not leave the area in darkness. (This does not refer to emergency lighting in accordance with section 7.8.) 19.2.8 This STANDARD is not met as evidenced by: Based on observation on 4/5/05 between 8 PM and 8:30 PM, the facility failed to provide exit discharge lighting fixtures that prevent the loss of illumination if a single bulb failed for 1 of 8 exits in accordance with NFPA 101 Section 19.2.8. The findings were: 1. The South exit discharge light fixture near resident room #206 had two light bulbs which were not illuminated during the evening inspection.	K 045	This facility will ensure exit illumination. Bulbs will be replaced in south exit fixture. All exit lighting will be checked by Maintenance Staff and bulb replacement as appropriate. Monitored by Safety Officer through monthly exit lighting inspection and quarterly Quality Improvement reporting.	4-6-05	