

RECEIVED

PRINTED: 02/09/2021
FORM APPROVED

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES
AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA
IDENTIFICATION NUMBER:

ALF004

(X2) MULTIPLE CONSTRUCTION 2021

A. BUILDING:

Healthcare Licensing and Surveys

B. WING:

(X3) DATE SURVEY
COMPLETED

01/28/2021

NAME OF PROVIDER OR SUPPLIER

PARK PLACE ASSISTED LIVING COMMUNITY

STREET ADDRESS, CITY, STATE, ZIP CODE

1930 EAST 12 STREET
CASPER, WY 82601

(X4) ID
PREFIX
TAG

SUMMARY STATEMENT OF DEFICIENCIES
(EACH DEFICIENCY MUST BE PRECEDED BY FULL
REGULATORY OR LSC IDENTIFYING INFORMATION)

ID
PREFIX
TAG

PROVIDER'S PLAN OF CORRECTION
(EACH CORRECTIVE ACTION SHOULD BE
CROSS-REFERENCED TO THE APPROPRIATE
DEFICIENCY)

(X5)
COMPLETE
DATE

S 000

General Comments

S 000

A Life Safety Code survey was conducted by
Healthcare Licensing and Surveys on January 28,
2021.

The facility was a three story fully sprinklered
building of Type V (111) construction built in 1987.
The building was equipped with a supervised
automatic wet sprinkler system, and an
addressable fire alarm system. The facility had a
capacity of 116 licensed beds with a census of 48
residents.

Wyoming Department of Health Rules and
Regulations for licensure of Assisted Living
Facilities Chapter 4, Section 10, Life Safety and
Electrical Safety. The requirements in the
Department of Health Chapter III, Construction
Rules for Healthcare Facilities apply. (ii) Assisted
Living Facilities in operation prior to the effective
date of these rules shall meet the Life Safety
Code of the National Fire Protection Association
that was in effect at the time the facility was
licensed as an Assisted Living Facility.

All references are based on the requirements of
the NFPA 101, Life Safety Code, New Residential
Board and Care, 1994 Edition, unless otherwise
noted.

S8999

State Miscellaneous Life Safety

S8999

State Miscellaneous

This STANDARD is not met as evidenced by:
Based on observation and staff interview, the
facility failed to maintain medical gas cylinders in

Wyoming Dept of Health, Aging Division, Healthcare Licensing and Surveys
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Executive Director

2-11-2021

If continuation sheet 1 of 3

STATE FORM

5290

R7R011

Talked To Heather Flolin, Executive Director by Phone
on 2/16/21 @ 2:00 PM and advised her of The POC
Acceptance.

Will P. A. K.
38730

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 01/28/2021
NAME OF PROVIDER OR SUPPLIER PARK PLACE ASSISTED LIVING COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 EAST 12 STREET CASPER, WY 82601		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S8999	Continued From page 1 accordance with the 1993 NFPA 99, Health Care Facilities Code. Failure to maintain medical gas cylinders as required could result in injury or death. The deficiency affected one (1) of numerous rooms in the facility. The findings were: Observation on 1/26/21 at 9:28 AM in room 104 revealed several oxygen cylinders sitting on the floor unsecured. Further observation revealed three (3) nine (9) cubic foot cylinders unsecured. Interview with the facility maintenance director at the time of observation acknowledged the deficiency and indicated awareness of the requirement. Interview with the facility administrator at the time of exit acknowledged the deficiency. REF: 1993 NFPA 99, Section: 4-3.1.1.2(3) Based on observation and staff interview, the facility failed to maintain electrical systems in accordance with the 1994 NFPA 101, Life Safety Code, and the 1993 NFPA 70, National Electrical Code. Failure to maintain electrical systems as required could result in injury or death during an emergency. The deficiency affected one (1) of numerous rooms in the facility. The findings were: Observation on 1/28/21 at 9:50 AM in the second floor activities room revealed an extension cord. Further observation revealed nothing plugged into the extension cord. Interview with the facility maintenance director at the time of observation acknowledged the deficiency and indicated awareness of the requirement.	S8999		

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: ALF004	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____		(X3) DATE SURVEY COMPLETED 01/28/2021
NAME OF PROVIDER OR SUPPLIER PARK PLACE ASSISTED LIVING COMMUNITY		STREET ADDRESS, CITY, STATE, ZIP CODE 1930 EAST 12 STREET CASPER, WY 82501			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
S8999	Continued From page 2 Interview with the facility administrator at the time of exit acknowledged the deficiency. REF: 1994 NFPA 101, Section: 7-1.2 1993 NFPA 70, Section: 400-8 Based on observation and staff interview, the facility failed to maintain decorations in accordance with the 1994 NFPA 101, Life Safety Code. Failure to maintain decorations as required could result in injury or death during an emergency. The deficiency affected one (1) of numerous rooms in the facility. The findings were: Observation on 1/28/21 at 9:38 AM in the first floor trash room revealed two small hay bales stored in the room. Interview with the facility maintenance director revealed that the hay bales were used for fall decorations. Interview with the facility maintenance director at the time of observation acknowledged the deficiency, and indicated awareness of the requirement. Interview with the facility administrator at the time of exit acknowledged the deficiency. REF: 1994 NFPA 101, Sections: 31-7.5.1; 31-1.4.5	S8999			

PLAN OF CORRECTION

CLIA ID: ALF004

FACILITY NAME: PARK PLACE ASSISTED LIVING COMMUNITY

SURVEY DATE: 01/28/2021

TAG: S8999

1. CORRECTIVE ACTION

- a. The gas cylinders have since been secured in proper storage containers.
- b. The extension cord was removed immediately by the maintenance director at the time of survey.
- c. The hay bales in the trash room were removed immediately by the activities coordinator at the time of survey.

2. IDENTIFICATION OF OTHERS AT RISK

- a. All residents, staff and guests at the facility were put at risk with these deficiencies. That is why they were all immediately corrected on the spot when they were discovered by the surveyor.

3. SYSTEM MEASURES

Staff will be educated and reminded on the proper way to store gas cylinders. They will also be educated on electrical safety practices and safe storage procedures for miscellaneous decorations and other supplies. Staff will be trained by February 11th 2021. Staff will be required to sign an acknowledgement of this training.

4. MONITORING

The maintenance director will do periodic monitoring (bi-monthly) of storage areas and check electrical outlets for proper usage for the next 3 months and document these audits. The clinical services director will conduct bi-monthly checks of the gas cylinder storage area and document the audits.

5. QA

The corrective action was put into place on January 28th 2021 where the hazardous items were removed and proper storage found for the cylinders. Education for all staff was completed on February 11th 2021 and audits started during the week of February 15th on a bi-monthly basis for 3 months.