

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 255302		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 08/07/2025	
NAME OF PROVIDER OR SUPPLIER SENATOBIA HEALTHCARE & REHAB				STREET ADDRESS, CITY, STATE, ZIP CODE 402 GETWELL DR , SENATOBIA, Mississippi, 38668			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
E0000	Initial Comments		E0000				
	EMERGENCY PREPAREDNESS Survey conducted on 8/5/25 revealed the above facility meets all applicable Federal, State and local emergency preparedness requirements. No deficiencies were cited.						
K0000	INITIAL COMMENTS		K0000				
	42 CFR 483.73						
	The facility meets the applicable provisions of the 2012 (existing) Edition of the Life Safety Code (LSC) of the National Fire Protection Association (NFPA).						
K0341 SS = F	Fire Alarm System - Installation		K0341				
	CFR(s): NFPA 101						
	Fire Alarm System - Installation						
	A fire alarm system is installed with systems and components approved for the purpose in accordance with NFPA 70, National Electric Code, and NFPA 72, National Fire Alarm Code to provide effective warning of fire in any part of the building. In areas not continuously occupied, detection is installed at each fire alarm control unit. In new occupancy, detection is also installed at notification appliance circuit power extenders, and supervising station transmitting equipment. Fire alarm system wiring or other transmission paths are monitored for integrity.						
	18.3.4.1, 19.3.4.1, 9.6, 9.6.1.8						
	This STANDARD is NOT MET as evidenced by:						
	Based on observations, the facility failed to maintain a complete manual fire alarm system as directed by NFPA 72 Chapter 10, and NFPA 101 section 9.6. The deficient practice affected all smoke compartments and all 87 residents in facility on the day of survey. Findings Include: On 8/5/25 at 11:45 AM, observation revealed a "trouble signal" on the fire alarm system panel in the facility. Observation and records record review also revealed the facility was unable the sensitivity inspection of the fire alarm system for the last two						

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See reverse for further instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTIONS		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 255302		(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED 08/07/2025	
NAME OF PROVIDER OR SUPPLIER SENATOBIA HEALTHCARE & REHAB				STREET ADDRESS, CITY, STATE, ZIP CODE 402 GETWELL DR , SENATOBIA, Mississippi, 38668			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K0341 SS = F	Continued from page 1 (2) years.		K0341				