


Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL079033	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/05/2015
NAME OF PROVIDER OR SUPPLIER BEVERLY RUCKER'S FAMILY CARE HOME #2		STREET ADDRESS, CITY, STATE, ZIP CODE 503 NE MARKET STREET REIDSVILLE, NC 27320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Paul Dixon DHSR Construction Section conducted a Biennial Survey on May 5, 2015 from 10:30 AM to 11:45 AM at the above referenced facility. DHSR records indicate the home was first licensed on November 17, 1995 as a Family Care Home for six (6) ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency). Based on this information we are requiring the home to maintain compliance with the following: the 1992 "Rules for Family Care Homes Minimum and Desired Standards and Regulations", the applicable portions of the 2005 Rules 10A NCAC 13G for Family Care Homes, the 1991 (95 Rev) North Carolina State Building Code - Section 514.1 Exception 1 - Residential Care Homes. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:	C 000		
C 148	Outside Entrances/Exits-Free of Obstructions SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (e) All entrances/exits shall be free of all obstructions or impediments to allow for full instant use in case of fire or other emergency. This Rule is not met as evidenced by: Observations during the survey indicated that the side exit door at the end of the hallway had two (2) cinder blocks leaning against the door on the outside. During the survey, the Staff Person on duty removed the cinder blocks. Provide evidence to DHSR that the doorway will remain	C 148		



Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X9) DATE

STATE FORM

8899

SKPK21

If continuation sheet 1 of 2

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL079033	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/05/2015
NAME OF PROVIDER OR SUPPLIER BEVERLY RUCKER'S FAMILY CARE HOME #2		STREET ADDRESS, CITY, STATE, ZIP CODE 503 NE MARKET STREET REIDSVILLE, NC 27320		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 148	Continued From page 1 free of obstructions.	C 148		
C 183	Outside Premises-Clean, Safe SECTION .0300 - THE BUILDING 10A NCAC 13G .0318 OUTSIDE PREMISES (a) The outside grounds of new and existing family care homes shall be maintained in a clean and safe condition. This Rule is not met as evidenced by: 1. Observations during the survey showed that several boards on the ramp from the front porch were warped and protruding above the plane of the ramp. One at the bottom, one approximately 3 feet from the bottom, and one approximately 10 feet from the bottom of the ramp. Have a qualified individual secure or replace the boards. Provide the DHSR Construction section with copies of all invoices, work orders, receipts, photographs and any other supporting documentation concerning this repair. 2. Observations during the survey showed that the window screen for the rear center bedroom is damaged. Have the screen repaired or replaced. Provide the DHSR Construction section with copies of all invoices, work orders, receipts, photographs and any other supporting documentation concerning this repair.	C 183		