

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL017040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 10/26/2018
---	---	--	--

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

G ANTHONY RUCKER REST HOME

**1196 HODGES DAIRY ROAD
YANCEYVILLE, NC 27379**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey by Ed Miller, conducted on October 26, 2018. Deficiencies were cited that will require a new Plan of Correction.	{C 000}		
{C 160}	Outside Premises-Clean, Safe SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (m) The requirements for outside premises are: (1) The outside grounds of new and existing facilities shall be maintained in a clean and safe condition; This Rule is not met as evidenced by: 1. Observations revealed that the outside premises were not maintained in a clean and safe condition. Findings on October 26, 2018: b. Smoking porch - there is a broken table, water cooler and other items that are laying under the porch. d. The stucco finish is falling off of the chimney in chunks. The broken material is on the roof and ground around the chimney. Per staff stucco contractor started repair but has been delayed due to weather. g. The back of the facility has gutters with small plants growing in them.	{C 160}	<i>Administrator will assure that all misc. items be removed from the Smoking porch</i> <i>Administrator will that stucco falling on ground be picked up and that chimney be painted</i> <i>Administrator will assure that gutters be cleared out where small plants are growing in them</i>	<i>11/30/18</i> <i>11/30/18</i> <i>11/30/18</i>
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT	{C 189}		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

G. Anthony Rucker **Owner**

TITLE

(X6) DATE

11/16/18

Division of Health Service Regulation				
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL017040	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 10/26/2018
NAME OF PROVIDER OR SUPPLIER G ANTHONY RUCKER REST HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 1196 HODGES DAIRY ROAD YANCEYVILLE, NC 27379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 189}	Continued From page 1 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 2. Observations revealed that the mechanical equipment is not maintained in operating condition. Findings on October 26, 2018: a. Room 1 - the Return Air grille has a heavy accumulation of dust. 3. Based on observation the facility's fire safety equipment is not maintained in operating condition. Failure to maintain fire safety equipment in operating condition could effect occupants of the facility if the equipment did not function during a fire or other emergency. Findings on October 26, 2018: a. Room 1 - there is no smoke detector or heat detector in the room. 5. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. This could effect occupants of the facility if egress paths and exits were not illuminated during a power outage. Findings on October 26, 2018: a. Dining Room - the emergency light did not illuminate when tested.	{C 189}	<i>Administrator will assure that room #1 return air be cleaned</i> <i>Administrator will assure that smoke detector is placed back in Room #1</i> <i>Administrator will assure that emergency light be repaired</i>	11/30/18 11/30/18 11/30/18

