

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060111	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED R 12/20/2018
NAME OF PROVIDER OR SUPPLIER WILLOW RIDGE ASSISTED LIVING			STREET ADDRESS, CITY, STATE, ZIP CODE 2140 MILTON ROAD CHARLOTTE, NC 28205		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
{C 000}	Initial Comments Construction Section Follow-up Survey report by Frank Strickland on 12/20/2018: Some of the previous cited deficiencies have been corrected. However, there are outstanding deficiencies that require correction action and a new Plan of Correction is required.	{C 000}			
{C 101}	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by: 1. Based on observation, the facility failed to meet the NC State Building Code in effect at the time of construction by not having all of the required components for doors with Special Locking System. This could affect all occupants who would need to evacuate through the door(s) if the exit were obstructed.	{C 101}	Regarding (10A NCAC 13F .0301) All required components for door with special locking system has been corrected to ensure residents evaluate through the door safely	on 1/11/19	

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

6899

J2R823

If continuation sheet 1 of 3

Kathy Ideal RVPD

1/17/2019

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060111	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 12/20/2018
NAME OF PROVIDER OR SUPPLIER WILLOW RIDGE ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 2140 MILTON ROAD CHARLOTTE, NC 28205		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 101}	Continued From page 1 Finding on 12/20/2018: There is a component map, but no wiring diagram posted under glass at the fire alarm panel.	{C 101}	Regarding (Component) map A component map was posted under glass at the fire panel, so residents/occupants can safely evacuate	On 1/14/19
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 2. Based on observation, corridor doors are prevented from closing quickly and latching to resist the passage of fire and smoke. Corridor doors that do not close completely and latch present the possibility that a fire that begins in one space can quickly spread to the corridor and the remainder of the facility. Finding on 20/21/2018: b. The door to the hopper room is not smoke tight near the latch. d. The door to the adjacent Women's room is not smoke tight near the latch. e. The door to the living room is not smoke tight near the latch. f. There was a hole at the latchset through the door to the maintenance room. g. The door to the 100 Hall Shower room is very hard to close and latch. h. The door to room 201 is very hard to close	{C 189}	Regarding (10A NCAC 13F) .0311 All corridor doors that do not close completely and/or latch have been corrected to prevent a potential fire from spreading from one space to the other corridor for all occupants on safety	1/11/2019

Division of Health Service Regulation
STATE FORM

5899

J2R823

If continuation sheet 2 of 3

Kathy Lindo RVPD

* Except 100 Hall Shower room as is scheduled to be repaired on 1/18/19
1/17/2019

Division of Health Service Regulation
STATE FORM