

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: fcI074052	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/19/2024
NAME OF PROVIDER OR SUPPLIER L & C FAMILY CARE HOME #2		STREET ADDRESS, CITY, STATE, ZIP CODE 4224 WASHINGTON STREET AYDEN, NC 28513		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Jonathan Gamsey DHSR Construction Section conducted a Biennial Survey on June 19, 2024 from 09:55 AM to 11:31 AM at the above referenced facility. DHSR records indicate the home was first licensed on December 14, 2021 as a Family Care Home for six (6) ambulatory Clients (Who are able to respond and evacuate without any physical or verbal assistance during a fire or other emergency.)Based on this we are requiring the home to be in compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes, and the 2018 North Carolina State Building Code - Section 428.2 - Small non-ambulatory care facilities. NOTES: 1.) At the time of our visit, we cited deficiencies that require an acceptable plan of correction. All deficiencies listed were discussed with onsite staff during the exit interview. There were previous deficiencies that were not closed out from an open biennial survey, these deficiencies were brought forward from previous survey. 2.) Take actions to correct all listed deficiencies, once completed provide verification in the form of photos, receipts, invoices, etc. for all work performed. The cited deficiencies are as follows:	C 000		
C 147	Outside Entrances/Exits-Single Hand Motion SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (d) All exit door locks shall be easily operable,	C 147		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: fc1074052	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/19/2024
NAME OF PROVIDER OR SUPPLIER L & C FAMILY CARE HOME #2		STREET ADDRESS, CITY, STATE, ZIP CODE 4224 WASHINGTON STREET AYDEN, NC 28513		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 147	Continued From page 1 by a single hand motion, from the inside at all times without keys. Existing deadbolts or turn buttons on the inside of exit doors shall be removed or disabled. This Rule is not met as evidenced by: 1.) At the time of the survey, it was observed that multiple door knobs throughout the facility are not single-hand motion. This could impede egress in a time of need. This is not compliant with the rule. Take the necessary steps to alter the door knobs and or replace them.	C 147		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1.) At the time of the survey, it was observed that the left side of the facility the first bedroom on the left side door would not latch as intended. This is not compliant with the rule. Take the necessary steps to repair the door to ensure it latches as intended. 2.) At the time of the survey, it was observed the left side of the facility the 2nd bedroom window was cracked. This is not compliant with the rule. Take the necessary steps to repair and or replace the window.	C 174		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: fcI074052	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/19/2024
NAME OF PROVIDER OR SUPPLIER L & C FAMILY CARE HOME #2		STREET ADDRESS, CITY, STATE, ZIP CODE 4224 WASHINGTON STREET AYDEN, NC 28513		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 2 3.) At the time of the survey it was observed that the hallway bathroom had a loose toilet at the base causing a potential for leaks to happen and also for residents to be injured when using the facilities. This is not compliant with the rule. Take the necessary steps to secure the toilets to prevent any leaks or possible injuries. 4.) At the time of the survey, it was observed that the staff bedroom window was blocked by a fan. This is not compliant with the rule. Take the necessary steps to remove any obstructions from the staff window to ensure proper egress in a time of need.	C 174		
C 180	Building Service Equipment-Call System SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (f) Where the bedroom of the live-in staff is located in a separate area from residents' bedrooms, an electrically operated call system shall be provided connecting each resident bedroom to the live-in staff bedroom. The resident call system activator shall be such that it can be activated with a single action and remain on until deactivated by staff. The call system activator shall be within reach of resident lying on his bed. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1.) AT the time of the survey, it was observed that the call system was not working. This is not compliant with the rule. Take the necessary steps to bring the call system back to working condition.	C 180		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: fc1074052	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 06/19/2024
NAME OF PROVIDER OR SUPPLIER L & C FAMILY CARE HOME #2		STREET ADDRESS, CITY, STATE, ZIP CODE 4224 WASHINGTON STREET AYDEN, NC 28513		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 183	Outside Premises-Clean, Safe SECTION .0300 - THE BUILDING 10A NCAC 13G .0318 OUTSIDE PREMISES (a) The outside grounds of new and existing family care homes shall be maintained in a clean and safe condition. This Rule is not met as evidenced by: 1.) At the time of the survey, it was observed that the exterior windows were beginning to chip paint. This is not compliant with the rule. Take the necessary steps to remove chipping paint and paint windows. 2.) At the time of the survey, it was observed that the left side vinyl corner guard had a hole in it. This is not compliant with the rule. Take the necessary steps to repair and or replace the corner guard. 3.) At the time of the survey, it was observed that the rear facility ramp had a grade drop to the right of it. This is not compliant with the rule. Take the necessary steps to build the grade back up. 4.) At the time of the survey, it was observed that the rear right deck had loose steps. This is not compliant with the rule. Take the necessary steps to repair and or replace the boards.	C 183		