

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034097	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 07/23/2024
NAME OF PROVIDER OR SUPPLIER MAGNOLIA CREEK ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 2560 WILLARD ROAD WINSTON SALEM, NC 27107		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of Construction Section Biennial Follow Up Survey by Tod Hancock conducted on July 23, 2024. Deficiencies remain uncorrected and a Plan of Correction is required.	{C 000}	Responses to the cited deficiencies do not constitute an admission by the facility of the truth of the facts alleged or conclusions set forth in the statement of deficiencies or corrective action report. The plan of correction is prepared solely as a matter of compliance with state laws.	
{C 111}	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1. Review of records revealed that the facility did not have current fire and building safety inspection reports available for review. Findings July 23, 2024: a. The Fire Alarm Control Panel (FACP) was indicating trouble with the water flow switch and the Fire Sprinkler Inspection report indicated multiple deficiencies including the Quick Opening Device was out of service and the Inspectors Test Valve was clogged. Note: NFPA 25 (2014) Section 14.3.1 (4) Plugging of inspectors test connection requires an obstruction investigation.	{C 111}	Facility had the Fire Sprinkler Inspection on 8/5/2024. First Fire was in charge of doing the inspection for the facility. Both the Quick Opening Device has been put back into service and the Inspectors Test Valve has been unclogged. All parts of the system are normal at this time. Facility has been in compliance since the time of 8/5/2024.	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE