

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL032071	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 05/08/2025
NAME OF PROVIDER OR SUPPLIER CAMELLIA GARDENS		STREET ADDRESS, CITY, STATE, ZIP CODE 5010 S ALSTON AVENUE DURHAM, NC 27713		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey by Suzanna Fay conducted on May 8, 2025. There are deficiencies cited in the Biennial Construction Survey that remain to be corrected.	{C 000}		
{C 134}	Bathrooms-Roll-in Shower SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (e) The requirements for bathrooms and toilet rooms are: (7) Each home shall have at least one bathroom opening off the corridor with: (A) a door of three feet minimum width; (B) a three feet by three feet roll-in shower designed to allow the staff to assist a resident in taking a shower without the staff getting wet; (C) a bathtub accessible on at least two sides; (D) a lavatory; and (E) a toilet. (8) If the tub and shower are in separate rooms, each room shall have a lavatory and a toilet; This Rule is not met as evidenced by: 1. Observations revealed that the facility did not have a bathroom opening off the corridor with a bathtub accessible on at least two sides. Findings May 8, 2025: a. The facility had one bathroom opening off the corridor for residents with a shower only. The tub had been removed. Interview with staff revealed that they have not been able to find a tub that meets these requirements.	{C 134}		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL032071	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 05/08/2025
NAME OF PROVIDER OR SUPPLIER CAMELLIA GARDENS		STREET ADDRESS, CITY, STATE, ZIP CODE 5010 S ALSTON AVENUE DURHAM, NC 27713		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 199}	Continued From page 1	{C 199}		
{C 199}	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Observations revealed that the facility did not maintain exhaust ventilation in specified spaces. Lack of ventilation allows for the buildup of humidity that can cause mildew and slick areas and prevents the dissipation of odors. Findings May 8, 2025: a. There was a pattern of fans not working in the facility. Some locations include but are not limited to: Community Bath, Staff Bathroom, Laundry by Room 34, and Housekeeping. Interview with staff revealed that they had made repairs and found not all of the units worked. They are waiting on repairs to another unit.	{C 199}		