

North Dakota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8072	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - WATERFORD ON CENTURY B. WING _____	(X3) DATE SURVEY COMPLETED 05/03/2021
NAME OF PROVIDER OR SUPPLIER TOUCHMARK ON WEST CENTURY LLC		STREET ADDRESS, CITY, STATE, ZIP CODE 1000 W CENTURY AVE BISMARCK, ND 58503		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 32 New Residential Board and Care Occupancies (Large) and Chapter 33 Existing Residential Board and Care Occupancies (Large), in compliance with NDAC 33-03-24.2. The facility was located on the first floor of a three-story structure of Type V (111) construction. A two-story addition of Type V (111) construction was attached to the southwest side of the existing building in 2016. The buildings were protected throughout by an automatic fire sprinkler system designed to meet the requirements of NFPA 13, Standard for the Installation of Sprinkler Systems. The 2016 addition was surveyed using Chapter 32 of the Life Safety Code. A two-hour horizontal occupancy separation at the floor/ceiling assemblies and a vertical occupancy separation at the north and east sides isolates the basic care from the assisted living. Resident evaluation determined a slow level of evacuation difficulty. The E Score was 1.68. Note: At the conclusion of the 05/03/2021 Life Safety Code survey, it was determined the facility was in compliance with the provisions of NFPA 101, Life Safety Code.	K 000		

Health Resources Section

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE