

North Dakota Health and Human Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8059	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 12/10/2024
NAME OF PROVIDER OR SUPPLIER DAKOTA POINTE		STREET ADDRESS, CITY, STATE, ZIP CODE 3503 43RD ST NW MANDAN, ND 58554		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 33 Existing Residential Board and Care Occupancies (Small), in compliance with NDAC 33-03-24.2. The facility was located in a one-story Type V (000) building with no basement. The building was fully sheathed and was protected with an automatic sprinkler system designed to meet the requirements of NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height. The attic space was protected with a heat detection system. Based on resident evaluation, a Prompt level of evacuation difficulty was determined. E-score was .40. Note: Observation and records review determined the facility to be in compliance with the minimum requirements of the 2012 Life Safety Code.	K 000		

Health Repsonse and Licensure

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE