



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900


Business Name Aljoya Thornton Place
Address 450 100TH ,
City, State, Zip Seattle, WA 98125


Provider Number 2040
Approval Status Approved
Facility Type Residential Care

On 03/11/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature


Print Name and Title

Executive
Director

Deputy State Fire Marshal Alan Harlan
2803 156TH AVE SE
Bellevue WA 98007
(425) 495-7121


Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Aljoya Thornton Place	Provider Number 2040
Address 450 100TH ,	Approval Status Disapproved
City, State, Zip Seattle, WA	Facility Type Residential Care

On 10/7/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Contents

Fire safety, evacuation and lockdown plan contents shall be in accordance with Sections 404.2.1 through 404.2.3.2.

(IFC 404.2 2021)

Findings during the reinspection were:

Facility cannot provide documentation for the completion of unannounced fire drills, one drill per shift, per quarter, in the previous 12 months.

2 Cleaning

Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3.

(IFC 606.3.3 2021)

Findings during the reinspection were:

Documentation provided for the facility's semi-annual hood cleaning indicated a deficiency within the duct system.

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

3 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space.

(IFC 701.6 2021)

Corrected

4 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.

(IFC 705.2.4 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Aljaya Thornton Place	Provider Number 2040
Address 450 100TH ,	Approval Status Disapproved
City, State, Zip Seattle, WA	Facility Type Residential Care

On 10/7/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

5 Duct and Air Transfer Openings - Maintaining Protection

Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced. (IFC 706.1 2018)	Corrected
---	-----------

6 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	Findings during the reinspection were: Facility is unable to provide documentation for the 5 year internal piping inspection. Facility was unable to provide documentation that the Fire Department Connection has been hydrostatically tested in accordance with NFPA 25. NFPA 25 (2017) 13.8.5 The piping from the fire department connection to the fire department check valve shall be hydrostatically tested at 150 psi (10 bar) for 2 hours at least once *All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.*
--	--

7 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	Findings during the reinspection were: Facility is unable to provide documentation for the monthly single or multi station smoke alarm testing *All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.*
--	---



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Aljoya Thornton Place	Provider Number 2040
Address 450 100TH ,	Approval Status Disapproved
City, State, Zip Seattle, WA	Facility Type Residential Care

On 10/7/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

8 Carbon Monoxide Detection - General

Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code.

(IFC 0915.1 2021 WAC 51-54A)

Findings during the reinspection were:

Facility is unable to provide documentation for the monthly carbon monoxide detector testing.

NFPA 720

8.7.1 Single - and multiple-station carbon monoxide alarms and all connected appliances shall be inspected and tested in accordance with the manufacturer's published instructions at least monthly.

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

9 Means of Egress Continuity

The path of egress travel along a means of egress shall not be interrupted by any building element other than a means of egress component as specified in this chapter. Obstructions shall not be placed in the minimum width or required capacity of a means of egress component except projections permitted by this chapter. The minimum width or required capacity of a means of egress system shall not be diminished along the path of egress travel.

(IFC 1003.6 2021)

Findings during the reinspection were:

The fireside lounge balcony egress pathway is blocked by a piano.

10 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.

(IFC 1203.4 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Aljoya Thornton Place	Provider Number	2040
Address	450 100TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA	Facility Type	Residential Care


On 10/7/2025 the Office of the State Fire Marshal conducted an inspection at your facility.


Code Requirement	Statement of Violation
------------------	------------------------

Next inspection scheduled on or after: 11/20/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

 **Facilities Director**
Print Name and Title

Deputy State Fire Marshal Damon Roberson
2803 156 AVE SE
Bellevue WA 98007
(360) 584-4392


Signature