

State Form: Revisit Report

(Y1) Provider / Supplier / CLIA / Identification Number ALF028	(Y2) Multiple Construction A. Building B. Wing	(Y3) Date of Revisit 09/01/2015
Name of Facility MOUNTAIN PLAZA ASSISTED LIVING	Street Address, City, State, Zip Code 4154 TALON DRIVE CASPER, WY 82604	

This report is completed by a State surveyor to show those deficiencies previously reported that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the State Survey Report (prefix codes shown to the left of each requirement on the survey report form).

(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date	(Y4) Item	(Y5) Date
Correction Completed ID Prefix S8003 Reg. # NFPA LSC	06/10/2015	Correction Completed ID Prefix S8004 Reg. # NFPA LSC	07/09/2015	Correction Completed ID Prefix S8015 Reg. # NFPA LSC	07/09/2015
Correction Completed ID Prefix S8018 Reg. # NFPA LSC	07/09/2015	Correction Completed ID Prefix S8022 Reg. # NFPA LSC	06/10/2015	Correction Completed ID Prefix Reg. # LSC	
Correction Completed ID Prefix Reg. # LSC		Correction Completed ID Prefix Reg. # LSC		Correction Completed ID Prefix Reg. # LSC	
Correction Completed ID Prefix Reg. # LSC		Correction Completed ID Prefix Reg. # LSC		Correction Completed ID Prefix Reg. # LSC	
Correction Completed ID Prefix Reg. # LSC		Correction Completed ID Prefix Reg. # LSC		Correction Completed ID Prefix Reg. # LSC	
Correction Completed ID Prefix Reg. # LSC		Correction Completed ID Prefix Reg. # LSC		Correction Completed ID Prefix Reg. # LSC	
Reviewed By State Agency	Reviewed By TS 9/2/15	Date:	Signature of Surveyor:		Date: 9/02/15
Reviewed By CMS RO	Reviewed By	Date:	Signature of Surveyor:		
Followup to Survey Completed on: 06/09/2015		Check for any Uncorrected Deficiencies. Was a Summary of Uncorrected Deficiencies (CMS-2567) Sent to the Facility? YES NO			