STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	FCL001089	A. BUILDING: **01** B. WING _____	**03/14/2017**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
C & M ADULT CARE HOME	**422 N MAIN STREET** **BURLINGTON, NC 27217**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Suzanna Fay DHSR Construction Section conducted a Biennial Survey on March 14, 2017 from 10:07 AM to 11:39 AM at the above referenced facility. DHSR records indicate the home was first licensed on November 19, 1991 as a Family Care Home for six ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency.) Based on this information we are requiring the home to maintain compliance with the following: the 1991 Family Care Homes Minimum Standards and Regulations, applicable portions of the 2005 Rules 10A NCAC 13G for Family Care Homes and the 2006 North Carolina State Building Code - Section 513.1, Exception 1 - Residential Care Facilities. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:	C 000		
C 153	Houskeeping And Furnishings-Clean, Repaired SECTION .0300 - THE BUILDING 10A NCAC 13G .0315 HOUSEKEEPING AND FURNISHINGS (a) Each family care home shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing homes. This Rule is not met as evidenced by: 1. Observations revealed that the ceiling of the Staff bath was cracked and peeling in the corner	C 153		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	FCL001089	A. BUILDING: **01** B. WING _____	**03/14/2017**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
C & M ADULT CARE HOME	**422 N MAIN STREET** **BURLINGTON, NC 27217**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 153	Continued From page 1 by the door. Have a qualified technician repair the ceiling finish. Provide documentation of the repairs in the form of photos or receipts.	C 153		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. Observations revealed that the emergency light outside of the dining room did not work when tested. Have a qualified technician repair the light. Provide documentation of the repairs in the form of photos or receipts. 2. Observations revealed that the downspout at the back left corner of the facility had fall off. Have a qualified technician reattach the downspout. Provide documentation of the repairs in the form of photos or receipts.	C 174		
C 143	Outside Exits-Locks Single Hand Motion IV. The Building C. Physical Environment (10 NCAC 42C .2201) 8. Outside Entrances/Exits (10 NCAC 42C .2209) d. All exit doors locks must be easily operable, by a single hand motion, from the inside at all times without keys. (This limits each door to one locking device which meets the criteria set forth in	C 143		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	FCL001089	A. BUILDING: **01** B. WING _____	**03/14/2017**

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
C & M ADULT CARE HOME	**422 N MAIN STREET** **BURLINGTON, NC 27217**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 143	Continued From page 2 this standard.) This Rule is not met as evidenced by: 1. Observations revealed that the screen door at the dining room exit had a thumb latch that is not single action. Have a qualified technician remove or disable the thumb latch. Provide documentation of the repairs in the form of photos or receipts.	C 143		
C 148	Floors IV. The Building C. Physical Environment (10 NCAC 42C .2201) 10. Floors (10 NCAC 42C .2211) a. All floors must be of smooth, non-skid material and so constructed as to be easily cleanable. b. Scatter or throw rugs are not to be used. c. All floors must be kept in good repair. This Rule is not met as evidenced by: 1. Observations revealed that the vinyl floors throughout the main level were not maintained. The floors in the halls, the bathrooms and bedrooms were worn and torn. Some of the areas had been patched with packing tape. Interview with Staff revealed that they had a contract to replace the flooring. Provide documentation of the completed repairs in the form of photos or receipts.	C 148		