STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X3) DATE SURVEY COMPLETED
	AL11966547	**10/16/2018**
NAME OF PROVIDER OR SUPPLIER **ADA ALF INC**	STREET ADDRESS, CITY, STATE, ZIP CODE **683 NW 122 Place** **MIAMI, FL 33182**	

SUMMARY STATEMENT OF DEFICIENCIES
(FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)

0000 - Initial Comments

A Generator Monitoring Survey was conducted on . . . . . Ada ALF Inc with License #10770 had a deficiency at the time of the survey:

0200 - Emergency Environmental Control - 58A-5.036 FAC

Based on observation and interview, the facility failed to fully comply with the requirements of the Emergency Environmental Control Plan. The facility did not have monoxide . . . . detectors installed.

Findings included:

During a tour of the facility on . . . . . at 18:36 AM no . . . . monoxide detectors were observed.

During an interview on . . . . . at 8:58 AM, the Administrator stated "we were never told to put a . . . . monoxide detector in the facility."

Class III