Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING	(X3) DATE SURVEY COMPLETED
	FCL001140		R 08/05/2015

NAME OF PROVIDER OR SUPPLIER
CREEKVIEW FAMILY CARE HOME

STREET ADDRESS, CITY, STATE, ZIP CODE
3524 DICKEY MILL ROAD
MEBANE, NC 27302

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report by Robin Fay and Rick Benton A Biennial follow-up survey was conducted on August 5, 2015 from 1:00pm to 2:00pm at the above referenced facility. Several listed deficiencies remain uncorrected from the May 5, 2015 Biennial survey. There were also new deficiencies from the August 5, 2015 Biennial follow-up survey that will be addressed in this report. The new and uncorrected deficiencies will require another Plan of Correction. They are as follows:	{C 000}		
{C 153}	Houskeeping And Furnishings-Clean, Repaired SECTION .0300 - THE BUILDING 10A NCAC 13G .0315 HOUSEKEEPING AND FURNISHINGS (a) Each family care home shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing homes. This Rule is not met as evidenced by: 1) In the Kitchen, the cabinet to the left of the range is missing the bottom drawer. Locate and install the missing drawer. Proof of completed work must be provided by way of receipts, invoices, photographs, etc. Forward proof of completed work with you plan of correction. *05/05/2015-PD: Observations during the Follow-Up Survey indicated that the drawer is still missing. Locate and install the missing drawer. Proof of completed work must be provided by way of receipts, invoices, photographs, etc.	{C 153}	**08/05/2015 RB/RF The air exchange vent in the water heater/furnance closet is in need of cleaning and painting or replacement.	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	FCL001140	A. BUILDING: 01 B. WING _____	R 08/05/2015

NAME OF PROVIDER OR SUPPLIER

CREEKVIEW FAMILY CARE HOME

STREET ADDRESS, CITY, STATE, ZIP CODE

3524 DICKEY MILL ROAD
MEBANE, NC 27302

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 153}	Continued From page 1 Forward proof of completed work with you plan of correction. **08/05/2015 - RB/RF: This deficiency remains uncorrected. At the time of the survey, the drawer was being held in place with duct tape. This deficiency must be corrected. Provide to our office any supporting documentation that verifies the completed work.	{C 153}		
{C 174}	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: NEW DEFICIENCIES 1) On the rear of the home, the doors from the den leading to the porch/deck have rotted wood below the glass on the lower sections of both doors. Provide to our office any supporting documentation that verifies the completed work. 2) The carpet in the den leading to the rear of the home is extremely stained. Contact a qualified technician to have the carpet cleaned. Provide to our office a receipt from the carpet technician that verifies the completed work.	{C 174}	**RB/RF The air exchange vent for the furance and water heater closet is in need of cleaning and painting or replacement.	