Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Kenney	***Provider Number***	128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Approved
City, State, Zip	Seattle, WA	***Facility Type***	Residential Care

On 01/21/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or ~~Owner's~~ Representative

Joe Reno

Signature

Joe Reno Facilities Director

Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2502 112 ST E
Tacoma WA 984455104
(509) 406-7209

DSFM Van Gorkum, Jason

Digitally signed by DSFM Van Gorkum, Jason
Date: 2026.01.21 10:20:39 -08'00'

Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA	***Facility Type***	Residential Care

On 08/12/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Annual report, 3/19/2024 report has deficiencies 2. Annual forward flow test (NFPA 25 13.7.2) 3. Quarterly inspections All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: 1. 2nd floor kitchen AL side dry storage room has a blocked sprinkler from ceiling tiles. 2..Main kitchen has sprinkler system that shows it has notbeen inspected since 2019.

2 Extinguishing System Service

Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion. (IFC 904.13.5.2 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. First semi-annual servicing 4/2/2024 report has deficiencies 2. Second semi-annual service All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: 1. Main kitchen suppression system shows past due plus in yellow statis 2. AL Kitchen suppression system shows past due.

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA	***Facility Type***	Residential Care

On 08/12/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
3 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	The following deficiencies were cited as a result of thisinspection: At the time of inspection, the following paperwork was not provided: 2. Sensitivity Testing (IFC 907.8.3) 4/24/2024 report has deficiencies All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
4 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 3. Monthly 30-minute full load test All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of Re-inspection the following was observed: 1. Facility looks to not be performing 30 min load test per paperwork On next annual testing, 4-hour load test will be required.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA	***Facility Type***	Residential Care

On 08/12/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

Next inspection scheduled on or after: 09/11/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Seth Crawford
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2803 156 AVE SE
Bellevue WA 98007
(509) 406-7209

Signature

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Time

Drills shall be held at unexpected times and under varying conditions to simulate the unusual conditions that occur in case of fire. Exceptions: 1. In severe climates, the fire code official shall have the authority to modify the emergency evacuation drill termination points and frequency. 2. In Groups I-1, I-2, I-3 and R-4, where staff-only emergency evacuation drills are conducted after visiting hours or where care recipients are expected to be asleep, a coded announcement shall be an acceptable alternative to audible alarms. (IFC 405.2 2021) Records shall be maintained of required emergency evacuation drills and include the following information: 1. Identity of the person conducting the drill. 2. Date and time of the drill. 3. Notification method used. 4. Employees on duty and participating. 5. Number of occupants evacuated. 6. Special conditions simulated. 7. Problems encountered. 8. Weather conditions when occupants were evacuated. 9. Time required to accomplish complete evacuation. (IFC 0405.6 2021) Where a fire alarm system is provided, emergency evacuation drills shall be initiated by activating the fire alarm system. (IFC 405.8, 2021	Corrected

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
2 Owner's Responsibility	
The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	Corrected
3 Penetrations - Maintaining Protection	
Materials and firestop systems used to protect membrane and through penetrations in fire-resistance-rated construction and construction installed to resist the passage of smoke shall be maintained. The materials and firestop systems shall be securely attached to or bonded to the construction being penetrated with no openings visible through or into the cavity of the construction. Where the system design number is known, the system shall be inspected to the listing criteria and manufacturer's installation instructions. (IFC 703.1 2021)	Corrected
4 Door Operation	
Swinging fire doors shall close from the full-open position and latch automatically. (IFC 705.2.4 2021)	Corrected
5 Testing	
Horizontal and vertical sliding and rolling fire doors shall be inspected and tested annually to confirm proper operation and full closure. Records of inspections and testing shall be maintained. (IFC 705.2.6 2018)	Corrected

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
6 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 3/19/2024 report has deficiencies 1. Annual report Corrected, due 10/2025 2. 5-Year internal pipe Testing (NFPA 25 14.2.1.1) Corrected Due, 9/2025 3. 3-Year Dry System Full flow trip test (NFPA 25 13.1.1.2) Corrected 4. Annual Trip Test (NFPA 25 13.1.1.2) 5. Annual forward flow test (NFPA 25 13.7.2) Corrected , due 10/2025 6. 5-Year FDC Hydro testing (NFPA 25 13.8.5) 7. Quarterly inspections All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: Corrected 1. 3rd floor next to elevators has wires connect to sprinkler line. 2. 2nd floor kitchen AL side dry storage room has a blocked sprinkler from ceiling tiles. 3. Main kitchen has sprinkler system that shows it has not been inspected since 2019.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
7 Extinguishing System Service	
Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion. (IFC 904.13.5.2 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 4/2/2024 report has deficiencies 1. First semi-annual servicing 2. Second semi-annual service All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: 1. Main kitchen suppression system shows past due plus in yellow statis 2. AL Kitchen suppression system shows past due.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
8 Portable Fire Extinguishers - General Requirements	
Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10. Exceptions: 1. The distance of travel to reach an extinguisher shall not apply The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies. 2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met: 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed. 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal. 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment. 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed. 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10. 3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations. (IFC 906.2 2021)	Corrected

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: Corrected 1. Annual report 4/24/2024 report has deficiencies 2. Sensitivity Testing (IFC 907.8.3) Corrected 3. Monthly single and multiple station alarms test (IFC 907.8) All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: Corrected 1. Covered smoke detection found in wood shop.
10 Carbon Monoxide Detection - General	
Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code. (IFC 0915.1 2021 WAC 51-54A)	Corrected
11 Activation Test	
Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired. (IFC 1032.10.1 2021)	Corrected

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
12 Power Test	
Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	Corrected
13 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: Corrected 1. Annual service report Corrected 2. Log of weekly inspections Deficiencies 3. Monthly 30-minute full load test Corrected 4. Diesel fuel testing All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of Re-inspection the following was observed: 1. Facility looks to not be performing 30 min load test per paperwork On next annual testing, 4-hour load test will be required.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
14 NFPA 80 Fire Door Inspection and Testing	
5.2.1 Inspection and Testing. Upon completin of the installation, door, shutters, and window assemblies shall be inspected and tested in accordance with 5.2.4. 5.2.4 Periodic Inspection and Testing. 5.2.4.1 Periodic inspections and testing shall be performed not less than annually. 5.2.2.4 A record of all inspections and testing shall be provided that includes, but is not limited to, the following information: 1. Date of inspection 2. Name of facility 3. Address of facility 4. Name of person(s) performing inspections and testing 5. Company name and address of inspecting company 6. Signature of inspector of record 7. Individual record of each inspected and tested fire door assembly 8. Opening identifier and location of each inspected and tested fire door assembly 9. Type and description of each inspected and tested fire door assembly 10. Verification of visual inspection and functional operation 11. Listing of deficiencies in accordance with 5.2.3, Section 5.3, and Section 5.4 And the following hall be checked: 1. Labels are clearly visible and legible 2. No open holes or breaks exist in surfaces of wither the door or frame 3. Glazing, vision light frames, and glazing beads are intact and securely fastened in place, if so equipped. 4. The door, frame, hinges, hardware, and non combustible threshold are secured, aligned and in working order with no visible, signs of damage 5. No parts are missing or broken 6. Door clearances do not exceed clearances listed in 4.8.4 and 6.3.1.7 7. The self-closing device is operational,: that is, the active door completely closes when operated from the full open position 8. If a coordinator is installed, the inactive lead close before the active lead	Corrected

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 03/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9. Latching hardware operates and secures the door when it is in the closed positon 10. Auxiliary hardware items that interfere or prohibit operation are not installed on the door or frame 11. No field modification to the door assembly have been preformed that void the label. 12. Meeting edge protection, gasketing and edge seals where required, are inspected to verify their presence and intertie 13. Signage affixed to a door meets the requirements listed in 4.1.4	

Next inspection scheduled on or after: 04/10/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Joe Reno Facilities Director
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2803 156 AVE SE
Bellevue WA 98007
(509) 406-7209

Signature

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Time

Drills shall be held at unexpected times and under varying conditions to simulate the unusual conditions that occur in case of fire. Exceptions: 1. In severe climates, the fire code official shall have the authority to modify the emergency evacuation drill termination points and frequency. 2. In Groups I-1, I-2, I-3 and R-4, where staff-only emergency evacuation drills are conducted after visiting hours or where care recipients are expected to be asleep, a coded announcement shall be an acceptable alternative to audible alarms. (IFC 405.2 2021) Records shall be maintained of required emergency evacuation drills and include the following information: 1. Identity of the person conducting the drill. 2. Date and time of the drill. 3. Notification method used. 4. Employees on duty and participating. 5. Number of occupants evacuated. 6. Special conditions simulated. 7. Problems encountered. 8. Weather conditions when occupants were evacuated. 9. Time required to accomplish complete evacuation. (IFC 0405.6 2021) Where a fire alarm system is provided, emergency evacuation drills shall be initiated by activating the fire alarm system. (IFC 405.8, 2021	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Facility cannot provide documentation for the completion of twelve planned and unannounced fire drills in the previous 12 months. The following drills are missing. 1st Shift - Quarter 4 2nd Shift - Quarter 4 3rd Shift - Quarter 4 All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
2 Owner's Responsibility	
The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Facility will need to identify and establish a schedule for inspection of Fire-Rated construction. Annual inspection of fire-resistance-rated construction will need to be performed and completed. All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
3 Penetrations - Maintaining Protection	
Materials and firestop systems used to protect membrane and through penetrations in fire-resistance-rated construction and construction installed to resist the passage of smoke shall be maintained. The materials and firestop systems shall be securely attached to or bonded to the construction being penetrated with no openings visible through or into the cavity of the construction. Where the system design number is known, the system shall be inspected to the listing criteria and manufacturer's installation instructions. (IFC 703.1 2021)	At time of inspection the following was observed: 1. 3rd floor stairwell outside elevator has a penetration through fire wall
4 Door Operation	
Swinging fire doors shall close from the full-open position and latch automatically. (IFC 705.2.4 2021)	At time of inspection the following was observed: 1. 4th floor Double doors will not latch outside of administrators office.
5 Testing	
Horizontal and vertical sliding and rolling fire doors shall be inspected and tested annually to confirm proper operation and full closure. Records of inspections and testing shall be maintained. (IFC 705.2.6 2018)	At time of inspection the following was observed: 1. Kitchen AL side has a roll up fire door showing past due for inspection.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
6 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Annual report O Def. 2. 5-Year internal pipe Testing (NFPA 25 14.2.1.1) ✓ 3. 3-Year Dry System Full flow trip test (NFPA 25 13.1.1.2) ✓ 4. Annual Trip Test (NFPA 25 13.1.1.2) ✓ 5. Annual forward flow test (NFPA 25 13.7.2) O ✓ 6. 5-Year FDC Hydro testing (NFPA 25 13.8.5) ✓ 7. Quarterly inspections O All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: 1. 3rd floor next to elevators has wires connect to sprinkler line. ✓ 2. 2nd floor kitchen AL side dry storage room has a blocked sprinkler from ceiling tiles. O 3. Main kitchen has sprinkler system that shows it has not been inspected since 2019. O

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
7 Extinguishing System Service	
Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion. (IFC 904.13.5.2 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. First semi-annual servicing ✓ Def 2. Second semi-annual service O All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: 1. Main kitchen suppression system shows past due plus in O yellow statis 2. AL Kitchen suppression system shows past due. O

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

8 Portable Fire Extinguishers - General Requirements

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10. Exceptions: 1. The distance of travel to reach an extinguisher shall not apply The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies. 2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met: 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed. 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal. 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment. 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed. 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10. 3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations. (IFC 906.2 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Annual Servicing (NFPA 10 7.3) ✓ 2. Monthly Inspection by Facility Maintenance Log Provided ✓ (NFPA 10 7.2) All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Annual report ✓ 2. Sensitivity Testing (IFC 907.8.3) o Def 3. Monthly single and multiple station alarms test (IFC 907.8) ✓ All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: 1. Covered smoke detection found in wood shop.
10 Carbon Monoxide Detection - General	
Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code. (IFC 0915.1 2021 WAC 51-54A)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Carbon Monoxide Alarms and Detectors will need to be tested, maintained and documented on am monthly schedule ✓ All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
11 Activation Test	
Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired. (IFC 1032.10.1 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Monthly 30-second activation testing had not been performed and documented All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
12 Power Test	
Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Annual 90 minute power test had not been performed and documented All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
13 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Annual service report 2. Log of weekly inspections 3. Monthly 30-minute full load test ⊘ about 15 min 4. Diesel fuel testing All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
14 NFPA 80 Fire Door Inspection and Testing	
5.2.1 Inspection and Testing. Upon completin of the installation, door, shutters, and window assemblies shall be inspected and tested in accordance with 5.2.4. 5.2.4 Periodic Inspection and Testing. 5.2.4.1 Periodic inspections and testing shall be performed not less than annually. 5.2.2.4 A record of all inspections and testing shall be provided that includes, but is not limited to, the following information: 1. Date of inspection 2. Name of facility 3. Address of facility 4. Name of person(s) performing inspections and testing 5. Company name and address of inspecting company 6. Signature of inspector of record 7. Individual record of each inspected and tested fire door assembly 8. Opening identifier and location of each inspected and tested fire door assembly 9. Type and description of each inspected and tested fire door assembly 10. Verification of visual inspection and functional operation 11. Listing of deficiencies in accordance with 5.2.3, Section 5.3, and Section 5.4 And the following hall be checked: 1. Labels are clearly visible and legible 2. No open holes or breaks exist in surfaces of wither the door or frame 3. Glazing, vision light frames, and glazing beads are intact and securely fastened in place, if so equipped. 4. The door, frame, hinges, hardware, and non combustible threshold are secured, aligned and in working order with no visible, signs of damage 5. No parts are missing or broken 6. Door clearances do not exceed clearances listed in 4.8.4 and 6.3.1.7 7. The self-closing device is operational,: that is, the active door completely closes when operated from the full open position 8. If a coordinator is installed, the inactive lead close before the active lead	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Facility will need to identify and establish a schedule for inspection of Fire Doors. Annual inspection of fire doors will need to be performed and completed. All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Kenney, The	***Provider Number***	000128
Address	7125 FAUNTLEROY WAY SW,	***Approval Status***	Disapproved
City, State, Zip	Seattle, WA 98136	***Facility Type***	Residential Care

On 01/13/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9. Latching hardware operates and secures the door when it is in the closed positon 10. Auxiliary hardware items that interfere or prohibit operation are not installed on the door or frame 11. No field modification to the door assembly have been preformed that void the label. 12. Meeting edge protection, gasketing and edge seals where required, are inspected to verify their presence and intertie 13. Signage affixed to a door meets the requirements listed in 4.1.4	

Next inspection scheduled on or after: 02/12/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Joe Reno Facilities Director
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2803 156 AVE SE
Bellevue WA 98007
(509) 406-7209

Jason E Van Gorkum
Signature

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.