DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 05/31/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	535036	A. BUILDING 01 - MAIN BUILDING 01 B. WING	05/26/2017

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
RAWLINS REHABILITATION AND WELLNESS	542 18TH STREET RAWLINS, WY 82301

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	INITIAL COMMENTS A Life Safety Code survey was conducted by Healthcare Licensing and Surveys on May 25, 2017. Requirements for Long Term Nursing Homes Section 42 CFR 483.70 (a) except as otherwise provided in the section, the facility must meet the applicable provisions of the 2012 Edition of the Life Safety Code, Existing Health Care of the National Fire Protection Association. The facility was a partially sprinklered, single story building with a basement of Type V (111) construction built in 1966. The building was equipped with a supervised automatic wet sprinkler system with an addressable fire alarm system. The facility had a capacity of 62 certified Medicare and Medicaid beds with a census of 38 residents.	K 000	This Plan of Correction is the center's credible allegation of compliance. Preparation and/or execution of this plan of correction does not constitute admission or agreement by the provider of the truth of the facts alleged or conclusions set forth in the statement of the deficiencies. The plan of correction is prepared and/or executed solely because it is required by the provisions of federal and state law.	
K 351 SS=E	NFPA 101 Sprinkler System - Installation Sprinkler System - Installation 2012 EXISTING Nursing homes, and hospitals where required by construction type, are protected throughout by an approved automatic sprinkler system in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems. In Type I and II construction, alternative protection measures are permitted to be substituted for sprinkler protection in specific areas where state or local regulations prohibit sprinklers. In hospitals, sprinklers are not required in clothes closets of patient sleeping rooms where the area of the closet does not exceed 6 square feet and sprinkler coverage covers the closet footprint as required by NFPA 13, Standard for Installation of	K 351	K351 Corrective action: Bids will be obtained for installation of sprinklers in resident closets. Bids/plans will be submitted to State of Wyoming Life Safety office for approval. ID of others: No other areas identified as not having sufficient sprinkler coverage. Systemic Changes: Sprinkler installation to closets. Monitoring: Progress toward installation of sprinklers will be reported to monthly QAPI until project has been completed.	11/25/17

ORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE: NHA | (X5) DATE: 6/17/17

deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that er safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days owing the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 s following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued gram participation.

JUN 17 2017
Healthcare Licensing and Surveys

M CMS-2567(02-99) Previous Versions Obsolete | Event ID: XTCS21 | Facility ID: WY0029 | If continuation sheet Page 1 of 2

Accepted for POC on 6-27-17

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 05/31/2017
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	535036	A. BUILDING 01 - MAIN BUILDING 01 B. WING _____	05/25/2017

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
RAWLINS REHABILITATION AND WELLNESS	542 16TH STREET RAWLINS, WY 82301

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 351	Continued From page 1 Sprinkler Systems. 19.3.5.1, 19.3.5.2, 19.3.5.3, 19.3.5.4, 19.3.5.5, 19.4.2, 19.3.5.10, 9.7, 9.7.1.1(1) This STANDARD is not met as evidenced by: Based on observation and staff interview, the facility failed to protect the building throughout by an approved, supervised automatic sprinkler system in accordance with the 2012 NFPA 101, Life Safety Code and the 2012 NFPA 13, Standard for the Installation of Sprinkler Systems. The findings were: Observation on 5/25/2017 starting at 11:00 AM in all resident rooms throughout the facility revealed built-in closets that included a bar for hanging clothing, and that the top of the closet enclosure was continuous to the ceiling of the room. Further observation revealed that the closets were not provided with sprinkler protection, and the doors had been removed from each closet. Failure to provide sprinklers as required could result in injury or death during a fire. Interview with the Facility Maintenance Manager at the time of observation indicated he was aware of the requirement, but thought removing the closet doors would meet the requirement. Ref: 2012 NFPA 101 Sections 19.3.5.1 and 9.7.1.1 2010 NFPA 13 Section 1-6.1 SNC Letter 13-55	K 351		