

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 05/02/2017
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11953648	(X3) DATE SURVEY COMPLETED R 04/27/2017
NAME OF PROVIDER OR SUPPLIER BROOKDALE SARASOTA CENTRAL	STREET ADDRESS, CITY, STATE, ZIP CODE 4540 BEE RIDGE ROAD SARASOTA, FL 34233	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments An unannounced revisit survey was conducted on _____ at Brookdale Sarasota Central, an Assisted Living Facility license # 5851 in Sarasota, Florida. This was a follow-up to the biennial survey completed on _____. The following is description of the deficiencies found at the time of the visit. 0152 - Physical Plant - Safe Living Environ/Other - 58A-5.023(3) FAC Based on observation and interview the facility failed to provide a safe living environment free of hazards and ensure all existing structural systems were maintained in good working order. The findings included: On _____ it was noted that duct tape was still on Resident #2's windows. On _____ at 9:49 a.m., Resident #2's granddaughter said she was informed they are not replacing the windows, and at this point there is no choice but to keep the tape on the window, said the facility told her they had hired a contracting company to replace the seals and screens which will hopefully rectify the problem. A tour throughout the facility on _____ found wadded material in the corners of multiple windows. Webs and debris were both inside and outside the windows throughout the facility. Windows in dining _____ on the first and third floor had webbing both inside and outside with some dining tables directly next to these windows. On _____ at 9:15 a.m., the Executive Director (ED) provided a letter from a contractor indicating they had been out to evaluate the buildings window situations and the windows are in bad condition due to the weather. The letter indicated the contractor felt they may be able to correct most of the windows. However, many windows are rusted and may need to be replaced. The letter indicated they were working on a solution package that may be presented to senior management for approval. On _____ at 9:15 a.m., the ED said at this time they do not have an actual contract with the company to have the windows fixed yet and is unsure how long the process will take. Class III		