

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 08/28/2017
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11965291	(X3) DATE SURVEY COMPLETED 08/15/2017
NAME OF PROVIDER OR SUPPLIER BROADVIEW ASSISTED LIVING	STREET ADDRESS, CITY, STATE, ZIP CODE 2110 Fleischmann Road TALLAHASSEE, FL 32308	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments An unannounced complaint survey for allegations contained within CCR#2017007583, CCR#2017008426, & CCR#2017009186 was conducted at Broadview Assisted Living Facility, license #9700, in Tallahassee, FL on . At the time of the survey, deficient practice was identified. 0152 - Physical Plant - Safe Living Environ/Other - 58A-5.023(3) FAC Based on observation and interview, the facility failed to ensure that existing structural systems were maintained in good working order. There was a visible hole in the roof and 2 of 3 vents observed in the dry goods storage area within the kitchen had a visible black colored substance on and around them. (Photographic evidence obtained) The findings were: A tour of the facility was conducted on . at 9:15am. During the tour, the facility was observed to have a hole in the roof. There were 3 vents observed in the dry goods storage area of the kitchen. 2 of the events were observed with a black colored substance on and around them. An interview was conducted with the Administrator on . at 12:25pm. She stated, "We have a hole in the roof due to storm damage and originally the roof was contracted with a local company (Talco roofing company). They were contracted by our corporate office and they kept pushing it back on starting and never came through, so I had to find another company to do the work (contract for new company was signed on)." Class III		