

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 10/02/2018
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11969153	(X3) DATE SURVEY COMPLETED 08/10/2018
NAME OF PROVIDER OR SUPPLIER SAFE FAITH PARADISE ALF LLC	STREET ADDRESS, CITY, STATE, ZIP CODE 541 BRENTFORD CT KISSIMMEE, FL 34758	

SUMMARY STATEMENT OF DEFICIENCIES
(FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)

0000 - Initial Comments

An unannounced monitoring visit related to emergency environmental control plan was conducted at Safe Faith Assisted Living Facility (license 12988), Kissimmee, Florida, on Deficient practice was found at the time of the monitoring visit.

0200 - Emergency Environmental Control - 58A-5.036 FAC

Based on record reviews, observation and interviews the facility failed to ensure the safety of residents by completing all components of the emergency environmental action plan including having a county approved emergency action plan.

Findings include:

On in a record review of the facility emergency action plan, the plan did not document the following items; submittal of a request to the county for approval of an emergency action plan, an approved county building permit for electrical work, documentation the emergency system had been tested, communication on the operation of the system for staff and communication to residents and family members that the system is in place.

On at 3:30 PM, in an interview with the facility administrator, the administrator stated the facility had not submitted an emergency plan for approval to the county. The administrator stated she had not tested the system and considered how to purchase fuel for the system.

On at 3:30 PM, in a continued interview with the facility administrator, the administrator stated she had yet to purchase chillers/coolers for the area to be cooled. The administrator stated she had communicated to residents and family members about the emergency plan. The administrator stated she was unaware of how long the fuel in the generator would last.

On at 3:30 PM, during a tour of the facility, the agency observed the generator sitting in the garage with the directions sitting on top of it. It was observed that the facility did not have fuel for the generator on site.

Class III