

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 10/10/2018
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11910384	(X3) DATE SURVEY COMPLETED 09/25/2018
NAME OF PROVIDER OR SUPPLIER ROYAL CARE A.C.L.F., INC.	STREET ADDRESS, CITY, STATE, ZIP CODE 5081 DUNN ROAD FORT PIERCE, FL 34981	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments An unannounced Generator Monitoring survey was conducted on at Royal Care A.C.L.F., Inc, License #7462. The facility had a deficiency identified at the time of the survey. The above Generator Monitoring survey was conducted in conjunction with the Relicensure revisit survey. Please see separate report for findings. 0200 - Emergency Environmental Control - 58A-5.036 FAC Based on interview it was determined the facility failed to acquire a monoxide alarm. The findings include: During interview conducted with the Administrator, on at approximately 10:20 AM, he was asked where the facility's monoxide detectors are located in the facility. He stated he does not have any and was not aware of need to have any. Class III		