

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 12/03/2018
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11967227	(X3) DATE SURVEY COMPLETED R 11/14/2018
NAME OF PROVIDER OR SUPPLIER J H PUIG INVESTMENTS INC	STREET ADDRESS, CITY, STATE, ZIP CODE 3144 SW 21 STREET MIAMI, FL 33145	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments A Limited Mental Health Expansion Revisit survey was conducted on 11/14/2018. J H Puig Investments, Inc, had deficiencies identified at the time of survey: 0200 - Emergency Environmental Control - 58A-5.036 FAC Based on observation, record review, and interview the facility failed to store a minimum fuel supply (48 hrs.) onsite to operate the emergency generator and maintain the facility's temperature at or below 81 degrees in the event of an emergency. Findings included: On at 12:10 PM, observed ten gallons of gasoline inside a shed. A review of the facility's Consumer Friendly Summary on the Florida Health Finder Database showed that the Emergency Power Plan implementation date was The facility had not requested an extension. Emergency power plan reviewed showed that the facility needed twenty gallons of gas for 48 hours operation of the alternative source. Interview conducted on at 12:15 PM, Staff B confirmed that the facility did not have a minimum fuel supply for 48 hours operation of the alternative source. Class III Uncorrected Deficiency.		

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 12/03/2018
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11967227	(X3) DATE SURVEY COMPLETED R 11/14/2018
NAME OF PROVIDER OR SUPPLIER J H PUIG INVESTMENTS INC	STREET ADDRESS, CITY, STATE, ZIP CODE 3144 SW 21 STREET MIAMI, FL 33145	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments A Limited Mental Health Expansion Revisit survey was conducted on 11/14/2018. J H Puig Investments, Inc, had deficiencies identified at the time of survey: 0200 - Emergency Environmental Control - 58A-5.036 FAC Based on observation, record review, and interview the facility failed to store a minimum fuel supply (48 hrs.) onsite to operate the emergency generator and maintain the facility's temperature at or below 81 degrees in the event of an emergency. Findings included: On at 12:10 PM, observed ten gallons of gasoline inside a shed. A review of the facility's Consumer Friendly Summary on the Florida Health Finder Database showed that the Emergency Power Plan implementation date was The facility had not requested an extension. Emergency power plan reviewed showed that the facility needed twenty gallons of gas for 48 hours operation of the alternative source. Interview conducted on at 12:15 PM, Staff B confirmed that the facility did not have a minimum fuel supply for 48 hours operation of the alternative source. Class III Uncorrected Deficiency.		