

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 06/04/2019
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11911942	(X3) DATE SURVEY COMPLETED 04/02/2019
NAME OF PROVIDER OR SUPPLIER ROYAL PALM RETIREMENT CENTRE	STREET ADDRESS, CITY, STATE, ZIP CODE 2500 AARON STREET PORT CHARLOTTE, FL 33952	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments An unannounced emergency power plan monitoring survey was conducted through at Royal Palm Retirement Centre, an assisted living facility in Port Charlotte, Florida. The following is description of the deficiency. 0200 - Emergency Environmental Control - 58A-5.036 FAC Based on record review and staff interview, the facility failed to ensure compliance in emergency environmental control in the event of the loss of primary electrical power. The findings included: On at 10:42 a.m., the Maintenance Director explained the facility will be getting a new generator. He was unsure when it would be installed. He said the new generator will power the whole building. The current generator is unable to power the whole building as they can't add any more breaker panels. He said the current generator would only be able to cool 457 square which would not be sufficient for 20 square . . . per current census of 96 people. He also said there is only enough fuel onsite to power the generator for 60 hours. On at 12:00 p.m., the Administrator said the residents/legal representatives were notified of the generator. However, he did not have written documentation of this. He also agreed there were currently no policies and procedures for staff to follow to operate the current generator. Class III		