

STATE LICENSING COMPLIANCE REPORT

Report #: #HL370069640C

Date Concluded: April 28, 2026

Name, Address, and County of Facility

Investigated:

Esteem Home Health Services LLC
4024 Idaho Avenue
Crystal, MN 55427
Hennepin County

Facility Type: Assisted Living Facility (ALF)

Evaluator's Name: Erin Johnson-Crosby, RN
Special Investigator

The Minnesota Department of Health conducted a complaint investigation to determine compliance with state laws and rules governing the provision of care under Minnesota Statutes, Chapter 144G. The purpose of this complaint investigation was to review if facility policies and practices comply with applicable laws and rules. No maltreatment under Minnesota Statutes, Chapter 626 was alleged.

To view a copy of the correction orders, if any, please visit:

<https://www.health.state.mn.us/facilities/regulation/directory/provcompselect.html>, or call 651-201-4201 to be provided a copy via mail or email. If you are viewing this report on the MDH website, please see the attached state form.

Minnesota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 37006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/27/2026
NAME OF PROVIDER OR SUPPLIER ESTEEM HOME HEALTH SERVICES			STREET ADDRESS, CITY, STATE, ZIP CODE 4024 IDAHO AVENUE CRYSTAL, MN 55427		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
0 000	Initial Comments *****ATTENTION***** ASSISTED LIVING PROVIDER CORRECTION ORDER In accordance with Minnesota Statutes, section 144G.08 to 144G.95, these correction orders are issued pursuant to a complaint investigation. Determination of whether a violation is corrected requires compliance with all requirements provided at the statute number indicated below. When a Minnesota Statute contains several items, failure to comply with any of the items will be considered lack of compliance. INITIAL COMMENTS: #HL370067869C/#HL370067870C/#HL370067871C/#HL370069640C On March 27, 2026, the Minnesota Department of Health conducted a complaint investigation at the above provider, and the following correction orders are issued. At the time of the complaint investigation, there were three residents receiving services under the provider's Assisted Living license. The following correction order is issued/orders are issued for #HL370067869C/#HL370067870C/#HL370067871C/HL370069640C, tag identification 0780, and 0790.	0 000			
0 780 SS=F	144G.45 Subd. 2 (a) (1) Fire protection and physical environment (a) Each assisted living facility must comply with	0 780			

Minnesota Department of Health

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Minnesota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 37006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/27/2026
NAME OF PROVIDER OR SUPPLIER ESTEEM HOME HEALTH SERVICES		STREET ADDRESS, CITY, STATE, ZIP CODE 4024 IDAHO AVENUE CRYSTAL, MN 55427			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
0 780	Continued From page 1 the State Fire Code in Minnesota Rules, chapter 7511, and: (1) for dwellings or sleeping units, as defined in the State Fire Code: (i) provide smoke alarms in each room used for sleeping purposes; (ii) provide smoke alarms outside each separate sleeping area in the immediate vicinity of bedrooms; (iii) provide smoke alarms on each story within a dwelling unit, including basements, but not including crawl spaces and unoccupied attics; (iv) where more than one smoke alarm is required within an individual dwelling unit or sleeping unit, interconnect all smoke alarms so that actuation of one alarm causes all alarms in the individual dwelling unit or sleeping unit to operate; and (v) ensure the power supply for existing smoke alarms complies with the State Fire Code, except that newly introduced smoke alarms in existing buildings may be battery operated; This MN Requirement is not met as evidenced by: Based on observation and record review, the licensee failed to provide interconnected smoke alarms that complied with fire protection requirements. This had the potential to directly affect all residents, staff, and visitors. This practice resulted in a level two violation (a violation that did not harm a resident's health or safety but had the potential to have harmed a resident's health or safety) and was issued at a	0 780			

Minnesota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 37006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/27/2026
NAME OF PROVIDER OR SUPPLIER ESTEEM HOME HEALTH SERVICES			STREET ADDRESS, CITY, STATE, ZIP CODE 4024 IDAHO AVENUE CRYSTAL, MN 55427		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
0 780	Continued From page 2 widespread scope (when problems are pervasive or represent a systemic failure that has affected or has the potential to affect a large portion or all of the residents). The findings include: A comprehensive survey conducted from July 8, through July 11, 2024, indicated a licensing order was written because the licensee did not have interconnected smoke alarms. The licensee's application for assisted living licensure signed June 6, 2025, by licensed assisted living director (LALD)-A indicated the licensee read and understood Minnesota statute 144G.45. On March 27, 2026, at 11:00 a.m., an onsite visit was conducted. The investigator observed the physical environment of the facility. West Metro Fire-Rescue Complete Inspection Report dated April 10, 2026, indicated there was a violation of the fire code when smoke alarms and carbon monoxide detectors were not interconnected throughout the facility. No further information was provided TIME PERIOD FOR CORRECTION: Seven (7) days	0 780	Statement of Deficiencies" column. This column also includes the findings which are in violation of the state requirement after the statement, "This Minnesota requirement is not met as evidenced by." Following the evaluators' findings is the Time Period for Correction. PLEASE DISREGARD THE HEADING OF THE FOURTH COLUMN WHICH STATES,"PROVIDER'S PLAN OF CORRECTION." THIS APPLIES TO FEDERAL DEFICIENCIES ONLY. THIS WILL APPEAR ON EACH PAGE. THERE IS NO REQUIREMENT TO SUBMIT A PLAN OF CORRECTION FOR VIOLATIONS OF MINNESOTA STATE STATUTES. THE LETTER IN THE LEFT COLUMN IS USED FOR TRACKING PURPOSES AND REFLECTS THE SCOPE AND LEVEL ISSUED PURSUANT TO 144G.31 SUBDIVISION 1-3.		
0 790 SS=F	144G.45 Subd. 2 (a) (2-3) Fire protection and physical environment (2) install and maintain portable fire extinguishers in accordance with the State Fire Code; (3) install portable fire extinguishers having a	0 790			

Minnesota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 37006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/27/2026
NAME OF PROVIDER OR SUPPLIER ESTEEM HOME HEALTH SERVICES			STREET ADDRESS, CITY, STATE, ZIP CODE 4024 IDAHO AVENUE CRYSTAL, MN 55427		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
0 790	Continued From page 3 minimum 2-A:10-B:C rating within Group R-3 occupancies, as defined by the State Fire Code, located so that the travel distance to the nearest fire extinguisher does not exceed 75 feet, and maintained in accordance with the State Fire Code; and This MN Requirement is not met as evidenced by: Based on observation and record review, the licensee failed to maintain portable fire extinguishers in accordance with the State Fire Code as required by MN Statute 144G.45 Subd(a)(2). This had the potential to directly affect all residents and staff. This practice resulted in a level two violation (a violation that did not harm a resident's health or safety but had the potential to have harmed a resident's health or safety, but was not likely to cause serious injury, impairment, or death), and is issued at a widespread scope (when problems are pervasive or represent a systemic failure that has affected or has the potential to affect a large portion or all of the residents). The findings include: The licensee's application for assisted living licensure signed June 6, 2025, by licensed assisted living director (LALD)-A indicated the licensee read and understood Minnesota statute 144G.45. On March 27, 2026, at 11:00 a.m., an onsite visit was conducted. The investigator observed the physical environment of the facility.	0 790			

Minnesota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 37006	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____		(X3) DATE SURVEY COMPLETED C 03/27/2026
NAME OF PROVIDER OR SUPPLIER ESTEEM HOME HEALTH SERVICES			STREET ADDRESS, CITY, STATE, ZIP CODE 4024 IDAHO AVENUE CRYSTAL, MN 55427		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
0 790	Continued From page 4 West Metro Fire-Rescue Complete Inspection Report dated April 10, 2026, indicated there was a violation of the fire code when the extinguisher was expired. No further information was provided. TIME PERIOD FOR CORRECTION: Seven (7) days	0 790			