

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL006007	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 07/05/2017
NAME OF PROVIDER OR SUPPLIER CRANBERRY HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 6255 US HIGHWAY 19 EAST NEWLAND, NC 28657		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Construction Survey by Ed Miller on July 5, 2017. Deficiencies were cited that will require a new plan of correction.	{C 000}		
{C 164}	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1-Based on observation, this facility has not maintained the wood finishes of the interior doors in good repair. Findings on 05/11/2017: a. The entry doors for Rooms 101 and 103 have damaged due to wheelchair interaction. Interview with Staff revealed that due to the number of doors that had been damaged from wheelchairs, they have requested that all of the doors be replaced. They have not received approval from their corporate office for the repairs. Findings on 07/5/2017: Replacement doors are scheduled to be ordered with delivery and installation taking 7 to 13 weeks.	{C 164}		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE