

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL018032	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED R 08/23/2017
NAME OF PROVIDER OR SUPPLIER SPRINGS OF CATAWBA			STREET ADDRESS, CITY, STATE, ZIP CODE 2010 29TH AVENUE DRIVE NE HICKORY, NC 28601		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey by Suzanna Fay conducted on August 23, 2017. There is one deficiency from the Biennial Follow Up Construction Survey that remains to be corrected.	{C 000}			
{C 101}	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost; This Rule is not met as evidenced by: 1-Based on observation, this facility has failed to prevent dead-end travel distances of greater than twenty feet from being created due to interior alterations that do not comply with the NC Building Code. Findings on 08/23/2017: The existing hallway door leading into the	{C 101}	Fire rated doors were installed on August 28, 2017. Facility was inspected for other dead end areas to ensure they are within NC Building Code compliance.		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE


(X6) DATE

STATE FORM

6899

YRSP22

If continuation sheet 1 of 2



Executive Director 9-21-2017

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL018032	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED R 08/23/2017
NAME OF PROVIDER OR SUPPLIER SPRINGS OF CATAWBA			STREET ADDRESS, CITY, STATE, ZIP CODE 2010 29TH AVENUE DRIVE NE HICKORY, NC 28601		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
{C 101}	Continued From page 1 Sunroom that is located in the "DOGWOOD" community has been removed, creating a dead-end travel distance condition that is located adjacent to Rooms 107 & 108. At the time of this survey, the prep work has been completed and the door is on order. The door required a five week lead time and will be shipped the week of September 4, 2017.	{C 101}			