

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034097	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 12/18/2018
NAME OF PROVIDER OR SUPPLIER MAGNOLIA CREEK ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 2560 WILLARD ROAD WINSTON SALEM, NC 27107		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of Biennial Follow Up Construction Survey by Dennis Harrell on 12-18-2018. A deficiency was not corrected. Further action is required.	{C 000}	Responses to cited deficiencies do not constitute an admission or agreement by the facility of truth of the facts alleged or conclusions set forth in this Statement of Deficiencies or Corrective Action report. The Plan of Corrections is prepared as a matter of compliance with state law.	
{C 166}	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the Building floor is not free of all obstructions and hazards. Finding on 12-18-2018: a. Bathroom Between Bedrooms 110 & 112 - because of the May 5, 2018 fire, which involved the bathrooms exhaust fan, still has a melted hole through the floor covering.	{C 166}	aHousekeeping - Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities The bathroom floor between bedrooms 110 & 112 is scheduled to be completely installed by the facility's maintenance technician.	01/28/19

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

[Signature]

TITLE *Executive Director*

(X6) DATE

1/3/19