

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 05/23/2019
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey by Suzanna Fay conducted on May 23, 2019. There are deficiencies cited in the Biennial Construction Survey that remain to be corrected.	{C 000}		
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 2. Based on observation the facility did not maintain electrical emergency/safety lighting equipment in safe operating condition. Occupants of the facility could be effected if the signs indicating exit paths could not be seen in the event of an emergency evacuation. Findings on May 23, 2019: a. Observation at the time of survey revealed the facility does not have battery backed up emergency exit lighting. Staff indicated the facility's exit signs/lights (with one exception) receive emergency power from the building generator. At the time of this survey, the generator is not capable of supplying emergency power to the exit signs. The new generator must meet the requirements for an emergency	{C 189}		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL078083	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 05/23/2019
NAME OF PROVIDER OR SUPPLIER RED SPRINGS ASSISTED LIVING		STREET ADDRESS, CITY, STATE, ZIP CODE 1301 E. FOURTH AVENUE RED SPRINGS, NC 28377		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 189}	Continued From page 1 generator or if it only meets the requirements for standby generator, supply battery backed up exit lighting. Note: Review of DHSR Construction Records indicated that there is no evidence the generator meets the requirements for an emergency generator.	{C 189}		