



Division of Health Service Regulation

PRINTED: 09/25/2019
FORM APPROVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023047	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/19/2019
NAME OF PROVIDER OR SUPPLIER OPENVIEW RETIREMENT HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 112 PONY BARN ROAD LAWNDALE, NC 28090		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of a Construction Section Biennial Survey by Ed Miller, conducted on September 19, 2019. Records indicate that this facility was license is 08/01/1973. This facility is currently licensed for 24 residents. Based on this information, we are requiring that this facility to meet the 1971 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm, applicable portions of the 2005 Regulations for Adult Care Homes, and the 1967 North Carolina State Building Code Section 407.1, Group D-2 Institutional Occupancy. Deficiencies were cited that require a Plan of Correction.	C 000		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the building walls are not kept clean and in good repair. Findings on September 19, 2019: a. Main Corridors - the wall base has been removed while the walls were painted. 2. Based on Observation, and interview with	C 164	(a) New Base Board will be installed after new flooring 10/31/19 	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Bernice R Hosch 

TITLE

Administrator

(X6) DATE

10-10-19

STATE FORM

6899

Q7H221

If continuation sheet 1 of 6

Division of Health Service Regulation

PRINTED: 09/25/2019
FORM APPROVED

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023047	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____		(X3) DATE SURVEY COMPLETED 09/19/2019
NAME OF PROVIDER OR SUPPLIER OPENVIEW RETIREMENT HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 112 PONY BARN ROAD LAWNDALE, NC 28090		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
C 164	Continued From page 1 Manager, the facility failed to keep plumbing system devices clean and in good repair. Findings on September 19, 2019: a. Half Bath near Bedroom 2 - the connection of the commode to the floor is loose.	C 164	(a) Commode Properly secured to floor	9-21-19	
C 183	Fire Extinguishers SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0308 FIRE EXTINGUISHERS (a) At least one five pound or larger (net charge) A-B-C type fire extinguisher is required for each 2,500 square feet of floor area or fraction thereof. (b) One five pound or larger (net charge) A-B-C or CO/2 type is required in the kitchen and, where applicable, in the maintenance shop. This Rule is not met as evidenced by: 1. Based on observation, the facility failed to properly maintain the fire extinguishers and associated equipment. This could hamper staff's ability to extinguish a small fire and permit it to grow larger. Findings on September 19, 2019: a. Kitchen - the documentation of the "K" portable fire extinguisher's monthly inspections stopped in July 2019.	C 183			
C 185	Fire Safety-Rehearsals on Each Shift SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (b) There shall be rehearsals of the fire plan quarterly on each shift in accordance with the requirement of the local Fire Prevention Code Enforcement Official. (c) Records of rehearsals shall be maintained and copies furnished to the county department of	C 185		(a) All portable fire extinguisher were annually inspected and will be <i>BD</i> monthly inspected 10-1-19	

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023047	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/19/2019
NAME OF PROVIDER OR SUPPLIER OPENVIEW RETIREMENT HOME		STREET ADDRESS, CITY, STATE, ZIP CODE 112 PONY BARN ROAD LAWNDALE, NC 28090		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 185	Continued From page 2 social services annually. The records shall include the date and time of the rehearsals, the shift, staff members present, and a short description of what the rehearsal involved. (f) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Record review and interview with Manager, fire safety rehearsals are not being performed regularly with at least one per shift for each quarter. Findings on September 19, 2019: a. In the 1st quarter for the last 12 months, no rehearsal occurred during 1st shift. b. In the 3rd quarter for the last 12 months, no rehearsal occurred during 1st shift. c. In the 4th quarter for the last 12 months, no rehearsal occurred during 3rd shift.	C 185	Staff In-service on Fire Drill rehearsals Fire Drill Manuel updated	10-1-19
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the Fire Alarm system was not maintained in a safe and operating condition. This would affect all by not providing early detection and activating the fire alarm	C 189		

Division of Health Service Regulation
STATE FORM

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL023047	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 09/19/2019
---	---	--	--

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

OPENVIEW RETIREMENT HOME

**112 PONY BARN ROAD
LAWNDALE, NC 28090**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 4 latch into its frame when closed. 5. Based on observation, the Facility failed to maintain the electrical system in a safe and operating condition. Findings on September 19, 2019: a. AA Office - the light fixture is missing its globe. b. AA Office -there is a power cable running from this room, under the door, powering a device in the Living Room. 6. Based on observations, the Facility's method of storing material in the facility was not maintained in a safe and proper operating condition for a non-sprinklered building. High storage could hinder firefighter availability to effectively provide manual hose streams of water to a fire. Findings on September 19, 2019: a. Bedroom 3 Closet - materials are being stored within 24-inches of the ceiling. b. Bedroom 2 Closet - materials are being stored within 24-inches of the ceiling. c. Living Room Storage Closet - materials are being stored within 24-inches of the ceiling. d. Bedroom 10 Window Side Closet - materials are being stored within 24-inches of the ceiling.	C 189	(a) Door strike adjusted-Door properly latching (a) New light fixture installed (b) Power Cable immediately removed (a-b-c-d) Staff removed all materials stored within 24inch of ceiling	10-1-19 10-2-19 9-19-19 10-2-19
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in	C 199		

If continuation sheet 6 of 6