

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL080027	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 12/04/2019
NAME OF PROVIDER OR SUPPLIER ALPHA CONCORD PLANTATION		STREET ADDRESS, CITY, STATE, ZIP CODE 2809 OLD CONCORD ROAD SALISBURY, NC 28146		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Construction Section Biennial Survey by Dennis Harrell on 12-4-2019. Records indicate this facility was operating as a Rest Home in March of 1961. The facility is currently licensed for 29 beds. Based on this information, the facility is required to meet the 1971 Minimum and Desired Standards and Regulations for Homes for the Aged and Infirm and the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds.	C 000		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on observation, the exit door near room 116 was stuck and very hard to open. Exits that could stick or be difficult to open could delay or prevent an evacuation in an emergency. Note; This deficiency was corrected during the survey. 2. Based on observation, the building was not maintained in a safe manner by not properly handling portable medical oxygen cylinders. This could affect all residents, staff and visitors if cylinders fall, breaking their valves, propelling the cylinder and turning it into a dangerous projectile. Findings on 12-4-2019;	C 166		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL080027	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 12/04/2019
NAME OF PROVIDER OR SUPPLIER ALPHA CONCORD PLANTATION		STREET ADDRESS, CITY, STATE, ZIP CODE 2809 OLD CONCORD ROAD SALISBURY, NC 28146		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 1 a. Two portable medical oxygen cylinders were stored in no rack or container in room 131. b. Two portable medical oxygen cylinders, one small and one large, were stored in no rack or container in the oxygen storage room.	C 166		