

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL077012	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/25/2022
NAME OF PROVIDER OR SUPPLIER HERMITAGE RETIREMENT CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 139 MALLARD LANE ROCKINGHAM, NC 28379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{D 000}	Initial Comments The Adult Care Licensure Section conducted a follow up survey on February 23 - 25, 2022.	{D 000}		
{D 113}	10A NCAC 13F .0311(d) Other Requirements 10A NCAC 13F .0311 Other Requirements (d) The hot water system shall be of such size to provide an adequate supply of hot water to the kitchen, bathrooms, laundry, housekeeping closets and soil utility room. The hot water temperature at all fixtures used by residents shall be maintained at a minimum of 100 degrees F (38 degrees C) and shall not exceed 116 degrees F (46.7 degrees C). This rule applies to new and existing facilities. This Rule is not met as evidenced by: TYPE B VIOLATION Based on observations, interviews, and record reviews the facility failed to ensure that hot water temperatures were maintained at 100° to 116° degrees Fahrenheit (F) for 4 of 23 fixtures in the common residents' bathroom and a resident's rooms (#67) on the Moore and Roosevelt halls located on the Special Care Unit (SCU) with temperatures of 118.2° degrees F to 133.8° degrees F. The findings are: Observation of resident room #67's bathroom on the SCU Roosevelt hall on 02/23/22 at 9:58am revealed the hot water temperature at the sink was 118.2°F. Based on observations and interviews, it was	{D 113}		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL077012	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/25/2022
NAME OF PROVIDER OR SUPPLIER HERMITAGE RETIREMENT CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 139 MALLARD LANE ROCKINGHAM, NC 28379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{D 113}	Continued From page 1 determined the resident residing in room #67 was not interviewable. Observation of the common residents' bathroom on the SCU Moore hall on 02/23/22 at 10:47am revealed: -The hot water temperature at the sink was 133.8°F. -The hot water temperature at the shower was 127.4°F. -There was visible steam coming from the running hot water. Interview with a personal care aide (PCA) on 02/23/22 at 11:00am revealed: -She assisted 2 residents on the SCU Moore hall with showers. -She had not turned the hot water knob on high. -She checked the water temperature with her hand to determine if the water was too hot. -Residents had not complained to her the water temperature was too hot during their baths. -She added cold water to the hot water to cool off the hot water. -She did not know the required water temperatures. -She had not observed any steam coming from the water. -She did not report the water being too hot to the Maintenance Director. Interview with a second PCA on 02/23/22 at 11:06am revealed: -She had adjusted the hot water temperature by adding cold water. -She tested the water temperature with her hand and would have the resident to test the water to see if it was too hot. -She had not observed any steam coming from the water.	{D 113}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL077012	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/25/2022
NAME OF PROVIDER OR SUPPLIER HERMITAGE RETIREMENT CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 139 MALLARD LANE ROCKINGHAM, NC 28379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{D 113}	Continued From page 2 -Many of the resident could not respond to say if the water was too hot and that was why she always tested the water temperature first. -She was not trained on testing hot water temperatures. Interview with a medication aide (MA) on 02/23/22 at 10:58m revealed: -The PCAs had not reported the water temperature was too hot in the SCU room #67 and the common bathroom on the SCU Moore hall. -Residents had not complained to her of the water temperature being too hot. -If the water temperature was too hot, she reported it to the Maintenance Director by completing the maintenance service log. Interview with the Special Care Coordinator (SCC) on 02/23/22 at 10:51am revealed: -Staff had not reported the hot water was too hot in resident room #67 and the common geriatric bathroom on the SCU Moore hall. -Staff were to report hot water issues to the Maintenance Director. -She did not know the hot water requirements. -The Maintenance Director was responsible for maintaining the water temperatures. -She would place a "Do Not Use" posting on common residents' geriatric bathroom until the hot was adjusted. -She would notify the Maintenance Director of the hot water being too hot in resident room #67 and the common bathroom on the SCU Moore hall. Review of the February 2022 facility's weekly maintenance log dated 02/08/22 revealed: -The weekly maintenance log hot water temperature check for the residents' common bath on the SCU Moore hall was 109.1°F.	{D 113}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL077012	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/25/2022
NAME OF PROVIDER OR SUPPLIER HERMITAGE RETIREMENT CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 139 MALLARD LANE ROCKINGHAM, NC 28379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{D 113}	Continued From page 3 -The weekly maintenance log did not list resident room #67 as recorded for a hot water temperature check. Interview with the Maintenance Director on 02/23/22 at 10:39am revealed: -He completed random hot water temperature checks weekly. -All residents' common bathrooms were checked weekly. -He last completed hot water temperature checks was on 02/08/22. -New hot water tanks were recently installed separately on the SCU Moore and Roosevelt halls. -The hot water temperatures were within range of 100°F and 116°F when checked. -He was responsible for completing weekly hot water checks and regulating the temperature. Observation of water thermometers being calibrated on 02/24/22 at 8:59am revealed: -The Maintenance Director and Surveyor's water thermometers were placed in a cup of ice water. -Both water thermometers temperatures were calibrated at 32°F. Observations of re-check of water temperatures with the Maintenance Director on 02/24/22 revealed: -At 8:58am, "Do not use/Caution Hot Water" sign had been placed on the door of the residents' common bathroom on the Moore hall. -At 9:10am, the hot water temperature at the sink in the residents' common bathroom on the SCU Moore hall was at 122.6°F completed by the Maintenance Director and at 122.1°F completed by the Surveyor. -At 9:11am, the hot water temperature at the shower in the residents' common bathroom on	{D 113}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL077012	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/25/2022
NAME OF PROVIDER OR SUPPLIER HERMITAGE RETIREMENT CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 139 MALLARD LANE ROCKINGHAM, NC 28379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{D 113}	Continued From page 4 the SCU hall was at 117.8°F completed by the Maintenance Director and at 118.3°F completed by the Surveyor. -At 9:15am, the hot water temperature at the sink in resident room #67 was at 104.4°F completed by the Maintenance Director and at 106.6°F completed by the Surveyor. Observations of re-check of water temperatures with the Maintenance Director on 02/25/22 revealed: -At 10:09am, a "Do not use/Caution Hot Water" sign was still placed on the door residents' common bathroom on the SCU Moore hall. -At 10:10am, the hot water temperature at the sink in the residents' common bathroom on the SCU Moore hall was at 109.1°F completed by the Maintenance Director and at 109.4°F completed by the Surveyor. -At 10:11am, the hot water temperature at the shower in the residents' common bathroom on the SCU Moore hall was at 103.0°F completed by the Maintenance and was at 102°F completed at by the Surveyor. Interview with the Maintenance Director on 02/25/22 at 10:05am revealed: -He had left the "Do not use/Caution Hot Water" signs on the residents' common bathroom door on the Moore hall until the hot water temperature for the shower and sink had been rechecked with the Surveyor. -He knew the required hot water temperature range was 100°F to 116°F. -He adjusted the temperatures on the hot water heater and had released some of the hot water on 02/23/22. Interview with the Assistant Administrator on 02/23/22 at 11:34am revealed:	{D 113}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL077012	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/25/2022
NAME OF PROVIDER OR SUPPLIER HERMITAGE RETIREMENT CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 139 MALLARD LANE ROCKINGHAM, NC 28379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{D 113}	Continued From page 5 -Residents had not complained to her about the water temperature being too hot. -She was not responsible for completing the hot water temperatures. -The Maintenance Director was responsible for completing the hot water temperatures. -The Maintenance Director was the only staff to monitor the hot water temperatures. -The Maintenance Director completed hot water temperatures weekly and log the results. The facility failed to ensure hot water temperatures were maintained between 100° to 116° degrees Fahrenheit (F) which resulted in hot water temperatures of 118.2°degrees F to 133.8° degrees F at 3 of 23 fixtures accessible by residents residing on the SCU (common residents' bathroom on the Moore hall and one resident's room #67). A water temperature of 118.4 degrees F could result in a first degree burn in 15 minutes and a second degree burn in 20 minutes. A water temperature of 127.4 degrees F could result in a first degree burn in 30 seconds and a second degree burn in 60 seconds. A third degree burn can occur in 10 seconds when skin is placed in contact with water measuring 130 degrees F. This failure of the facility was detrimental to the safety, health and welfare of the residents and constitutes a Type B Violation. The facility provided a plan of protection in accordance with G.S. 131D-34 on 02/23/22 for this violation. CORRECTION DATE FOR THE TYPE B VIOLATION SHALL NOT EXCEED APRIL 9, 2022.	{D 113}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL077012	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/25/2022
NAME OF PROVIDER OR SUPPLIER HERMITAGE RETIREMENT CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 139 MALLARD LANE ROCKINGHAM, NC 28379		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{D912}	Continued From page 6	{D912}		
{D912}	G.S. 131D-21(2) Declaration of Residents' Rights G.S. 131D-21 Declaration of Residents' Rights Every resident shall have the following rights: 2. To receive care and services which are adequate, appropriate, and in compliance with relevant federal and state laws and rules and regulations. This Rule is not met as evidenced by: Based on observations, interviews and record reviews, the facility failed to ensure residents received care and services which were adequate, appropriate and in compliance with relevant federal and state laws and rules and regulations related to other requirements. The findings are: Based on observations, interviews, and record reviews the facility failed to ensure that hot water temperatures were maintained at 100° to 116° degrees Fahrenheit (F) for 4 of 23 fixtures in the common residents' bathroom and a resident's rooms (#67) on the Moore and Roosevelt halls located on the Special Care Unit (SCU) with temperatures of 118.2° degrees F to 133.8° degrees F. [Refer to Tag 113 10A NCAC 13F .0311(d) Other Requirements (Type B Violation)].	{D912}		