

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL034028	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 11/07/2023
NAME OF PROVIDER OR SUPPLIER SOUTHFORK		STREET ADDRESS, CITY, STATE, ZIP CODE 1345 JONESTOWN ROAD WINSTON SALEM, NC 27103		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Construction Section Biennial Follow Up Survey by Tod Hancock conducted on November 7, 2023. Deficiencies were cited that require a Plan of Correction.	{C 000}	Responses to the cited deficiencies do not constitute an admission by the facility of the truth of the facts alleged or conclusions set forth in the statement of deficiencies or corrective action report. The plan of correction is prepared solely as a matter of compliance with state laws.	
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 4. Based on observation the facility's fire safety equipment is not maintained in operating condition. Failure to maintain fire safety equipment in operating condition could affect occupants of the facility if the equipment could not operate properly to suppress a fire. Findings on November 7, 2023: a. The deflector on the sprinkler head outside of Room D125 is bent which may deter the ability of the head to suppress a fire.	{C 189}	Section .0300- Physical Plant 10A NCAC 13F .0311 Other Requirements (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. Community will ensure that deflector on the sprinkler head outside of Room D125 is replaced with a new deflector. Community has ordered the new sprinkler head and is awaiting the arrival of the sprinkler head. Sprinkler company has given us a TBD date of install. Estimated time from them is May, 24th 2024. Community will take a picture of installed sprinkler head and send to construction survey when completed.	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE