

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041086	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 02/14/2024
--	--	--	---

NAME OF PROVIDER OR SUPPLIER HARMONY AT GREENSBORO	STREET ADDRESS, CITY, STATE, ZIP CODE 3420 WHITEHURST ROAD GREENSBORO, NC 27410
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey by Tod Hancock, conducted on February 14, 2024. Deficiencies were cited that require a new Plan of Correction.	{C 000}	The following is a Plan of Correction (POC) for Harmony at Greensboro Assisted Living. This POC is in regard to the Follow - Up Survey, completed 2/14/2024. This POC is not to be constructed as an admission of or an agreement with the findings and conclusions in the State of Deficiencies, or any related sanction or fine. Rather, it is submitted as confirmation of our ongoing efforts to comply with statutory and regulatory requirements. In this document, we have outlined a specific response to identified issues. We have not provided a detailed response to each allegation, or identified mitigating factors.	
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 3. Based on observation, the building was not maintained in a safe and operating condition, because the door(s), protecting the opening in the Elevator Lobbies Enclosure and smoke barriers do not close completely and latch to restrict fire and smoke. This could affect all residents, staff, and visitors by not containing the smoke of the fire in the compartment of origin. Findings on February 14, 2024: d. 2nd FL, Elevator Lobby - the pair of cross-corridor doors, are not labeled.	{C 189}	Physical Plant 10A NCAC 13F .0311 Other Requirements The community has a vendor that will be completing a field labelling of the fire doors. This will be completed by 7/31/2024.	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

6899

19MV23

If continuation sheet 1 of 1