

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL092174	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/28/2025
NAME OF PROVIDER OR SUPPLIER LYNN'S HOME AT RIVERSIDE		STREET ADDRESS, CITY, STATE, ZIP CODE 5614 APALACHICULA CIRCLE RALEIGH, NC 27616		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Kelly Myers DHSR Construction Section conducted a Biennial Survey on May 28, 2025, from 10:50 AM to 12:15 PM at the above referenced facility. DHSR records indicate the home was first licensed on April 26, 2012 as a Family Care Home for six (6) ambulatory Residents (Who are able to respond and evacuate without any physical or verbal assistance during a fire or other emergency). Based on this information we are requiring the home to maintain compliance with the following: the 2005 Rules 10A NCAC 13G for Family Care Homes, the 2009 North Carolina State Building. - Section 421.2 Residential Care Homes 1.) At the time of the our visit, we cited deficiencies that require an acceptable plan of correction. All deficiencies listed were discussed with onsite staff during exit interview 2.) Take actions to correct all listed deficiencies, once completed provide verification in the form of photos, receipts, invoices, etc. for all work performed. The cited deficiencies are as follows:	C 000		
C 146	Outside Entrances/Exits-Ramp(s) SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (c) At least one principal outside entrance/exit for the residents' use shall be at grade level or accessible by ramp with a one inch rise for each 12 inches of length of the ramp. For the purposes of this Rule, a principal outside entrance/exit is one that is most often used by	C 146		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL092174	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/28/2025
NAME OF PROVIDER OR SUPPLIER LYNN'S HOME AT RIVERSIDE		STREET ADDRESS, CITY, STATE, ZIP CODE 5614 APALACHICULA CIRCLE RALEIGH, NC 27616		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 146	Continued From page 1 residents for vehicular access. If the home has any resident that must have physical assistance with evacuation, the home shall have two outside entrances/exits at grade level or accessible by a ramp. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that the back ramp did not have a smooth transition from the ramp to grade level. This is not compliant with the rule. Take the necessary steps provide and maintain a smooth transition that does not have a lip.	C 146		
C 170	Fire Safety-Any Other City Ordinances SECTION .0300 - THE BUILDING 10A NCAC 13G .0316 FIRE SAFETY AND DISASTER PLAN (c) Any fire safety requirements required by city ordinances or county building inspectors shall be met. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that there was not 18 inches of clearance from the sprinkler head in the left hallway closets. This is not compliant with the rule. Take the necessary steps to remove any items that are closer than 18 inches to the sprinkler head.	C 170		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical,	C 174		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL092174	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/28/2025
NAME OF PROVIDER OR SUPPLIER LYNN'S HOME AT RIVERSIDE		STREET ADDRESS, CITY, STATE, ZIP CODE 5614 APALACHICULA CIRCLE RALEIGH, NC 27616		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 2 mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1 At the time of the survey it was observed that the left hall bath had wall damage behind the vanity faucet. This this not compliant with the rule. Take the necessary steps to repair the wall.	C 174		
C 183	Outside Premises-Clean, Safe SECTION .0300 - THE BUILDING 10A NCAC 13G .0318 OUTSIDE PREMISES (a) The outside grounds of new and existing family care homes shall be maintained in a clean and safe condition. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that the back patio had a drop off to grade level. This is not compliant with the rule. Take the necessary steps to bring the grade level to the top of the patio.	C 183		