

North Dakota Health and Human Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8021	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/18/2025
---	--	--	--

NAME OF PROVIDER OR SUPPLIER ROCK OF AGES HOME, INC	STREET ADDRESS, CITY, STATE, ZIP CODE 1315 4TH ST NE JAMESTOWN, ND 58401
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 33 Existing Residential Board and Care Occupancies (Large), in compliance with NDAC 33-03-24.2. The facility was located in a two-story structure of Type II (000) construction protected with a wet automatic fire sprinkler system designed to meet the requirements of NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height. The attic space was protected with a heat detection system. Closets under 24 sq. ft. and bathrooms under 55 sq. ft. were not protected by the automatic sprinkler system. Resident evaluation determined a Slow level of evacuation difficulty. The E-Score was 2.0. Note: Observation and records review determined the facility to be in compliance with the minimum requirements of NFPA 101, Life Safety Code.	K 000		

Health Repsonse and Licensure LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
--	-------	-----------