

North Dakota Department of Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8038	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 03/29/2021
NAME OF PROVIDER OR SUPPLIER ROSEADELE			STREET ADDRESS, CITY, STATE, ZIP CODE 1505 3RD ST SE JAMESTOWN, ND 58401		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 33 Existing Residential Board and Care Occupancies (Large), in compliance with NDAC 33-03-24.2. The facility was located in a one-story structure of Type II (000) construction protected throughout with a wet automatic fire sprinkler system designed to meet the requirements of NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height. Resident evaluation determined a Slow level of evacuation difficulty. The E-Score was 1.16. Note: Review of records and observations made during the survey determined the facility was in compliance with the 2012 edition of NFPA 101, Life Safety Code.	K 000			

Health Resources Section

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE