

North Dakota Health and Human Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 8096	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - BASIC CARE MAIN BUILDING B. WING _____		(X3) DATE SURVEY COMPLETED 11/17/2025
NAME OF PROVIDER OR SUPPLIER OSNABROCK COMMUNITY LIVING CENTER, II			STREET ADDRESS, CITY, STATE, ZIP CODE 326 RAINBOW RD OSNABROCK, ND 58269		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 33 Existing Residential Board and Care Occupancies (Large), in compliance with NDAC 33-03-24.2. The facility was located in a one-story building of Type V (000) construction with no basement. The building was equipped with a wet/dry automatic sprinkler system designed to meet the requirements of NFPA 13R, Standard for the Installation of Sprinkler Systems in Residential Occupancies up to and Including Four Stories in Height. The attic space was protected with a heat detection system. Resident evaluation determined a Prompt level of evacuation difficulty. The E-Score was 0.733. Note: Observation and records review determined the facility to be in compliance with the minimum requirements of NFPA 101, Life Safety Code.	K 000			

Health Repsonse and Licensure

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE