



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 12/30/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Application and Use

603.5.2 Application and use. Relocatable power taps and current taps shall be directly connected to a permanently installed receptacle.

Exceptions:

1. Where approved for use in a Group A occupancy or in a meeting room in a Group B occupancy, not more than five relocatable power taps shall be permitted to be connected together or connected to an extension cord for temporary use to supply power to electronic equipment.

2. Current taps and relocatable power taps shall not be required to connect directly to a permanently installed receptacle outlet where used for 90 days or less for the purpose of testing the performance of such devices.

(IFC 603.5.2, 2021)

Corrected

2 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..

(IFC 603.6 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 12/30/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

3 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space.

(IFC 701.6 2021)

Corrected

4 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection the following paperwork was not provided:

- Corrected 1. Annual report
- 2. 5-Year internal pipe Testing (NFPA 25 14.2.1.1)
- 3. 3-Year Dry System Full flow trip test (NFPA 25 13.1.1.2)
- Corrected 4. Annual Trip Test (NFPA 25 13.1.1.2)
- 5. Annual forward flow test (NFPA 25 13.7.2)
- 6. 5-Year FDC Hydro testing (NFPA 25 13.8.5)
- 7. Quarterly inspections

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

5 Extinguishing System Service

Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion.

(IFC 904.13.5.2 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Hilltop Manor Boarding Home

Provider Number 001278

Address 1732 16TH ,

Approval Status Disapproved

City, State, Zip Seattle, WA 98122

Facility Type Residential Care

On 12/30/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

6 Portable Fire Extinguishers - General Requirements

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.

Exceptions:

1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.

2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:

2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.

2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.

2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.

2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.

2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.

3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.

(IFC 906.2 2021)

Corrected

7 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 12/30/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

8 Power Test

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.

(IFC 1031.10.2 2021)

Corrected

9 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.

(IFC 1203.4 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection the following paperwork was not provided:

1. Annual service report
- Corrected 2. Log of weekly inspections
3. Monthly 30-minute full load test

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

10 Security

Compressed gas containers, cylinders, tanks and systems shall be secured against accidental dislodgement and against access by unauthorized personnel in accordance with Sections 5303.5.1 through 5303.5.3.

(IFC 5303.5 2021)

Corrected

11 NFPA 80 Fire /Smoke Dampers Inspection and Testing

19.4 Periodic Inspection and Testing.

19.4.1 Each damper shall be tested and inspected 1 year after installation.

19.4.1.1 The test and inspection frequency shall then be every 4 years, except in hospitals, where the frequency shall be every 6 years.

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 12/30/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 01/29/2025


Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

Lauren Duran, Administrator
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2803 156 AVE SE
Bellevue WA 98007
(509) 406-7209


Signature

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Hilltop Manor Boarding Home

Provider Number 001278

Address 1732 16TH ,

Approval Status Disapproved

City, State, Zip Seattle, WA 98122

Facility Type Residential Care

On 09/25/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Application and Use

603.5.2 Application and use. Relocatable power taps and current taps shall be directly connected to a permanently installed receptacle.

Exceptions:

1. Where approved for use in a Group A occupancy or in a meeting room in a Group B occupancy, not more than five relocatable power taps shall be permitted to be connected together or connected to an extension cord for temporary use to supply power to electronic equipment.

2. Current taps and relocatable power taps shall not be required to connect directly to a permanently installed receptacle outlet where used for 90 days or less for the purpose of testing the performance of such devices.

(IFC 603.5.2, 2021)

Corrected

2 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..

(IFC 603.6 2021)

Corrected

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Hilltop Manor Boarding Home

Provider Number 001278

Address 1732 16TH ,

Approval Status Disapproved

City, State, Zip Seattle, WA 98122

Facility Type Residential Care

On 09/25/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

3 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space.

(IFC 701.6 2021)

Corrected

4 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection the following paperwork was not provided:

- Corrected
1. Annual report
 2. 5-Year internal pipe Testing (NFPA 25 14.2.1.1)
 3. 3-Year Dry System Full flow trip test (NFPA 25 13.1.1.2)
 - Corrected 4. Annual Trip Test (NFPA 25 13.1.1.2)
 5. Annual forward flow test (NFPA 25 13.7.2)
 6. 5-Year FDC Hydro testing (NFPA 25 13.8.5)
 7. Quarterly inspections

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Hilltop Manor Boarding Home

Provider Number 001278

Address 1732 16TH ,

Approval Status Disapproved

City, State, Zip Seattle, WA 98122

Facility Type Residential Care

On 09/25/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

5 Extinguishing System Service

Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion.

(IFC 904.13.5.2 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection the following paperwork was not provided:

1. First semi-annual servicing
2. Second semi-annual service

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Hilltop Manor Boarding Home
Address 1732 16TH ,
City, State, Zip Seattle, WA 98122

Provider Number 001278
Approval Status Disapproved
Facility Type Residential Care

On 09/25/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

6 Portable Fire Extinguishers - General Requirements

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.

Exceptions:

1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.
2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:
 - 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.
 - 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.
 - 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.
 - 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.
 - 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.
3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.

(IFC 906.2 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection the following paperwork was not provided:

1. Annual Servicing (NFPA 10 7.3)
2. Monthly Inspection by Facility Maintenance Log Provided (NFPA 10 7.2)

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

At time of inspection the following was observed:

1. Missing portable fire extinguisher found in lobby area

7 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

Corrected



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Hilltop Manor Boarding Home
Address 1732 16TH ,
City, State, Zip Seattle, WA 98122

Provider Number 001278
Approval Status Disapproved
Facility Type Residential Care

On 09/25/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
8 Power Test	
Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	Corrected
9 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. Annual service report Corrected 2. Log of weekly inspections 3. Monthly 30-minute full load test All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
10 Security	
Compressed gas containers, cylinders, tanks and systems shall be secured against accidental dislodgement and against access by unauthorized personnel in accordance with Sections 5303.5.1 through 5303.5.3. (IFC 5303.5 2021)	Corrected
11 NFPA 80 Fire /Smoke Dampers Inspection and Testing	
19.4 Periodic Inspection and Testing. 19.4.1 Each damper shall be tested and inspected 1 year after installation. 19.4.1.1 The test and inspection frequency shall then be every 4 years, except in hospitals, where the frequency shall be every 6 years.	Corrected

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 09/25/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 10/28/2024

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Amlas
Signature

Amanda Wageer Director of Licensed
Print Name and Title Residential Facilities

Deputy State Fire Marshal Jason Van Gorkum
2803 156 AVE SE
Bellevue WA 98007
(509) 406-7209

Jason E Van Gorkum
Signature

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 07/15/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Application and Use

603.5.2 Application and use. Relocatable power taps and current taps shall be directly connected to a permanently installed receptacle.

Exceptions:

1. Where approved for use in a Group A occupancy or in a meeting room in a Group B occupancy, not more than five relocatable power taps shall be permitted to be connected together or connected to an extension cord for temporary use to supply power to electronic equipment.

2. Current taps and relocatable power taps shall not be required to connect directly to a permanently installed receptacle outlet where used for 90 days or less for the purpose of testing the performance of such devices.

(IFC 603.5.2, 2021)

At time of inspection the following was observed:

1. There was a power strip plugged into another power strip found in front office

2 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..

(IFC 603.6 2021)

At time of inspection the following was observed:

1. There was a extension cord found in use, in lobby by TV

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 07/15/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

3 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. Facility will need to identify and establish a schedule for inspection of Fire-Rated construction. Annual inspection of fire-resistance-rated construction will need to be performed and completed. All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
---	--

4 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. Annual report 2. 5-Year internal pipe Testing (NFPA 25 14.2.1.1) 3. 3-Year Dry System Full flow trip test (NFPA 25 13.1.1.2) 4. Annual Trip Test (NFPA 25 13.1.1.2) 5. Annual forward flow test (NFPA 25 13.7.2) 6. 5-Year FDC Hydro testing (NFPA 25 13.8.5) 7. Quarterly inspections All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
---	---

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 07/15/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

5 Extinguishing System Service

Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion. (IFC 904.13.5.2 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. First semi-annual servicing 2. Second semi-annual service All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
---	--

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 07/15/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

6 Portable Fire Extinguishers - General Requirements

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10. Exceptions: 1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies. 2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met: 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed. 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal. 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment. 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed. 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10. 3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations. (IFC 906.2 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. Annual Servicing (NFPA 10 7.3) 2. Monthly Inspection by Facility Maintenance Log Provided (NFPA 10 7.2) All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. At time of inspection the following was observed: 1. Missing portable fire extinguisher found in lobby area
---	---

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 07/15/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

7 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. Annual report 2. Sensitivity Testing (IFC 907.8.3) 3. Monthly single and multiple station alarms test (IFC 907.8) All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
---	--

8 Power Test

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. Annual 90 minute power test had not been performed and documented All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
--	--

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 07/15/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

9 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. Annual service report 2. Log of weekly inspections 3. Monthly 30-minute full load test All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
--	---

10 Security

Compressed gas containers, cylinders, tanks and systems shall be secured against accidental dislodgement and against access by unauthorized personnel in accordance with Sections 5303.5.1 through 5303.5.3. (IFC 5303.5 2021)	At time of inspection the following was observed: 1. Loose tanks found in basement in boiler room 2 Loose tank found outside by generator
---	--

11 NFPA 80 Fire /Smoke Dampers Inspection and Testing

19.4 Periodic Inspection and Testing. 19.4.1 Each damper shall be tested and inspected 1 year after installation. 19.4.1.1 The test and inspection frequency shall then be every 4 years, except in hospitals, where the frequency shall be every 6 years.	The following deficiencies were cited as a result of this inspection: At the time of inspection the following paperwork was not provided: 1. Fire/smoke damper inspection will need to be performed and documented All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
--	--

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hilltop Manor Boarding Home	Provider Number	001278
Address	1732 16TH ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98122	Facility Type	Residential Care

On 07/15/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 08/14/2024

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2803 156 AVE SE
Bellevue WA, 98007
(509) 406-7209

Signature

This document was prepared by Residential Care Services for the Locator website.