



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Aegis Senior Inn of Kent	Provider Number	1944
Address	10421 SE 248TH ST ,	Approval Status	Approved
City, State, Zip	Kent, WA	Facility Type	Residential Care

On 05/21/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

C. Saul
Signature

5/21/26

Came Saul, General Manager
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2502 112 ST E
Tacoma WA 984455104
(509) 406-7209

DSFM Van Gorkum, Jason

Digitally signed by DSFM Van Gorkum, Jason
Date: 2026.05.21 06:51:56 -07'00'

Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Aegis Senior Inn of Kent
Address 10421 SE 248TH ST ,
City, State, Zip Kent, WA

Provider Number 1944
Approval Status Disapproved
Facility Type Residential Care

On 04/16/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Admin Fire & Life Safety

On 04/16/2026 an unannounced Fire and Life Safety Code re-inspection was conducted at Aegis Senior Inn of Kent by a representative of the Washington State Patrol, State Fire Marshal's Office to determine compliance with all applicable codes.

The following deficiencies were cited as a result of this re-inspection:

2 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.

(IFC 705.2.4 2021)

The following violation was observed at the time of re-inspection:

The kitchen double doors did not close and latch when tested.

Next inspection scheduled on or after: 05/18/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2502 112 ST E
Tacoma WA 984155104
(509) 406-7209

Signature



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Aegis Senior Inn of Kent	Provider Number	1944
Address	10421 SE 248TH ST ,	Approval Status	Disapproved
City, State, Zip	Kent, WA	Facility Type	Residential Care

On 02/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Admin Fire & Life Safety

	On 02/24/2026 an unannounced Fire and Life Safety Code re-inspection was conducted at Aegis Senior Inn of Kent by a representative of the Washington State Patrol, State Fire Marshal's Office to determine compliance with all applicable codes.
--	---

	The following deficiencies were cited as a result of this re-inspection:
--	--

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Aegis Senior Inn of Kent	Provider Number	1944
Address	10421 SE 248TH ST ,	Approval Status	Disapproved
City, State, Zip	Kent, WA	Facility Type	Residential Care

On 02/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

2 Initiation

Drills shall be held at unexpected times and under varying conditions to simulate the unusual conditions that occur in case of fire.

Exceptions:

1. In severe climates, the fire code official shall have the authority to modify the emergency evacuation drill termination points and frequency.
2. In Groups I-1, I-2, I-3 and R-4, where staff-only emergency evacuation drills are conducted after visiting hours or where care recipients are expected to be asleep, a coded announcement shall be an acceptable alternative to audible alarms.

(IFC 405.5 2021)

Records shall be maintained of required emergency evacuation drills and include the following information:

1. Identity of the person conducting the drill.
2. Date and time of the drill.
3. Notification method used.
4. Employees on duty and participating.
5. Number of occupants evacuated.
6. Special conditions simulated.
7. Problems encountered.
8. Weather conditions when occupants were evacuated.
9. Time required to accomplish complete evacuation.

(IFC 0405.6 2021)

Where a fire alarm system is provided, emergency evacuation drills shall be initiated by activating the fire alarm system.

(IFC 405.8 2021)

Corrected

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Aegis Senior Inn of Kent	Provider Number	1944
Address	10421 SE 248TH ST ,	Approval Status	Disapproved
City, State, Zip	Kent, WA	Facility Type	Residential Care

On 02/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

3 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..

Corrected

(IFC 603.6 2021)

4 Cleaning

Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3.

Corrected

(IFC 606.3.3 2021)

5 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space.

Corrected

(IFC 701.6 2021)

6 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.

The following violation was observed at the time of re-inspection:

(IFC 705.2.4 2021)

The kitchen double doors did not close and latch when tested.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Aegis Senior Inn of Kent	Provider Number	1944
Address	10421 SE 248TH ST ,	Approval Status	Disapproved
City, State, Zip	Kent, WA	Facility Type	Residential Care

On 02/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

7 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.	The following violation was observed at the time of re-inspection:
--	--

(IFC 903.5 2021)

The facility was unable to provide the forward flow report. There was a sticker showing it had been completed.

8 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.	The following violation was observed at the time of re-inspection:
--	--

(IFC 907.8 2021)

The annual fire alarm report from 5/23/25 shows deficiencies on the report. The facility was unable to provide a correction report.

The facility has the semi annual fire alarm scheduled for 11/3/26.

9 Carbon Monoxide Detection - General

Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code.	Corrected
---	-----------

(IFC 0915.1 2021 WAC 51-54A)

10 Activation Test

Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired.	Corrected
---	-----------

(IFC 1032.10.1 2021)

11 Power Test

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.	Corrected
---	-----------

(IFC 1031.10.2 2021)



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Aegis Senior Inn of Kent
Address 10421 SE 248TH ST,
City, State, Zip Kent, WA

Provider Number 1944
Approval Status Disapproved
Facility Type Residential Care

On 02/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

12 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.

(IFC 1203.4 2021)


The following violation was observed at the time of re-inspection:

The facility was unable to provide the annual servicing of their generator.

Next inspection scheduled on or after: 03/26/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

Richard A. Duckin Maintenance
Print Name and Title

Deputy State Fire Marshal Cozetta Christian
106 11th AVE SW
Olympia WA 98501
(360) 584-5796


Signature



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Aegis Senior Inn of Kent	Provider Number	1944
Address	10421 SE 248TH ST ,	Approval Status	Disapproved
City, State, Zip	Kent, WA	Facility Type	Residential Care

On 01/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Admin Fire & Life Safety

This report is the result of an unannounced fire and life safety re-certification survey conducted at Aegis Senior Inn of Kent on 1/15/2026 by a DSFM representative of the Washington State Patrol, Fire Protection Bureau to determine compliance with all applicable codes.

All inspection reports must be completely filled out from the vendor and verify the report shows no deficiencies. If deficiencies are noted on report, additional documentation will be required to show that deficiencies have been corrected prior to re-inspection.

The facility is not in compliance at the time of this inspection.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Aegis Senior Inn of Kent	Provider Number	1944
Address	10421 SE 248TH ST ,	Approval Status	Disapproved
City, State, Zip	Kent, WA	Facility Type	Residential Care

On 01/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

2 Initiation

Drills shall be held at unexpected times and under varying conditions to simulate the unusual conditions that occur in case of fire.

Exceptions:

1. In severe climates, the fire code official shall have the authority to modify the emergency evacuation drill termination points and frequency.
2. In Groups I-1, I-2, I-3 and R-4, where staff-only emergency evacuation drills are conducted after visiting hours or where care recipients are expected to be asleep, a coded announcement shall be an acceptable alternative to audible alarms.

(IFC 405.5 2021)

Records shall be maintained of required emergency evacuation drills and include the following information:

1. Identity of the person conducting the drill.
2. Date and time of the drill.
3. Notification method used.
4. Employees on duty and participating.
5. Number of occupants evacuated.
6. Special conditions simulated.
7. Problems encountered.
8. Weather conditions when occupants were evacuated.
9. Time required to accomplish complete evacuation.

(IFC 0405.6 2021)

Where a fire alarm system is provided, emergency evacuation drills shall be initiated by activating the fire alarm system.

(IFC 405.8 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. Facility cannot provide documentation for the completion of twelve planned and unannounced fire drills in the previous 12 months.

The following drills are missing.

- 2nd Shift - Quarter 2 and 4
- 3rd Shift - Quarter 1

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Aegis Senior Inn of Kent	Provider Number 1944
Address 10421 SE 248TH ST ,	Approval Status Disapproved
City, State, Zip Kent, WA	Facility Type Residential Care

On 01/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

3 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..

(IFC 603.6 2021)

The following deficiencies were cited as a result of this inspection:

At time of inspection the following was observed:

1. In the nurses station has an extension cord in-use.

4 Cleaning

Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3.

(IFC 606.3.3 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. First semi-annual hood cleaning
2. Second semi-annual hood cleaning

5 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space.

(IFC 701.6 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. The facility must maintain detailed documentation and maps of fire-rated construction locations, including annual inspection reports detailing testing dates, modifications, and repairs.
2. Report on hand was not showing corridors throughout facility.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Aegis Senior Inn of Kent
Address 10421 SE 248TH ST ,
City, State, Zip Kent, WA

Provider Number 1944
Approval Status Disapproved
Facility Type Residential Care

On 01/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

6 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically.

(IFC 705.2.4 2021)

The following deficiencies were cited as a result of this inspection:

At time of inspection the following was observed:

1. The kitchen double doors will not close and latch.

7 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. Annual forward flow test (NFPA 25 13.7.2.1)
2. Quarterly inspections Reports

8 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. 5/23/2025 report shows deficiencies on report
2. Semi-Annual Report

9 Carbon Monoxide Detection - General

Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code.

(IFC 0915.1 2021 WAC 51-54A)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. The facility must maintain detailed documentation and maps of carbon monoxide detector locations, including monthly inspection reports detailing testing dates, modifications, and repairs.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Aegis Senior Inn of Kent	Provider Number 1944
Address 10421 SE 248TH ST ,	Approval Status Disapproved
City, State, Zip Kent, WA	Facility Type Residential Care

On 01/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

10 Activation Test

Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired.

(IFC 1032.10.1 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. Monthly 30-second activation testing had not been performed and documented

11 Power Test

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.

(IFC 1031.10.2 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. Annual 90 minute power test had not been performed and documented

12 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.

(IFC 1203.4 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following documentation was not provided. Documents shall include the following, where applicable:

1. Annual service report

This document was prepared by Residential Care Services for the Locator website.

