



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                                     |                        |                  |
|-------------------------|-------------------------------------|------------------------|------------------|
| <b>Business Name</b>    | Highgate Senior Living - Bellingham | <b>Provider Number</b> | 2097             |
| <b>Address</b>          | 155 E KELLOGG RD ,                  | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Bellingham, WA                      | <b>Facility Type</b>   | Residential Care |

On 02/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|------------------|------------------------|
|------------------|------------------------|

**1 Open electrical terminations**

|                                                                                                                                                                           |           |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes.<br><br>(IFC 603.2.2, 2021) | Corrected |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

**2 Working Space and Clearance**

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |           |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| Working space and clearances. Working space around electrical equipment shall be provided in accordance with Section 110.26 of NFPA 70 for electrical equipment rated 1,000 volts or less, and Section 110.32 of NFPA 70 for electrical equipment rated over 1,000 volts. The minimum required working space shall be not less than 30 inches (762 mm) in width, 36 inches (914 mm) in depth and 78 inches (1981 mm) in height in front of electrical service equipment. Where the electrical service equipment is wider than 30 inches (762 mm), the minimum working space shall be not less than the width of the equipment. Storage of materials shall not be located within the designated working space.<br><br>(IFC 603.4, 2021) | Corrected |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

**3 Cleaning**

|                                                                                                                                                                                 |           |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3.<br><br>(IFC 606.3.3 2021) | Corrected |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                                     |                        |                  |
|-------------------------|-------------------------------------|------------------------|------------------|
| <b>Business Name</b>    | Highgate Senior Living - Bellingham | <b>Provider Number</b> | 2097             |
| <b>Address</b>          | 155 E KELLOGG RD ,                  | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Bellingham, WA                      | <b>Facility Type</b>   | Residential Care |

On 02/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|------------------|------------------------|
|------------------|------------------------|

**4 Inspection and Maintenance**

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |           |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80.<br>Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105.<br>Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified.<br><br>(IFC 705.2 2021) | Corrected |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

**5 Door Operation**

|                                                                                                                |           |
|----------------------------------------------------------------------------------------------------------------|-----------|
| Swinging fire doors shall close from the full-open position and latch automatically.<br><br>(IFC 705.2.4 2021) | Corrected |
|----------------------------------------------------------------------------------------------------------------|-----------|

**6 Testing and Maintenance**

|                                                                                                          |           |
|----------------------------------------------------------------------------------------------------------|-----------|
| Sprinkler systems shall be tested and maintained in accordance with Section 901.<br><br>(IFC 903.5 2021) | Corrected |
|----------------------------------------------------------------------------------------------------------|-----------|

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

**Business Name** Highgate Senior Living - Bellingham  
**Address** 155 E KELLOGG RD ,  
**City, State, Zip** Bellingham, WA

**Provider Number** 2097  
**Approval Status** Disapproved  
**Facility Type** Residential Care

On 02/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

**7 Portable Fire Extinguishers - General Requirements**

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.

Exceptions:

1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.

2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:

2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.

2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.

2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.

2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.

2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.

3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.

(IFC 906.2 2021)

Corrected

**8 Hangers and Brackets**

Hand-held portable fire extinguishers, not housed in cabinets, shall be installed on the hangers or brackets supplied. Hangers or brackets shall be securely anchored to the mounting surface in accordance with the manufacturer's installation instructions.

(IFC 906.7 2021)

Corrected

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                                     |                        |                  |
|-------------------------|-------------------------------------|------------------------|------------------|
| <b>Business Name</b>    | Highgate Senior Living - Bellingham | <b>Provider Number</b> | 2097             |
| <b>Address</b>          | 155 E KELLOGG RD ,                  | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Bellingham, WA                      | <b>Facility Type</b>   | Residential Care |

On 02/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|------------------|------------------------|
|------------------|------------------------|

**9 Inspection, Testing and Maintenance**

|                                                                                                                                                                                                                                                                  |           |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.<br>(IFC 907.8 2021) | Corrected |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

**10 Inspection and Maintenance**

|                                                                                                                                                                                                        |                                                                                                                                              |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| Fire department connections shall be periodically inspected, tested and maintained in accordance with NFPA 25. Records of inspection, testing and maintenance shall be maintained.<br>(IFC 912.7 2021) | Facility was unable to provide documentation that the Fire Department Connection has been hydrostatically tested in accordance with NFPA 25. |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|

**11 Maintenance**

|                                                                                                                                                                                                                                                                            |           |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| Carbon monoxide alarms and carbon monoxide detection systems shall be maintained in accordance with NFPA 72. Carbon monoxide alarms and carbon monoxide detectors that become inoperable or begin producing end-of-life signals shall be replaced.<br>(IFC 915.6 2021 WAC) | Corrected |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

**12 Means of Egress Continuity**

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |           |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| The path of egress travel along a means of egress shall not be interrupted by any building element other than a means of egress component as specified in this chapter. Obstructions shall not be placed in the minimum width or required capacity of a means of egress component except projections permitted by this chapter. The minimum width or required capacity of a means of egress system shall not be diminished along the path of egress travel.<br>(IFC 1003.6 2021) | Corrected |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                                     |                        |                  |
|-------------------------|-------------------------------------|------------------------|------------------|
| <b>Business Name</b>    | Highgate Senior Living - Bellingham | <b>Provider Number</b> | 2097             |
| <b>Address</b>          | 155 E KELLOGG RD ,                  | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Bellingham, WA                      | <b>Facility Type</b>   | Residential Care |

On 02/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|------------------|------------------------|
|------------------|------------------------|

**13 Emergency Power for Illumination - General**

|                                                                                                                                                                                                                                                                                                         |           |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| In the event of power supply failure in rooms and spaces that require two or more exits or access to exits, an emergency electrical system shall automatically illuminate all of the following areas:<br><br>1. Aisles<br>2. Corridors<br>3. Exit access stairways and ramps<br><br>(IFC 1008.3.1 2021) | Corrected |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

**14 Graphics**

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |           |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| Externally illuminated exit signs shall comply with Sections 1013.6.1 through 1013.6.3<br><br>Every exit sign and directional exit sign shall have plainly legible letters not less than 6 inches (152 mm) high with the principal strokes of the letters not less than 3/4 inch (19.1 mm) wide. The word "EXIT" shall have letters having a width not less than 2 inches (51 mm) wide, except the letter "I," and the minimum spacing between letters shall not be less than 3/8 inch (9.5 mm). Signs larger than the minimum established in this section shall have letter widths, strokes and spacing in proportion to their height.<br><br>The word "EXIT" shall be in high contrast with the background and shall be clearly discernible when the means of exit sign illumination is or is not energized. If a chevron directional indicator is provided as part of the exit sign, the construction shall be such that the direction of the chevron directional indicator cannot be readily changed.<br><br>(IFC 1013.6.1 2021) | Corrected |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

**Business Name** Highgate Senior Living - Bellingham  
**Address** 155 E KELLOGG RD ,  
**City, State, Zip** Bellingham, WA

**Provider Number** 2097  
**Approval Status** Disapproved  
**Facility Type** Residential Care

On 02/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

**15 Activation Test**

Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired.

(IFC 1032.10.1 2021)

Corrected

**16 Power Test**

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.

(IFC 1031.10.2 2021)

Corrected

**17 Fire Drills**

In all Group I, Group E, and Group R2 Occupancies licensed by the state and inspected by the state fire marshal's office, at least twelve planned and unannounced fire drills shall be held every year.

(1) Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions.

(2) A detailed written record of all fire drills shall be maintained and available for inspection.

(3) When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms.

Corrected



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

**Business Name** Highgate Senior Living - Bellingham

**Provider Number** 2097

**Address** 155 E KELLOGG RD ,

**Approval Status** Disapproved

**City, State, Zip** Bellingham, WA

**Facility Type** Residential Care

On 02/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

**Next inspection scheduled on or after:** 03/27/2026

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Hunter Frew Maint. Mgr.

Print Name and Title

Deputy State Fire Marshal Brandon G. Brown  
MP 235 SB Interstate 5  
Bow WA 98232  
(360) 791-7037

Signature

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

**Business Name** Highgate Senior Living - Bellingham  
**Address** 155 E KELLOGG RD ,  
**City, State, Zip** Bellingham, WA

**Provider Number** 2097  
**Approval Status** Disapproved  
**Facility Type** Residential Care

On 12/23/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

**1 Open electrical terminations**

Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes.

(IFC 603.2.2, 2021)

There is an open junction box in the ceiling of the mechanical room near 219

**2 Working Space and Clearance**

Working space and clearances. Working space around electrical equipment shall be provided in accordance with Section 110.26 of NFPA 70 for electrical equipment rated 1,000 volts or less, and Section 110.32 of NFPA 70 for electrical equipment rated over 1,000 volts. The minimum required working space shall be not less than 30 inches (762 mm) in width, 36 inches (914 mm) in depth and 78 inches (1981 mm) in height in front of electrical service equipment. Where the electrical service equipment is wider than 30 inches (762 mm), the minimum working space shall be not less than the width of the equipment. Storage of materials shall not be located within the designated working space.

(IFC 603.4, 2021)

There was storage blocking access to the electrical panel in the mechanical room near 219.

**3 Cleaning**

Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3.

(IFC 606.3.3 2021)

Facility is unable to provide documentation for the 12 months of semi-annual hood cleanings.

This document was prepared by Residential Care Services for the Locator website.





Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                                     |                        |                  |
|-------------------------|-------------------------------------|------------------------|------------------|
| <b>Business Name</b>    | Highgate Senior Living - Bellingham | <b>Provider Number</b> | 2097             |
| <b>Address</b>          | 155 E KELLOGG RD ,                  | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Bellingham, WA                      | <b>Facility Type</b>   | Residential Care |

On 12/23/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|------------------|------------------------|
|------------------|------------------------|

**4 Inspection and Maintenance**

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                                                                                                                                                                                                                                    |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified.<br><br>(IFC 705.2 2021) | 1. The 2nd floor laundry room door that opens to the corridor was blocked open by a stool that prevented the door from closing and latching.<br><br>2. The cross corridor door near 101 had a handle that would not open the door. |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

**5 Door Operation**

|                                                                                                                |                                                                                                                                                                                                                                                                                                                                   |
|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Swinging fire doors shall close from the full-open position and latch automatically.<br><br>(IFC 705.2.4 2021) | 1. The fire rated cross corridor door near the O2 room would not close and latch from the fully open position.<br><br>2. The fire rated cross corridor door near MC 14 room would not close and latch from the fully open position.<br><br>3. Resident room 117 fire door would not close and latch from the fully open position. |
|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

**6 Testing and Maintenance**

|                                                                                                          |                                                                                        |
|----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|
| Sprinkler systems shall be tested and maintained in accordance with Section 901.<br><br>(IFC 903.5 2021) | Facility is unable to provide documentation for the 5 year internal piping inspection. |
|----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                                     |                        |                  |
|-------------------------|-------------------------------------|------------------------|------------------|
| <b>Business Name</b>    | Highgate Senior Living - Bellingham | <b>Provider Number</b> | 2097             |
| <b>Address</b>          | 155 E KELLOGG RD ,                  | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Bellingham, WA                      | <b>Facility Type</b>   | Residential Care |

On 12/23/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|------------------|------------------------|
|------------------|------------------------|

**7 Portable Fire Extinguishers - General Requirements**

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                   |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.</p> <p>Exceptions:</p> <ol style="list-style-type: none"><li>1. The distance of travel to reach an extinguisher shall not apply. The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.</li><li>2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:<ol style="list-style-type: none"><li>2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.</li><li>2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.</li><li>2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.</li><li>2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.</li><li>2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.</li></ol></li><li>3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.</li></ol> <p>(IFC 906.2 2021)</p> | <ol style="list-style-type: none"><li>1. The portable fire extinguisher in the mechanical room near 219 was missing the tamper seal.</li><li>2. The required monthly maintenance for the portable fire extinguisher in the 2nd floor laundry room has not be completed.</li></ol> |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

**8 Hangers and Brackets**

|                                                                                                                                                                                                                                                                                               |                                                                                                                                                                                                                                                                                                                       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>Hand-held portable fire extinguishers, not housed in cabinets, shall be installed on the hangers or brackets supplied. Hangers or brackets shall be securely anchored to the mounting surface in accordance with the manufacturer's installation instructions.</p> <p>(IFC 906.7 2021)</p> | <ol style="list-style-type: none"><li>1. Fire Extinguisher in the 2nd floor kitchen area was not mounted in accordance with the manufacturer's installation instructions.</li><li>2. Fire Extinguisher in the staff lounge was not mounted in accordance with the manufacturer's installation instructions.</li></ol> |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

**Business Name** Highgate Senior Living - Bellingham  
**Address** 155 E KELLOGG RD ,  
**City, State, Zip** Bellingham, WA

**Provider Number** 2097  
**Approval Status** Disapproved  
**Facility Type** Residential Care

On 12/23/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

**9 Inspection, Testing and Maintenance**

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

Facility is unable to provide documentation for the monthly single station smoke alarm testing.

**10 Inspection and Maintenance**

Fire department connections shall be periodically inspected, tested and maintained in accordance with NFPA 25. Records of inspection, testing and maintenance shall be maintained.

(IFC 912.7 2021)

Facility was unable to provide documentation that the Fire Department Connection has been hydrostatically tested in accordance with NFPA 25.

**11 Maintenance**

Carbon monoxide alarms and carbon monoxide detection systems shall be maintained in accordance with NFPA 72. Carbon monoxide alarms and carbon monoxide detectors that become inoperable or begin producing end-of-life signals shall be replaced.

(IFC 915.6 2021 WAC)

Facility is unable to provide documentation for the monthly carbon monoxide detector testing.

**12 Means of Egress Continuity**

The path of egress travel along a means of egress shall not be interrupted by any building element other than a means of egress component as specified in this chapter. Obstructions shall not be placed in the minimum width or required capacity of a means of egress component except projections permitted by this chapter. The minimum width or required capacity of a means of egress system shall not be diminished along the path of egress travel.

(IFC 1003.6 2021)

There was a cart blocking the emergency exit in the kitchen.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                                     |                        |                  |
|-------------------------|-------------------------------------|------------------------|------------------|
| <b>Business Name</b>    | Highgate Senior Living - Bellingham | <b>Provider Number</b> | 2097             |
| <b>Address</b>          | 155 E KELLOGG RD ,                  | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Bellingham, WA                      | <b>Facility Type</b>   | Residential Care |

On 12/23/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|------------------|------------------------|
|------------------|------------------------|

**13 Emergency Power for Illumination - General**

|                                                                                                                                                                                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                                                                 |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>In the event of power supply failure in rooms and spaces that require two or more exits or access to exits, an emergency electrical system shall automatically illuminate all of the following areas:</p> <ol style="list-style-type: none"><li>1. Aisles</li><li>2. Corridors</li><li>3. Exit access stairways and ramps</li></ol> <p>(IFC 1008.3.1 2021)</p> | <p>The emergency egress light in the following locations would not illuminate when the test button was pressed.</p> <ol style="list-style-type: none"><li>a. near 206</li><li>b. near 205</li><li>c. near 101</li><li>d. near MC 1</li><li>e. near MC 3</li><li>f. near MC 10</li><li>g. near 123</li><li>h. near 119</li></ol> |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

**14 Graphics**

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                                                                             |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|
| <p>Externally illuminated exit signs shall comply with Sections 1013.6.1 through 1013.6.3</p> <p>Every exit sign and directional exit sign shall have plainly legible letters not less than 6 inches (152 mm) high with the principal strokes of the letters not less than 3/4 inch (19.1 mm) wide. The word "EXIT" shall have letters having a width not less than 2 inches (51 mm) wide, except the letter "I," and the minimum spacing between letters shall not be less than 3/8 inch (9.5 mm). Signs larger than the minimum established in this section shall have letter widths, strokes and spacing in proportion to their height.</p> <p>The word "EXIT" shall be in high contrast with the background and shall be clearly discernible when the means of exit sign illumination is or is not energized. If a chevron directional indicator is provided as part of the exit sign, the construction shall be such that the direction of the chevron directional indicator cannot be readily changed.</p> <p>(IFC 1013.6.1 2021)</p> | <p>The front of the exit sign near MC spa is missing the internal face.</p> |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

**Business Name** Highgate Senior Living - Bellingham  
**Address** 155 E KELLOGG RD ,  
**City, State, Zip** Bellingham, WA

**Provider Number** 2097  
**Approval Status** Disapproved  
**Facility Type** Residential Care

On 12/23/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

**15 Activation Test**

Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired.

(IFC 1032.10.1 2021)

Facility is unable to provide documentation for the monthly 30 second activation test for the emergency lights.

**16 Power Test**

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.

(IFC 1031.10.2 2021)

Facility is unable to provide documentation for the annual 90 minute power test for the emergency lights.

**17 Fire Drills**

In all Group I, Group E, and Group R2 Occupancies licensed by the state and inspected by the state fire marshal's office, at least twelve planned and unannounced fire drills shall be held every year.

(1) Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions.

(2) A detailed written record of all fire drills shall be maintained and available for inspection.

(3) When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms.

Facility cannot provide documentation for the completion of twelve planned and unannounced fire drills in the previous 12 months.

The following Drills are missing.

1st Shift - Quarter 1 and 3

2nd Shift - Quarter 2 and 3

3rd Shift - Quarter 2, 3, and 4

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                                     |                        |                  |
|-------------------------|-------------------------------------|------------------------|------------------|
| <b>Business Name</b>    | Highgate Senior Living - Bellingham | <b>Provider Number</b> | 2097             |
| <b>Address</b>          | 155 E KELLOGG RD ,                  | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Bellingham, WA                      | <b>Facility Type</b>   | Residential Care |

On 12/23/2025 the Office of the State Fire Marshal conducted an inspection at your facility.


Code Requirement

Statement of Violation

Next inspection scheduled on or after: 01/22/2026

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

  
Signature

  
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown  
MP 235 SB Interstate 5  
Bow WA 98232  
(360) 791-7037

  
Signature

This document was prepared by Residential Care Services for the Locator website.