




Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Elma Home Care	Provider Number	2383
Address	901 YOUNG ,	Approval Status	Approved
City, State, Zip	Elma, WA 98541	Facility Type	Residential Care

On 09/05/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature

Sara Jordan - Administrator
Print Name and Title


Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067

Raul Murcia
Digitally signed by Raul Murcia
Date: 2024.09.09 10:02:37 -07'00'

Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212.12.

Initials of Authorized Facility Representative: 



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Elma Home Care	Provider Number	2383
Address	901 YOUNG ,	Approval Status	Disapproved
City, State, Zip	Elma, WA 98541	Facility Type	Residential Care

On 07/29/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

Findings during the inspection were:

Facility failed to provide the following documentation for the sprinkler system;

- Annual inspection report.
- 5-year internal pipe inspection.
- Annual trip test.
- Fire department connection hydrostatic test (every fire years).

2 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

Findings during the inspection were:

Facility failed to provide the following documents for the fire alarm;

- Annual inspection report.
- Monthly inspection of smoke alarms.

3 Smoke Detector Sensitivity

Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed.

(IFC 907.8.3 2021)

Findings during the inspection were:

Facility failed to provide documentation showing sensitivity testing for fire alarm smoke detectors.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Elma Home Care	Provider Number	2383
Address	901 YOUNG ,	Approval Status	Disapproved
City, State, Zip	Elma, WA 98541	Facility Type	Residential Care

On 07/29/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 08/29/2024

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature NOT AVAILABLE

Print Name and Title _____

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067

Signature R. Murcia

This document was prepared by Residential Care Services for the Locator website.