



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                           |                        |                  |
|-------------------------|---------------------------|------------------------|------------------|
| <b>Business Name</b>    | Merrill Gardens at Burien | <b>Provider Number</b> | 2406             |
| <b>Address</b>          | 15020 5 AVE SW,           | <b>Approval Status</b> | Approved         |
| <b>City, State, Zip</b> | Burien, WA                | <b>Facility Type</b>   | Residential Care |

On 04/06/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Robert Filipovic  
Signature

Robert Filipovic Maintenance Director  
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum  
2502 112 ST E  
Tacoma WA 984455104  
(509) 406-7209

DSFM Van Gorkum, Jason  
Digitally signed by DSFM Van Gorkum,  
Jason  
Date: 2026.04.06 09:15:12 -07'00'

Signature

This document was prepared by Residential Care Services for the Locator website.

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

**Business Name** Merrill Gardens at Burien  
**Address** 15020 5 AVE SW,  
**City, State, Zip** Burien, WA

**Provider Number** 2406  
**Approval Status** Disapproved  
**Facility Type** Residential Care

On 03/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

**1 Admin Fire & Life Safety Inspection**

This report is the result of an unannounced fire and life safety re-certification survey conducted at Merrill Gardens at Burien on 3/25/2026 by a DSFM representative of the Washington State Patrol, Fire Protection Bureau to determine compliance with all applicable codes.

All inspection reports must be completely filled out from the vendor and verify the report shows no deficiencies. If deficiencies are noted on report, additional documentation will be required to show that deficiencies have been corrected prior to re-inspection.

The facility is not in compliance at the time of this inspection.

**2 Modified or damaged.**

Electrical wiring, devices, equipment and appliances that are modified or damaged, and constitute an electrical shock or fire hazard, shall not be used until repaired or replaced in accordance with this code and NFPA 70.

(IFC 603.2.1 2021)

The following deficiencies were cited as a result of this inspection:

At time of inspection the following was observed:

1. Located in the kitchen has a portable hot box with exposed wires near the plug.

**3 Carbon Monoxide Detection - General**

Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code.

(IFC 0915.1 2021 WAC 51-54A)

The following deficiencies were cited as a result of this inspection:

At time of inspection the following was observed:

1. Located in the boiler room in parking garage has natural gas with no detection.

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol  
Fire Protection Bureau  
Phone: (360) 596-3900

|                         |                           |                        |                  |
|-------------------------|---------------------------|------------------------|------------------|
| <b>Business Name</b>    | Merrill Gardens at Burien | <b>Provider Number</b> | 2406             |
| <b>Address</b>          | 15020 5 AVE SW,           | <b>Approval Status</b> | Disapproved      |
| <b>City, State, Zip</b> | Burien, WA                | <b>Facility Type</b>   | Residential Care |

On 03/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

**4 Security**

Compressed gas containers, cylinders, tanks and systems shall be secured against accidental dislodgement and against access by unauthorized personnel in accordance with Sections 5303.5.1 through 5303.5.3.

(IFC 5303.5 2021)

The following deficiencies were cited as a result of this inspection:



At time of inspection the following was observed:

1. Located in the kitchen has 6 lose cylinders

**Next inspection scheduled on or after: 04/24/2026**


**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

   
Signature

Robert Filipovic Maintenance Director  
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum  
2502 112 ST E  
Tacoma WA 984455104  
(509) 406-7209

  
Signature